

Acme Coke  
11236 S. Torrence Ave.  
Chicago IL 60617



[acmecoke.com](http://acmecoke.com)

Document archive

Pinion Wall Inspection

Dated: 1998

*Recovered from site on Feb 13 2021*





June 30, 1998  
(Revised)

**ORBITAL ENGINEERING,® INC.**  
3800 179th Street • Hammond, IN 46323  
Tel: (219) 989-3300 • Fax: (219) 989-3310

Mr. M. T. McCarthy  
Manager of Project Engineering  
**Acme Steel Company**  
Chicago Coke Plant  
10730 Burley Avenue  
Chicago, IL 60617

Attention: Mr. R. Martello

Subject: **Acme - Chicago Coke**  
Coke Plant - Battery  
South Pinion Wall  
Floor Steel & Concrete Dock  
1998 Inspection

**Project No. 05-8126**  
ACME P.O. No. 7000000-880  
CSMP ID No. 10-2-1146

Gentlemen:

In reference to the above subject, we are submitting this letter report to present the inspection results of the alleyway floor steel and concrete deck located adjacent to the south pinion wall of Battery No. 1. The inspection was requested by the Acme Engineering Department after noticeable deterioration was observed by plant personnel. The inspection was conducted on May 7, 1998 in cooperation with the Coke Plant Operations Department.

### INTENT/SCOPE OF WORK

The intent of this project was to search out and define any readily discernible deficiencies and provide recommendations for any repairs that may be required.

The scope of work included a detailed visual inspection, with random ultrasonic thickness testing, of the alleyway floor steel framing members at Elevation 14'-5", in the alley between the Coal Bunker and Battery No. 1. Also, a visual inspection of the underside of the concrete deck was conducted.

### HISTORY/GENERAL DESCRIPTION

The subject alleyway floor steel is located between the Coal Bunker and Battery No. 1 at Elevation 14'-5". The alleyway is approximately 50'-0" long by 14'-3" wide and is comprised of S12, S10 and C10 framing, which in turn support a 6" thick concrete deck. The alleyway was designed and built by the Wilputte Coke Oven Division of New York, New York; circa 1955.





### HISTORY/GENERAL DESCRIPTION - continued

This was the initial inspection conducted by Orbital Engineering, Inc. of this structure.

### Reference Drawings

37089  
37136

### FINDINGS AND RECOMMENDATIONS

The following is a list of Inspection Findings (F) and corresponding Repair Recommendations (R) for the deficiencies which were encountered during the May 7, 1998 structural inspection. The Repair Recommendations are accompanied by Suggested Repair Priority (P) designations. Also, Standard Repair Procedures are included with the recommendations, where applicable. For descriptions of the Suggested Repair Priorities and the Standard Repair Procedures, refer to Attachment "1". For specific locations of the inspection findings, refer to the inspection drawing located in Attachment "2".

#### Alleyway Floor Steel

F1) The S12 is heavily rust layered and rusted thin and through throughout.

R1/P3) Replace the deficient S12 "in-kind" as required.

F2) The S12 and related seat assembly is rusted thin and through at the south end 24".

F3) The remainder of the S12 bottom flange exhibits approximately 50% section loss.

#### Recommendations "R2" and "R3"

P3) Replace the S12 and seat assembly "in-kind" as required.





**FINDINGS AND RECOMMENDATIONS - continued**

**Alleyway Floor Steel - continued**

- F4) Ultrasonic thickness testing was conducted on the S12 web ranging from .47" to .48", indicating 0% section loss (.428" [7/16"] original thickness). The top and bottom flanges exhibit only slight section loss.
- F5) Ultrasonic thickness testing was conducted on the S12 web ranging from .46" to .47", indicating 0% section loss (.428" [7/16"] original thickness). The top and bottom flanges exhibit only slight section loss.
- F6) Ultrasonic thickness testing was conducted on the S12 web ranging from .45" to .47", indicating 0% section loss (.428" [7/16"] original thickness). The top and bottom flanges exhibit only slight section loss.
- F7) Ultrasonic thickness testing was conducted on the S10 web ranging from .25" to .27", indicating 13% to 20% section loss (.311" [5/16"] original thickness). The top and bottom flanges exhibit only slight section loss.
- F8) Ultrasonic thickness testing was conducted on the C10 web ranging from .46" to .47", indicating 0% section loss (.428" [7/16"] original thickness). The top and bottom flanges exhibit only slight section loss.

**Recommendations "R4" thru "R8"**

- P5) No repair is required at this time. Monitor condition during future follow-up inspections.
- F9) Typically, the framing/support members are moderately rust layered by 1"± behind the existing coating/paint (peeling off) and are slightly rust pitted throughout.
- R9/P4) Sandblast and clean members of all rust layering and existing coating/paint. Reapply an appropriate coating/paint as per manufacturer's recommendations (existing condition is one of high humidity and dampness). Work with Recommendations "R10" through "R18".





**FINDINGS AND RECOMMENDATIONS - continued**

**Concrete Deck**

The underside of the concrete deck is spalled as follows:

- F10) 17'-0" long by 3'-0" wide area by 3" deep with exposed rusted thin and through rebar.
- F11) 6'-6" long x 2'-6" wide area by 3" deep with exposed rusted thin and through rebar.
- F12) 6'-0" long by 6'-0" wide area by 3" deep with exposed rusted thin and through rebar.
- F13) 3'-0" long by 2'-0" wide area by 3"± deep with exposed rusted thin and through rebar.
- F14) 18" long by 18" wide area by 3"± deep with exposed rusted thin and through rebar.
- F15) 5'-0" long by 4'-0" wide area by 3"± deep with exposed rusted thin and through rebar.
- F16) 2'-0" long by 2'-0" wide area by 3" deep.
- F17) 2" diameter hole through concrete deck.

**Recommendations "R10" thru "R17"**

- P4)** Monitor deficient area of concrete on a monthly basis with the intent of removing and replacing the concrete slab "in-kind" in the next twelve (12) months. Refer also to Finding "F18".





**FINDINGS AND RECOMMENDATIONS - continued**

**Concrete Deck - continued**

- F18) The underside of the concrete deck is sporadically cracked throughout.
- R18/P4) Monitor deficient area of concrete on a monthly basis with the intent of removing and replacing the concrete slab "in-kind" in the next twelve (12) months. Refer also to Finding "F17".

**Miscellaneous Appurtenances**

- F19) The stairway is rusted thin and through at the lower 8" (stringers and tread).
- R19/P3) Replace the deficient section of stairway "in-kind" as required.
- F20) The utility supports, which are attached to the bottom flanges of the S12's and S10, exhibit 25% to 50% section loss throughout.
- R20/P3) Replace the deficient utility supports "in-kind" as required.

**Note:** All the recommendations contained within this report should be worked in conjunction with each other.





**Acme Steel Company**  
**June 30, 1998**  
**(Revised)**

**Project No. 05-8126**  
**Page 6**

## OVERVIEW

Upon review of the inspection data, the overall structural integrity of the alleyway floor steel (Elevation 14'-5") is judged to be "Poor".

During the course of the inspection, two (2) S12 x 40.8's were found to be severely rust deteriorated and require replacement. (Refer to Findings "F1" thru "F3"). Also, approximately 150'-0" square feet of concrete deck was found to be spalled by 3"± deep with exposed rusted thin and through rebar (underside). (Refer to Findings "F10" thru "F17".) Along with the sporadic cracking present (Finding "F18"), it is our opinion that removing and replacing the concrete deck "in-kind" would be the most prudent, long term repair option. In the interim, we are recommending that the subject area be inspected monthly, until such repairs are made.

Although not included in the scope of work for this project, additional deficiencies were observed to exist during our inspection. The lower 18" of the stairway stringers and tread are rusted thin and through and the utility supports, attached to the bottom flange of the floor framing, exhibit 25% to 50% section loss (Findings "F19" and "F20").

The results of the inspection has been entered into the Critical Structures Management Program (CSMP). This program is designed to effectively track and record repairs that are implemented and to provide a historical record of the structures inspection/repair efforts. For an itemized listing of findings and recommendations that need to be implemented, refer to the CSMP information located in Attachment "3". Upon completion of future repair efforts, please fill out the forms located in Attachment "3" and forward them to the Orbital Engineering Program Coordinator and/or Acme Engineering Department.

In conclusion, it is recommended that the results of this inspection be reviewed by the Acme Steel Engineering and Coke Battery Maintenance Departments and that a remedial course of action be established and implemented.

If you have any questions concerning any aspect of this letter report, please contact our office.

Sincerely,

John A. Konarski, III  
Crew Chief - Field Services

*Attachments*

JMK/JAK:bal



BY JAK DATE 4-9-98  
 CHK'D PML DATE 6-12-98



ORBITAL ENGINEERING<sup>®</sup>, INC.  
 PITTSBURGH • CHICAGO • CLEVELAND • PHILADELPHIA  
 OAK BROOK • TOLEDO

SHEET 1 OF 1 PAGE

JOB NO. 05-8126

SUBJECT ACME STEEL - CHICAGO COKE PLANT  
 SOUTH PINION WALL #1 BATTERY  
 ALLEYWAY FLOOR STEEL & CONG. DECK

1998 INSPECTION  
 CSMP NO. 10-Z-11AG



BATTERY #1  
 PLAN  
 ALLEYWAY FLOOR @ EL. 14.5

REFERENCE ACME DWG 37136





ACME STEEL COMPANY

SECTION 1 - GENERAL INFORMATION

Facility: ACME - RIVERDALE Identification No.: 10 - 2 - 1146  
 DIV : COKE PLANT DIVISION Classification No.: C- 9-B- 0  
 DEPT: COKE BATTERIES Reg. Codes: 1.0,1.1  
 Item: SOUTH PINION WALL Year Installed: 1955  
 Item: FLOOR STEEL & CONCRETE DECK Current Status: IN-SERVICE  
 Type Of Struc: ACCESSWAYS  
 Type Of Const: STEEL FRAME Insp. Requirements: DETAIL  
 This Insp Date: 05/07/98 Type: DETAIL Frequency: 24 MO.  
 Next Insp Date: 05/07/00 Type: DETAIL  
 (Unless Adjustment Is Approved) Ref. Drawings: 37089 37136  
 CLIENT INFO: R. MARTELLO  
 :  
 Current OEI Proj. No.: 05-8126 Remarks:  
 Other OEI Ref.:

SECTION 2 - SUMMARY OF INSPECTION

General Condition Assessment  
POOR

<u>Qty. Suggested Repair Priorities</u> (Refer To Priority Desc. Attached)	<u>Recommended Course Of Action</u> (Refer To RCA Desc. Attached)
[ 0] P1-Emergency Repairs Required	[ ] 0-No Action Required
[ 0] P2-Repair Within 30 Days	[ X] 1-Implement Recommendations
[ 5] P3-Repair Within 6 Months	[ ] 2-Detailed Inspection
[ 10] P4-Repair Or Reinspect Within 1 Yr	[ ] 3-Engineering Evaluation
[ 5] P5-No Repairs Required (Ref. Only)	[ ] 4-Design And Detail
	[ ] 5-Adjust Inspection Freq.
[ 20] Total Quantity Of Priorities	[ ] 6-Further Investigation Req.

Previous Inspection History And Assessments

<u>OEI Proj.</u>	<u>Date</u>	<u>GCA</u>	<u># Recom</u>	<u>OEI Proj.</u>	<u>Date</u>	<u>GCA</u>	<u># Recom</u>
1)	/ /		0	3)	/ /		0
2)	/ /		0	4)	/ /		0

SECTION 3 - DISTRIBUTION AND SIGN-OFF

Distribution:

R. MARTELLO

INSPECTED BY: JAK/EES

PREPARED BY: J. KONARSKI

APPROVED BY: J. KIRK

DATE/ENTERED BY: BAL 6/24/98



ACME STEEL COMPANY  
 CRITICAL STRUCTURES MANAGEMENT PROGRAM  
CURRENT MAINTENANCE REPAIR & COMPLETION NOTICE

VISION COKE PLANT DIVISION REPORT DATE 06/24/98

DEPARTMENT COKE BATTERIES

ITEM DESCRIPTION SOUTH PINION WALL  
FLOOR STEEL & CONCRETE DECK

ID. NO. 10 - 2 - 1146 CLIENT INFO R. MARTELLO

FREQUENCY 24 MONTH(S) LAST INSPECTION TYPE DETAILED

ORIG. DATE FINDING ENCOUNTERED	RECOMM. NO.	PRIORITY CODE	S, M, E OR O	REPAIRS IMPLEMENT BY	DATE REPAIR COMPLETED	VERIFIED BY	VERIFIED DATE
05/07/98 D	R1	P3	S		/ /		/ /
05/07/98 D	R2	P3	S		/ /		/ /
05/07/98 D	R3	P3	S		/ /		/ /
05/07/98 D	R4	P5	S				
05/07/98 D	R5	P5	S				
05/07/98 D	R6	P5	S				
05/07/98 D	R7	P5	S				
05/07/98 D	R8	P5	S				
05/07/98 D	R9	P4	S		/ /		/ /
05/07/98 D	R10	P4	S		/ /		/ /
05/07/98 D	R11	P4	S		/ /		/ /
05/07/98 D	R12	P4	S		/ /		/ /
05/07/98 D	R13	P4	S		/ /		/ /
05/07/98 D	R14	P4	S		/ /		/ /
05/07/98 D	R15	P4	S		/ /		/ /
05/07/98 D	R16	P4	S		/ /		/ /
05/07/98 D	R17	P4	S		/ /		/ /
05/07/98 D	R18	P4	S		/ /		/ /
05/07/98 D	R19	P3	S		/ /		/ /



ACME STEEL COMPANY  
CRITICAL STRUCTURES MANAGEMENT PROGRAM  
CURRENT MAINTENANCE REPAIR & COMPLETION NOTICE

DIVISION COKE PLANT DIVISION REPORT DATE 06/24/98

DEPARTMENT COKE BATTERIES

ITEM DESCRIPTION SOUTH PINION WALL  
FLOOR STEEL & CONCRETE DECK

ID. NO. 10 - 2 - 1146 CLIENT INFO R. MARTELLO

FREQUENCY 24 MONTH(S) LAST INSPECTION TYPE DETAILED

ORIG. DATE	FINDING	RECOMM. NO.	PRIORITY CODE	S,M,E OR O	REPAIRS IMPLEMENT BY	DATE REPAIR COMPLETED	VERIFIED BY	VERIFIED DATE
05/07/98	D	R20	P3	S		/ /		/ /

COMMENTS: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

NOTE: Recommendations Not Listed Have Been Previously Checked & Verified