

Acme Coke
11236 S. Torrence Ave.
Chicago IL 60617



acmecoke.com

Document archive

Bustle Pipe Repairs

Dated: 1975-1977

Recovered from site on April 24 2021

INTEROFFICE
CORRESPONDENCE

Date: December 8, 1976

Copies to

To: Mr. N. H. Keyser
From: C. Lin
Subject: Investigation of Bustle Pipe Failures
in Chicago "A" Furnace
Reference: D3-002-001

V. Beaucaire
J. Bitner
R. Langhoff
S. Miller
J. Seaman
R. Winters

Characteristics of Failure:

1. Nearby the major crack, there were lots of secondary cracks. These secondary cracks, as well as major cracks, were perpendicular to bustle pipe direction (radial direction to the blast furnace). (Figure 1).





Figure 1: Location of Cracks

2. All these secondary cracks were straight and transgranular. They were perpendicular to the maximum tension stress direction, and tell us that the bustle wall had no strength at all under that service circumstance. (Figure 2)



Inside
Surface
↑

Bustle Pipe
Direction
↔

Figure 2. Secondary Cracks on Bustle Pipe (X80).

3. Thicker iron oxide at the beginning of the crack (near the surface) than the end of crack indicated that the entire cracking process was a time-consuming process. This process might take months or years just like creep test at elevated temperature (Figure 3).



Inside
Surface
↑

Bustle Pipe
Direction
↔

Figure 3. Typical Bustle Pipe Secondary Crack (X80).

To: Mr. N. H. Keyser
Subject: Investigation of Bustle Pipe
Failures in Chicago "A" Furnace

December 8, 1976
Page 3

4. From AGA picture, the temperature of hot spot on bustle pipe made a big difference with its surrounding. The temperature difference between "before casting" and "after casting" nearby cracking area was only 70° - 80° F.
5. During winter time, workers there could see the bustle pipe moving when winter wind blew.

Reason for Failure: Overheated

Apparently, the overheat of bustle pipe wall is due to the crack of inside refractory lining. The reason why inside refractory lining started to crack first is not entirely known yet. However, two reasons seem possible.

1. Due to thermal expansion, and thermal contraction.
2. Due to wind force.

From engineering drawings, bustle pipe is hung there and could almost move freely if without oak block spacer. According to mathematical calculation, wind force, as well as the shrinkage due to wind chill, could move bustle pipe and cause the lining to crack considerably. Since winter wind is mostly from north direction, maybe that is why the crack on bustle pipe is on the lower side of east direction. The shrinkage, together with wind force, produces a tension force there.

Action to be taken:

Since any kind of mathematical calculation or theory needs to be proved, the best way is to be proved by observation. We will use AGA and a home-make cathetometer to find out the real cause by doing the following:

1. Check the temperature variation on bustle pipe during winter time between wind blowing.
2. Check the bustle pipe movement during windy day.
3. Determine the combined bustle pipe movement due to both wind force and thermal contraction.

If our assumption is right, we will perform one or several of the following items:

1. Close casthouse opening in the north side to stop the wind blow, especially the winter wind. Of course, some new opening on the opposite side will be open.

To: Mr. N. H. Keyser
Subject: Investigation of Bustle Pipe
Failures in Chicago "A" Furnace

December 8, 1976
Page 4

2. Re-install wood blocks to confine the bustle pipe.
3. Attach a circular I-beam to strengthen the bustle pipe.
4. Use heat shield to prevent wind force and wind chill.

Since there is still plenty of time and there is still lots of work to be done before any decision can be made, I will keep in touch with Messrs. James, Langhoff, and Zbos.

C. Lin

C. Lin
Senior Research Engineer

CL/mw

INTEROFFICE
CORRESPONDENCE

Copies to:

Date: ~~January 26, 1977~~

February 10, 1977

V. Beaucaire
J. Bitner
S. Jansto
R. Langhoff
S. Miller
J. Seaman
R. Winters

To: Mr. N. H. Keyser

From: C. Lin


Subject: Investigation of Bustle Pipe Failure in Chicago
"A" Furnace, a Continuation of the Memo of
December 8, 1976

Reference: D3-002-001

After more careful studies, just like what I expected before, the bustle pipe in Chicago "A" furnace has some designing problems. Mr. Nick O'lenik, Chief Mechanical Engineer in Inland Steel, confirmed what I thought. These designing mistakes caused chain reactions, and the end of the chain reactions is what we saw -- cracks on the shell of bustle pipe in Chicago "A" furnace from time to time.

Mr. O'lenik said that the bustle pipe in Inland Steel has both expansion joints and asbestos bricks. Expansion joint is to minimize the movement of bustle pipe due to thermal expansion and contraction, or other causes. The asbestos brick is a compressible type insulation brick and can protect inside brick lining during bustle pipe movement. From various information sources, I found that there was no expansion joint and asbestos brick in our Chicago "A" furnace bustle pipe at all. The following are my suggestions:

1. Close casthouse opening in the north side to stop direct wind blow during winter time, if possible.
2. Add two expansion joints in Chicago "A" furnace bustle pipe inlet. (Fig. 1).



February 10, 1977

To: Mr. N. H. Keyser
Subject: Investigation of Bustle Pipe Failure
in Chicago "A" Furnace, a Continuation
of the Memo of December 8, 1976.

January 26, 1977
Page 2

The expansion joints should be air-tight, just like what we have in Baghouse, Selma, Alabama (DRWG. M-0894 and M-0896).

3. During next bustle pipe relinement, replace the superex block by more compressible superex S.G. Insulating Brick, Johns-Manville*. ~~Add~~ Put some compressible insulating bricks along other brick layers too.** (Fig. 2) (DRWG. C-4064).
4. Re-install wood blocks to confine the bustle pipe (DRWG. AL-2308).




Figure 2

If there is any further problems, please let me know.

C. Lin

C. Lin
Senior Research Engineer

~~* Please consult Steve Jansto for detail.~~

~~** Please consult Robert Winters for detail.~~

* These RF Expansion Joint Boards Can
sustain up to 2300°F, and made by Johns-
Manville. Please consult Steve Jansto for detail.

INTEROFFICE
CORRESPONDENCE

Copies to:

Date: February 23, 1977

To: Mr. N. H. Keyser

V. Beaucaire

From: C. Lin

J. Bitner

R. Langhoff

Subject: Investigation of Bustle Pipe Failure, in
Chicago "A" Furnace

S. Miller

J. Seaman

R. Winters

Reference: D3-002-001; Memo of December 8, 1976

The memorandum of December 8 pointed out that the bustle pipe for Chicago "A" Blast Furnace failed after being weakened from overheating. Despite the nearness of the failed region to the tap hole, surface temperature measurements showed that the heat that caused the damage did not come from external sources, it came from within the pipe. That is, the pipe failure resulted from a failure in the refractory lining. The purposes of this report are to explain why the refractory failed and to recommend measures to prevent similar failure in the future. Also presented are probable reasons for the pipe failing where it did, as compared to other points along its circumference, and why "B" bustle pipe is more durable even though it carries a hotter blast.

Facts Pertaining to the Failure

1. The failure occurred in the region of greatest refractory thickness - 22.5 inches. This includes 9 inches of Superduty Firebrick, 10.5 inches of 2300^oF Insulating Brick and 3 inches of Superex 2000 Block adjacent to the steel shell. Of the three, Superex Block has the lowest crush strength and the highest insulation value. This region of thickest refractory extends for approximately 30 feet as measured along the outside radius of the pipe - from tuyere No. 13 to tuyere No. 2. Forces due to thermal expansion will be greater in this location as compared to areas of thinner refractory.
2. Temperature measurements taken along the bottom of "A" bustle pipe on December 2, 1975 showed the pipe to be hottest along the 30 foot span of thickest refractory, the area where it should have been coolest (Figure 1). This indicates that the entire 30 foot span of refractory had apparently sustained damage prior to that date.
3. Personnel who witnessed the removal and replacement of a failed section of bustle pipe last year reported that the insulation behind the steel had crumbled. This would be the Superex Block.

N.H.K. FEB 25 '77

To: Mr. N. H. Keyser
Subject: Investigation of Bustle Pipe Failure, in
Chicago "A" Furnace

February 23, 1977
Page 2

4. Apparently the Superduty Firebrick and 2300^oF Insulating Brick sustained at least crack damage at the joints. Hot blast has been felt coming thru cracks in the shell, and the temperature measurements taken around a crack on February 4, 1976 showed evidence of hot blast channeling behind the shell⁽¹⁾.
5. As reported in the memorandum of December 8, 1976, the cracks developed on the inside of the bustle pipe and slowly propagated outward until failure occurred.

Probable Sequence of Events for Failure

1. Large thermal expansion forces of the refractory caused the Superex Block to crush in the region of thickest refractory. Cracks may also have developed in the Superduty Firebrick and 2300^oF Insulating Brick networks as well. Gross thermal expansion forces would be greater here than anywhere else along the pipe, so this area would be most susceptible to failure. Since the brick cannot expand lengthwise along the pipe, forces are exerted outward against the steel shell.
2. The Superex Block is the best insulator of the three refractories present and it has the lowest crush strength. Following its damage or destruction due to forces of thermal expansion, the shell rose to some higher-than-normal temperature. It is not known what temperatures were reached on the inside surfaces of the steel; outside surface temperatures of 490^oF⁽¹⁾ and 540^oF⁽²⁾ have been observed near cracks.
3. The weakened steel shell developed a series of cracks on the inside surface and gradually failed as a result of:
 - (a) Internal stresses and its own weight
 - (b) Vibrations
 - (c) Minor thermal expansion/contraction forces as a result of wind chill and 70^o to 80^oF temperature rise during casting.

Compared to "B" Furnace bustle pipe, "A" furnace bustle pipe would be more susceptible to failure because:

1. The area of thickest refractory (21 inches) for "B" bustle pipe extends for only approximately 7 feet as measured along the out-

(1) Memo from S. Jansto to Mr. N. H. Keyser, "Cracked Bustle Pipe - "A" Furnace", February 10, 1976.

(2) Memo from M. Jensen to Mr. N. H. Keyser, "Thermographic Survey Chicago "A" Bustle Pipe", September 24, 1976.

To: Mr. N. H. Keyser
Subject: Investigation of Bustle Pipe Failure, in
Chicago "A" Furnace

February 23, 1977
Page 3

side radius of the pipe. Compared to the 30 foot span (22.5 inches thick) for "A" bustle pipe, stress concentration would be less.

2. "B" bustle pipe is smaller in diameter than "A" bustle pipe, 39 ft. 8 in. compared to 46 feet 0 in. at the center of the pipe. Total thermal expansion of the refractory in the larger pipe would be greater and would tend to produce a greater incremental increase in both the circumference and the radius of the refractory liner [$c = 2\pi r$]. Also, since the circumference is confined, proportionately more stress will release in the radial direction against the steel shell.
3. The lower temperature of "A" Furnace hot blast, c 1600° F vs c 1800° F for "B" Furnace, does not compensate adequately for the two differences cited above.

Recommendations for the Future

1. Include 1/2 inch expansion gaps in the bustle pipe refractory. The spacings of these gaps should be carefully thought out to both provide for refractory expansion and avoid weakening of the refractory structure. The expansion gaps should be filled with 1/2 inch RF Expansion Joint Board. (Johns-Manville).
2. Use Superex SG 2000 in place of Superex 2000 to provide a cushion adjacent to the shell to absorb thermal expansion forces. This cushion will provide for expansion across the width and depth of the refractory bricks. The expansion joints will take care of length-wise expansion.

Less critical but worth considering are:

3. Engineering should review the possible need for an expansion joint in the shell of the hot blast main in the area where it passes thru the cast house wall. The refractory does have expansion gaps, filled with RF Expansion Joint Board, in this region.
4. Re-install and maintain the wooden blocks at the bustle pipe hangers to help confine the pipe and minimize vibrations.
5. During the winter, close the two openings in the north cast house wall closest to the furnace to reduce the direct blasts of cold wind against the bustle pipe. These cold blasts induce small thermal expansion/contraction cycles and vibration.

C. Lin

C. Lin
Sr. Research Engineer

CL/ey




Fig. 1 Chicago "A" Furnace Bustle Pipe Temperature, °F. 12-2-75

INTEROFFICE
CORRESPONDENCE

Copies to:

Date: February 10, 1976

J. L. Bitner
J. D. James
R. E. Langhoff
J. T. Seaman
R. P. Winters
J. A. Zbos

To: Mr. N. H. Keyser

From: S. Jansto

Subject: Cracked Bustle Pipe - "A" Furnace

Reference: D3-001-001

V. J. 2/10/76

On the morning of February 4, the crack on the bustle pipe reopened. Since the thermovision unit was in use at Beverly, Ohio, only surface pyrometer readings could be taken. These temperatures were taken after the 10:00 a.m. cast and the furnace was at approximately 80,000 wind.

Figure 1 illustrates the orientation of the series of temperatures measured.




Figure 1. Orientation of Temperatures

Within the banded region in Figure 1, the following temperatures were measured.

To: Mr. N. H. Keyser
Subject: Cracked Bustle Pipe
"A" Furnace

February 10, 1976
Page 2




Figure 2. Measured Temperatures

The temperature gradient indicates that the hot air may be channeling behind the brickwork from the 9 to 11 o'clock position. Therefore, grouting of the main in this region may patch up any existing channels.

If the crack reopens again, the pipe will be checked with the Thermovision (if available). Possibly, a hot spot line through the brickwork will be visible. Seeing this hot spot, grout could then be pumped into the main at the locations of the hot spot. This grouting should close off any channeling of hot air from the interior of the main out to the crack in the shell.

S. Jansto

S. Jansto

INTEROFFICE
CORRESPONDENCE

Copies to:

Date: September 24, 1976

V. Beaucaire

To: Mr. N. H. Keyser
From: M. D. Jensen
Subject: Thermographic Survey Chicago "A" Bustle Pipe
Reference: D3-022-009

C. Lin
J. T. Seaman
R. P. Winters
J. Zbos

At the request of Mr. Beaucaire, a thermographic study was performed on the "A" furnace bustle pipe in the area where cracking has occurred recently. The survey showed a hot spot measuring 540° F. adjacent to a previous repair. This was verified as an open crack by plant personnel who welded it immediately. Another hot spot was discovered under the new extension of the radiation shield. Temperature measurement of this area is extremely difficult due to the complex shape of the spot, shield and bustle pipe. However, there is definitely a hot spot in this area.

Please note attachments.

M. D. Jensen
M. D. Jensen

MDJ/mw

Attachment

To: Mr. N. H. Keyser

Copies to
V. Beaucaris

J. Bitner

From: C. Lin

R. Langhoff

S. Miller

Subject: Investigation of


J. Seaman

Bustle Pipe Failure, in

R. Winters

Chicago "A" Furnace, ~~at~~

~~Continuation of The~~ Memo
of December 8, 1976

Reference: D3-002-001; 

The memorandum of December 8 pointed out that the bustle pipe for Chicago "A" Blast Furnace failed after being weakened from overheating. Despite the nearness of the failed region to the top hole, surface temperature measurements showed ^{that the heat} that caused the damage did not come from external sources, it came from within the pipe. That is, the pipe failure resulted from a failure in the refractory lining. The purposes of this report are to explain why the refractory failed and to recommend measures to prevent similar failure in the future. Also presented are probable reasons for the pipe failing where it did, as compared to other points along its circumference, and why 3" bustle pipe is more durable even though it carries a

(2)

hotter blast.

Facts Pertaining to the Failure

1. The failure occurred in the region of greatest refractory thickness - 22.5 inches. This includes 9 inches of Superduty Firebrick, 10.5 inches of 2300°F Insulating Bricks, and 3 inches of Superex 2000 Block adjacent to the steel shell. Of the three, Superex Block has the lowest crush strength and the highest insulation value. This region of thickest refractory ~~thickness~~ extends for approximately 30 feet as measured along the outside radius of the pipe - from tuyere No. 13 to tuyere No. 2. Forces due to thermal expansion will be greater in this location as compared to areas of thinner refractory.
2. Temperature measurements taken along the bottom of "A" bustle pipe on December 2, 1975, ~~showed~~ showed the pipe to be hottest along the 30 foot span of thickest refractory, the area where it should have been coolest (Figure 1). This indicates that the entire 30 foot span of refractory had apparently sustained damage prior to that date.

3. Personnel who witnessed the removal and replacement of a failed section of bustle pipe last year reported that the insulation behind the steel had crumbled. This would be the Superex block.
4. Apparently the Superduty Firebrick and 2300°F Insulating Brick ~~was~~ sustained at least crack damage at the joints. Hot Blast has been felt coming thru cracks in the shell, and temperature measurements taken around a crack on February 4, 1976 showed evidence of hot blast channeling behind the shell.⁽¹⁾
5. As reported in the memorandum of December 8, 1976, the cracks developed on the inside of the bustle pipe and slowly propagated outward until failure occurred.

Probable Sequence of Events for Failure

1. Large thermal expansion forces caused the Superex block to crush in the region of thickest refractory. Cracks

⁽¹⁾ Memo from S. Jants to Mr. W. H. Keyser, "Cracked Bustle Pipe - "A" Furnace", February 10, 1976.

(4)

may also have developed in the Superduty Firebrick and 2300°F Insulating Brick networks as well. Gross thermal expansion forces would be greater here than anywhere else along the pipe, so this area would be most susceptible to failure. Since the brick cannot expand lengthwise along the pipe, forces are exerted outward against the steel shell.

2. The Superex Block is the best insulator of the three refractories present and it has the lowest crush strength. Following its damage or destruction due to forces of thermal expansion, the shell ~~temperature~~ rose to some higher-than-normal temperature. It is not known what ~~the~~ temperatures were reached on the inside surfaces of the steel; ~~the~~ outside surface temperatures of 490°F⁽¹⁾ and 540°F⁽²⁾ have been observed near cracks.

3. The weakened steel shell developed a series of cracks on the inside surface and gradually failed as a result of:

- (a) Internal stresses and its own weight
- (b) Vibrations

(2) Memo from M. Jensen to Mr. W. H. Keyser, "Thermographic Survey Chicago 'A' Bustle Pipe," September 24, 1976.

5

(c) Minor thermal expansion/contraction forces as a result of wind and ~~from the~~ chill and 70° to 80°F temperature rise during casting.

Compared to "B" Furnace bustle pipe, "A" Furnace bustle pipe would be more susceptible to failure ~~at a given temperature~~ because:

1. The area of thickest refractory (21 inches) for "B" bustle pipe extends for only approximately 7 feet as measured along the outside radius of the pipe. Compared to the 30 foot span (22.5 inches thick) for "A" bustle pipe, stress concentration would be less.
2. "B" bustle pipe is smaller in diameter than "A" bustle pipe, 39 ft. 8 in. compared to 46 ft. 0 in. at the center of the pipe. Total thermal expansion ~~forces in the larger pipe would have a greater tendency to increase the diameter of the refractory lining~~ of the refractory in the larger pipe would be greater and would tend to ^{produce} a greater incremental increase in both the circumference and the radius of the refractory liner [$C = 2\pi r$]. Also, since the circumference is confined, proportionately more stress will release in the radial direction against the steel shell.

3. The lower temperature of "A" Furnace hot flue, $\approx 1600^{\circ}\text{F}$ vs $\approx 1800^{\circ}\text{F}$ for "B" Furnace, does not compensate adequately for the two differences cited above.

Recommendations for the future

(1) Include ^{1/2 inch} expansion gaps in the bottle pipe refractory, using spacings either similar to those in the hot flue main or based on recommendations of the refractory supplier. The expansion gaps should be filled with 1/2 inch R.F.
Expansion ~~Joint~~ Board. (John-Manville, ~~etc.~~)

(2) Use Superox 56 2000 in place of Superox 2000 to ~~allow an additional cushion for~~ provide a cushion adjacent to the shell to absorb thermal expansion

forces. This cushion will provide for expansion across the width and depth of the refractory bricks. The expansion joints will take care of length-wise expansion.

Less critical but worth considering are:

(3) ~~Engineering Dept review~~ ~~the~~ possible need for an expansion joint in the ~~casthouse~~ shell of the hot blast main in the area where it passes thru the casthouse wall. The refractory does have expansion gaps, filled with R.F. Expansion Joint Board, in this region.

(4) Re-install ^{and maintain} the wooden blocks at the bustle pipe hangers to help confine the pipe and minimize vibrations.

(5) During the winter, close the two openings in the north casthouse wall closest to the furnace to ~~reduce~~ reduce the direct blasts of cold wind against the bustle pipes. These cold blasts induce small thermal expansion/contraction cycles and vibration.

~~If there is any further problems,~~
~~please let me know.~~

C. Lin
SR. Rec. Engineer

Summary

The causes of failures of the bustle pipe and Circle Cake oven gas line for Chicago

"A" furnace have been investigated through ~~metall~~ metallurgically metallography.

The blistering and cracking of bustle pipe was found to be due to overheating.

Using AGA check-up bustle pipe constantly was recommended. Patch the overheated area and overhaul the ^{refractory} lining during furnace shutting down seems to be the only solution.

shutting down.

The burst of COG line was caused by
material
corrosion. No other ~~better~~ recommendations can
be better than mild steel. ^{in our situation} So.

So, increasing wall thickness on COG line
was the recommendation.

Introduction

Two distinct failures of steel piping would be investigated under this project.

First one, the bustle pipe, which provides air or oxygen to ^{Chicaps} ~~the~~ "A" furnace, has been ^{disturbed &} cracked ^{several times} ~~more than once~~ recently. Serious crack may

lead toward shutting down the entire blast furnace operation. The financial loss due to delay of production time would be hard to estimate.

On the other hand, the ^{Circle} Coke oven gas line, ^{which} provides the ~~supplimentally~~ fuel to the blast furnace, ~~is~~ ruptured recently. The sudden

emergence of a large amount of coke
oven gas into the vicinity of the blast
furnace area could cause a deadly
explosion.

To find out the real causes of these
failures ~~would~~ ^{and} ~~would~~ ^{to provide} ~~prevent~~ ^{providing} the remedies for them
is essential.

Recommendation

Bustle Pipe

As long as the refractory lining could not be repaired during furnace operation, the only way to reduce the hazard of further widening of cracking is to check regular through AGA and patch with the same Carbon steel plate.

Spray water on overheated area in case of

red hot. Repack ~~Retine~~ the refractory lining in

bustle ^{pipe} ~~Pipe~~ during furnace shutting down.

Coke Oven Gas Line

Same material (mild steel 1020 or 1025)

with thicker wall was the recommendation.

Check wall thickness regularly.

Conclusion

Bustle Pipe

- The blisterings and cracks were perpendicular to the bustle pipe direction.
- All ~~the~~ cracks ~~was~~ ^{were} opened up from inside wall.
- Overheat ~~was~~ ^{is} due to the inside air flow not the radiation during casting.
- Cracking was a time consuming process. It may take months or years.
- The shape of crack indicates that the wall of bustle pipe had no strength at all under that service circumstance.
- The cracks and blistering are due to overheating.

Coke Oven Gas Line

- This COG line was made of either carbon steel or low alloy steel with 0.20 - 0.30% carbon.
- The burst was parallel to the pipe direction, because this seamless pipe was made ~~by~~ by extruding method.
- The origin of burst could be identified by the river pattern.
- The ^{cleavage of} burst was 45° to the radial direction which had the highest shearing stress.
- Most of the corrosion, here, was ^{uniform} general corrosion; however, there were some pitting corrosion.
- There was no stress corrosion cracks.
- These corrosion pits ^{could} ~~can~~ cause stress concentration and thus led to failure.
- Major cause of burst is due to corrosion.

Observation, Discussion and Results

Bustle Pipe

Bustle pipe provided the necessary air or oxygen for blast furnace. According to ASTM specification, bustle pipe is made of $A285_{\text{Grade C}}$ ^{which} is similar to 1025 Carbon steel. The




Fig. 1 Location of Bustle Pipe related to Blast Furnace

location of bustle pipe related to blast furnace is shown in Fig. 1. The cracking area was cut up and brought to the laboratory for further investigation. The shape of cracks is shown in Fig. 2



UP
↑

⊗ Outside
⊙ Inside

Fig. 2 The Cracks on Bustle Pipe




Fig. 3 Cross Section of the Crack Area.

The first appearance of the cracks on that bustle pipe was similar to the crack of mud pie due to shrinkage after drying.

Sampler from different locations were cut-up, mounted, and ready for metallographic study (Fig. 4).




Fig. 4 Locations of ~~Cut up~~ Sampler for Bustle Pipe

Sample No. 1 through No. 4 were in the vicinity of the major crack. No. 5 and No. 6 were away from the major crack. All secondary cracks were found to be straight, ~~and~~ transgranular, perpendicular to maximum tensile direction and 6 and containing iron oxide. (Fig. 5)





Fig. 5 Secondary Cracks on Bustle Pipe



Inside
↑

Fig. 6 Secondary Cracks on Bustle Pipe

They looked the same as these of creep test sample at elevated temperature. In addition, more iron oxide at the beginning of the crack than in the end indicated that the entire cracking process was a time-consuming process (Fig. 7). The cracking process

might take months or years.




Fig. 7 Typical Secondary Crack on Bustle Pipe

All in all, they indicates that ~~the carbon~~
 the carbon steel was almost no strength at all
 under that service circumstance, ~~Since the~~
~~cracks were perpendicular to the tensile direction,~~
 and
~~it is very clear that~~ the bustle pipe at our
 specified area had been overheated.

Overheated can be, and has been, suspected from two different sources:

① Radiation during casting.

② Leakage in the refractory lining inside bustle pipe. Air flow, inside bustle pipe, is approximately 1700°F .

In order to ^{find out} clarify which one is correct,

AGA was used to measure the bustle pipe

temperature before and during casting. See Appendix

for detail. It was found that the typical bustle

pipe wall temperature usually only went up ^{$70^{\circ}-80^{\circ}$} $50^{\circ}-60^{\circ}$

during casting in Fahrenheit. Blistering is always towards outside.

The hot spots, according to AGA picture, ~~were~~

always ^{had an} odd shape, not a regular shape, and
had ^{big temperature ~~gradient~~ ^{difference}} ~~made~~ a sharp ~~different~~ with ~~it~~ ^{its} surrounding.

Moreover, the opening of the crack was always
from the inside wall. Based on these reasons,
Overheat should be due to the ^{leakage of} inside refractory
lining in bustle pipe.

The spheroidized Carbide seems to indicate that this portion had been overheated to 800°F or more for a certain amount of time.

Unfortunately, we could not get samples from other locations (at least 3 or 4 feet away from this hot spot) or unused sample from the same heat. Since the stress release at

~~1100~~¹¹⁰⁰ - 1200°F, ^{required} specified by A285 specification,

yielded some spheroidized Carbide, ^{too} ^{information} this evidence

became not useful.

Change A285 to other high temperature alloy or low-alloy steel with 0.5-1.0% Mo is

recommended
not profitable here. Reasons are very simple!

If all bustle pipe was made by expensive alloy steel, cost would be too high. If only the overheated spot patched by low-alloy steel with 0.5 - 1.0% Mo, the welding might not hold, since the bustle pipe was constantly subjected to severe temperature change.

Coke Oven Gas Line

Coke oven gas line provides the supplemental fuel for blast furnace in addition to coke.

The location of coke oven gas line in relation to blast furnace & bustle pipe is shown in Fig. 11, and

Fig. 12:



Fig. 12. COG Pipe is underneath the Bustle Pipe.




Fig. 11. Vertical View of COG Pipe, Bustle Pipe & Blast Furnace. COG Pipe is underneath the Bustle Pipe.

This gas line, originally purchased from U.S. Steel during 1964, was a type of 6" diameter seamless pipe. Material specification was not able to obtain. However, judging from metallographic study, it should be made of low-alloy steel or carbon steel with 0.2%-0.3% Carbon. Whether it is low alloy steel or carbon steel, it is the same from fractographical point of view. The hardness of this pipe line is pretty soft, $R_B \approx 80$.

The shape of burst and locations of samples are shown in Figure 13.




Fig. 13 Shape of Burst and Locations of Samples for COG Line

The inner wall usually was corroded by Uniform General Corrosion. (Fig. 14)



Fig. 14 ^{Uniform} General Corrosion on COG Inner Wall

However, there were some pitting corrosion existed. These ^{pitting} ~~pitting~~ corrosion provided

stress concentration and finally led to rupture.

Some pits even ~~went~~ ^{penetrated} extreme ~~way~~ ^{way} deep into the wall (Fig. 17)

(Fig. 15)




Fig. 15 Pitting Corrosion on ^{COG} Inner Wall.

The fractograph of coke oven gas line reveals that the origin of rupture was

The cleavage of burst was 45° to COG Pipe radial direction p. 9
which had the highest shearing stress.

Originated from the middle of burst and
quickly spreaded towards two end




Fig. 16 Some ~~of the~~ pitting Corrosion with
Less Severe Stress Concentration.

On the Origin, two defects, one defect
and river pattern
on each surface, were found. These defects,
I believe, ^{were} is originated from the pitting

Corrosion. The wall thickness along the rupture path had been greatly thin-down by ^{Uniform} ~~General~~ corrosion. Few pitting corrossions, relatively sensitiveless of pit notch on mild steel, and the lack of stress corrosion cracks is the reason why this COG line could last for 12 years.

It seems to be ^{very} pretty hard to make a recommendation to substitute ^{this} mild steel by some other material. As we know, all brass or Copper metal is out of question, since Coke Oven gas contains lots of ammonia. All 300 or 400 level stainless steel

(except 316 or 321) are out of question too, since there is few Oxygen in the coke oven gas and naphthalene can aggregate crevice or pitting corrosion. Cast iron will not fit ^{either} ~~how~~ too, since it could not be bended. Finally, ^{Stainless} ~~321~~ ³¹⁶ and Carpenter ^{are} ~~2000~~ are too expensive. That is the reason, I believe, to increase the wall thickness and use the same material (mild steel) will be the best answer.