# Acme Coke 11236 S. Torrence Ave. Chicago IL 60617



## acmecoke.com

Document archive

Winterization Lists Dated: 1990-1992, 1995-1998, 2001

Recovered from site on Dec 25 2020

#### ACME STEEL COMPANY CHICAGO COKE PLANT

## 1990 WINTERIZATION LIST COKE OVENS DEPARTMENT

- \* TRACER HOT RAILS AT QUENCH STATION. 12/15
- 2. INSULATE MAKEUP WATER LINES AND VALVES.
- \* REPAIR OR REPLACE TRACER LINES FOR MAKEUP WATER LINES.
- A. DRAIN MAKEUP WATER LINES.
- 5. CLOSE WINDOWS IN ALLEYWAY AND BASEMENT. Deating
- #. INSPECT ALL MACHINERY HEATERS.
- /. INSPECT AND REPAIR LARRY CAR AIR DILER SYETEM.
- 2. INSPECT FLUSHING SYSTEM IN QUENCH TOWER.
- %. INSPECT AND REPAIR STEAM HEATERS IN DOOR REPAIR AREA.
- . ORDER TARPS FOR WINDBREAKERS.
- 11. REPAIR INSULATION ON CHARGING STEAM LINES.
- 12. INSPECT HEAT TRACERS AIR SYSTEM ON BOTH LARRY CARS. 13/15
- REPAIR WOOD ROOF ON THE NORTH AND SOUTH SIDE OF THE QUENCH STATION.
- INSPECT CHARGING AND SIDE STEAM TRAPS ON TOP OF BATTERIES.
- 15. REPAIR AS NEEDED TRANSITE SHEETING ON BOTH BATTERIES. 12/15
- 16. INSPECT HEATER IN H.K.C. (BOTH ROOMS).
- X +2 Bat Rain covers Nov 220
- 18 HKC stoom Fed to Fan
- A Flush all gear boxes
- 26 Bin gate iteam heater
- 21 wood doors in basement 1/18
- 22 Steam tracers drip Legs HKC 12/15
- 28 Relocate steam line to dog house # 1 Bat.

#### ACME STEEL COMPANY CHICAGO COKE PLANT Date: 09/06/91

#### 1991 WINTERIZATION LIST BY-PRODUCTS DEPARTMENT

- 1. RE-INSULATE THE LOW PRESSURE STEAM LINE FROM THE EXHAUSTER BUILDING TO THE NAPTH BAYS
- 2. RUN STEAM FEED TO THE TOP OF THE LBA'S
- 3. TRACE AND INSULATE GAS DRIPS ON THE NEW EXCESS GAS MAIN
- 4. SUCTION MAIN DRIPS
- 5. REPAIR METHANOL PUMP IN THE POWERHOUSE
- 6. INSULATE NORTH AND SOUTH DECANTER PUMPS
- 7. INSTALL PLYWOOD ON EXHAUSTER BUILDING WINDOWS
- 8. INSULATE STEAM LINES TO THE TAR COLLECTOR TANK
- 9. INSULATE FISHER VALVES AND AIR LINES AT LIGHT OIL
- 10. RUN AIR LINE HEADER ON EAST WALL OF EXHAUSTER BUILDING
- 11. FABRICATE NEW STEAM FLASH POT AT THE TAR COLLECTOR TANK
- 12. REPLACE CRACKED DRAIN PIPES ON THE LOW PRESSURE STEAM VENTS AT THE EXHAUSTER BUILDING
- 13. REPIPE 150# STEAM FEED INSIDE THE WEST WALL OF THE EXHAUSTER BUILDING

#### ACME STEEL COMPANY CHICAGO COKE PLANT Date: 09/06/91

#### BY-PRODUCTS DEPARTMENT AREAS THAT NEED LOCKOUT

- STEAM TURBINES
- GAS BOOSTERS

Parent

- EXHAUSTERS
  STEAM GAS,STEAM
  ELECTRIC GAS,ELECTRIC
- HIGH PRESSURE STEAM LINES
- ACID LINES
- CAUSTIC LINES
- GAS BLANKETING SYSTEMS
- TAR PUMPS / LINES
- AIR COMPRESSORS

Het III

#### ACME STEEL COMPANY CHICAGO COKE PLANT

1991 WINTERIZATION LIST COKE OVENS DEPARTMENT

Class-op bogging Loom

- 1. INSPECT/REPAIR MAKEUP WATER LINES AND VALVES. 10
- Z. H.K.C. STEAM FEED TO FAN TRACERS. Started Friday 9/27/91
- J. DRAIN MAKEUP WATER LINES. Conpt.
- 4. CLOSE WINDOWS IN ALLEYWAY AND BASEMENT. / Chock +
- 3. INSPECT ALL MACHINERY HEATERS. 19/5 -
- F. DRAIN AND FLUSH HYDRAULIC SYSTEMS ON DOOR MACHINES. COMPT.
- T. STEAM TRACERS ON DRIP LEGS FOR BLEEDER FLARES.
- 8. INSPECT AND REPAIR STEAM HEATERS IN DOOR REPAIR AREA FAN MOTOR . . . KICKS OUT LIGHTS. Complete
- 9. WOODEN DOORS ON #1 AND #2 BATTERY, COKE SIDE. Compt.
- 10. REPAIR INSULATION ON CHARGING STEAM LINES. Check
- 11. INSPECT HEAT TRACERS AIR SYSTEM ON BOTH LARRY CARS. 19/15 .
- 12 REPAIR AS NEEDED TRANSITE SHEETING ON BOTH BATTERIES. . Here &
- 13. SALAMANDERS FOR WATER BLASTERS. 12/1.
- 14. FLUSH ALL GEAR BOXES. IN OCT
- 15. BIN GATE STEAM HEAT TRACERS. /Check -
- 16. Lubs for larrycar air system
- IT. Steam tracers for Hot rail Quench Station.
- 18 Poors in door repair area

#### ACME STEEL COMPANY CHICAGO COKE PLANT

Date: 09/04/91

Copies To:

- TO DICK O'HEARN
- From: DOUG PODGORNY

9463 -- 1991 COAL HANDLING WINTERIZATION LIST

#### GENERAL MAINTENANCE:

- 1. FABRICATE (8) SALAMANDERS.
- 2. FABRICATE AIR LANCES OF VARIOUS LENGTHS.
- J. FABRICATE SCRAPER BARS.
- 4. CHECK TRAPS, LINES, VALVES, HEATERS AND COAL AND COKE STEAM.
- 5. NEED (2) DRUMS WASTE DIL TO C-21 TRANSFER HOUSE.
- 6. NEED SPARE HOSES FOR WHARF.
- 7. REPLACE SEVERAL LEAKY VALVES, CHICAGO FITTINGS FOR WHARF HOSES.
- 8. CHECK STEAM TRACING FOR WHARF WATER.
- 9. INSTALL WINTER DOORS ON EUCLIDS.
- 10. REPAIR/ACTIVATE HEATERS ON MOBILE EQUIPMENT.
- (E) 11. CLEAN, CHECK AND INSTALL HOT WORKS BURNERS FOR COAL AND COKE WHARF BY NOVEMBER 15.
  - 12. INSTALL GUARDS FOR FROPANE TANKS; COMPLETE PROPANE PIPING BY NOVEMBER 15. (SEE AREA MANAGER)
  - 13. CHECK LINES, REPLACE VALVES AND NOZZLES AS NEEDED FOR DUMPER SPUR TRACK.
  - 14. INSTALL NEW B.D.O. VALVE.
  - 15. REPLACE BOARD AT THE TAIL END OF "T" BELT.
  - 16. REFLACE BOARD AT THE HEAD END OF "W" BELT.
  - 17. 1st WINDOW (NORTH) ON EAST SIDE AND 1st (3) WINDOWS (NORTH) ON THE WEST SIDE OF MIXER BINS ARE BOARDED UP WOULD LIKE AT LEAST (1) ON EACH SIDE TO BE PLEXI-GLASS TO ALLOW NATURAL LIGHT IN THE AREA.

- 18. CHECK CONDITION OF C-22 BELT AND ALSO THE TAIL END CARRIAGE STRUCTURE.
- 19. STEAM HEATER FOR EUCLID SERVICE STORAGE AREA.
- (E) 20. ELECTRIC LIGHTS FOR EUCLID SERVICE STORAGE AREA.
  - 21. REPAIR BROKEN WINDOWS AND HOLES IN ROOF OF EUCLID PARKING AREA AND SERVICE STORAGE AREA.

#### TRANSITE REPAIRS:

- 1. #4 BELT ROOF AND SIDING
- 2. #4 BELT DOORS AND WINDOWS
- 3. TRANSITE AT C-21 HEAD END ROOF
- 4. "W" BELT MID INCLINE ABOVE WINDOW
- 5. "Y" BELT ROOF
- 6. TAIL END C-22 WALLS PATCH 2 OF 3 HOLES

#### CLEAN UP:

- 1. "D" DECKING FEEDER AREA
- 2. E-1 DECKING
- 3. E-2 AREA STORE TOOLS, CLEAN COAL, REPLACE COVER
- 4. E-3 LEVEL CLEAN COAL, STORE TOOLS
- 5. AREA AROUND E-SHANTY; ALSO REMOVE STEMS FROM ROOF
- 6. "T" DECKING WEST SIDE TAIL END TO MID BELT
- 7. CLEAN ALL OPERATOR MAN SHANTYS
- 8. HEAD END "T" CLEAN WALKWAYS AND STORE TOOLS
- 9. HEAD END OF "A"
- 10. "C" BELT DECKING AND WALKWAY
- 11. SWEEP OUT CAGE CONTROL ROOM DAILY AND CLOSE DOOR
- 12. "W" DRIVE CARRIAGE CLEAN <u>COMPLETELY</u>; ALSO EAST AND WEST SIDES OF SAME

- 13. CLEAN OFF ROOF FOR TRANSITE REPAIRS BY #4 BELT
- 14. CLEAN ENTIRE LEVEL C-20
- 15. CLEAN AND FREE UP SAMPLER DOOR EAST SIDE C-21
- 16. C-21 WALKWAY TAIL END AND PLOW AREA
- 17. GENERAL CLEAN UP HEAD END C-21; REMOVE SCRAP, EMPTY DRUMS AND BUCKETS
- 18. DO NOT BUILD OVERSIZE FILE UNDER C-21
- 19. #1 BELT DECKING UNDER WHARF ON BOTH SIDES
- 20. WALKWAY ON THE COKE STACKER BELT
- 21. #4 BELT DECKING AND RETURN; WALKWAYS

#### MATERIALS NEEDED:

1. TARPS

COAL RECLAIM HOPPER  $(4) - 16' \times 24'$ "W" DRIVE  $(4) - 10' \times 12'$ 3 PRIME  $(1) - 16' \times 24'$ 

- 2. SALT BULK / BAG STORE STOCK
- 3. PROPANE TANKS AND FUEL IN THE PLANT BY NOVEMBER 15
- 4. WINTER FUEL FOR MOBILE EQUIPMENT OCTOBER ORDER TO BE 50% #1 NOVEMBER ORDER TO BE 75% #1 DECEMBER ORDER TO BE 100% #1
- 5. ORDER SCRAPER BAR BLADES 4" (\$7.50 EACH) W. ROSE INC.

#### ACME STEEL COMPANY CHICAGO COKE PLANT

Date: 09/06/91

TO: ELECTRICAL DEPARTMENT

From: COAL AND COKE HANDLING

Subject: SAFETY ITEMS REQUIRING ATTENTION

- 1. OPEN JUNCTION BOX ABOVE A.C. CONTROL PANEL COAL HANDLING LOCKERROOM
- 2. GLASS PROTECTOR FOR LIGHT AT E-4 TO E-5 TRANSFER CHUTE
- 3. GLASS PROTECTOR FOR LIGHT ON EAST SIDE OF E-5 WALKWAY
- 4. GLASS PROTECTOR FOR LIGHT AT POINT "R" ALONG "T" BELT
- 5. GLASS PROTECTOR FOR LIGHT AT "W" PIT EAST SIDE OF BELT (2) LIGHTS
- 6. GLASS PROTECTOR FOR LIGHT AT "W" BELT BY WEST DOORWAY
- 7. GLASS PROTECTOR FOR LIGHT AT "W" BELT AT MIXER BIN SHANTY
- 8. GLASS PROTECTOR FOR LIGHT AT MIXER MACHINE NORTH AND CENTER
- 9. GLASS PROTECTOR FOR LIGHT AT C-21, JUST NORTH OF RECLAIM CHUTE

## 1992 WINTERIZATION LIST COKE OVENS DEPARTMENT

- 1. Inspect/repair makeup water lines and valves.
- 2. H.K.C. steam feed to fan tracers.
- 3. Drain makeup water lines.
- 4. Close windows in alleyway and basements.
- 5. Inspect all machinery heaters.
- 6. Drain and flush hydraulic systems on Door Machines and Pushers.
- 7. Steam tracers on drip legs for bleeder flare stacks.
- 8. Inspect and repair steam heaters in Door Repair area.
- 9. Inspect/repair wooden doors on #1 and #2 Battery coke side allies.
- 10. Repair insulation on charging steam lines.
- 11. Inspect heat tracers on air systems on both Larry Cars.
- 12. Repair as needed the transite sheeting on both batteries.
- 13. Install salamanders for water blasters.
- 14. Flush all gear boxes.
- 15. Inspect/repair the bin gate heat tracers.
- 16. Install salamanders for the Patcher area.
- 17. Install a canvas curtain on the east side of the water blasters.
- 18. Inspect/repair quench car third rail's steam tracing by station.
- 19. Dig out and lubricate quench car track switch on north end.
- 20. Petibone to clean both tracks north of switch.
- 21. United & Quigley to inspect/repair soup tank pump heaters.
- 22. Install plywood around three sides under each of the soup tanks.
- 23. Repair insulation on charging steam regulators on cross-overs.
- 24 Inspect/repair the doors on quencher pump house.
- 25. Inspect/repair the doors on H.K.C. building.
- 26. Inspect/repair the steam heaters in H.K.C. building.
- 27. Inspect/repair all steam traps on top of both batteries and under the suction main.
- 28. Pallet of salt or bucket of salt to be positioned at the north end of #1 Battery, and on east side of Quench Station.

: Steel Company

Acme Steel Company Chicago Coke Plant 10/19/95

1996 Winterization List Coke Ovens Department

- 1.Inspect/repair makeup water lines and valves.
- ok2.H.K.C. steam feed to fan tracers.
- ∠3.Drain makeup water lines.
- 4.Close windows in alleyway and basements.
- 5.Inspect all machinery heaters.
- (k6.Drain and flush hydraulic systems on door machines and pushers.
- ck7. Inspect and repair steam heaters in door repair area.
- ok 8. Inspect/repair wooden doors on #1 and #2 battery coke side allies.
  - 9. Repair insulation on charging steam lines.
  - 10. Inspect heat tracers on air systems on both larry cars.
  - 11. Repair as needed the transite sheeting on both batteries.
- ★12.Install salamanders for water blasters.
- 13. Flush all gear boxes.
  - 14.Inspect/repair the bin gate heat tracers.
- ▶ 15. Install salamanders for the patcher area.
- ▲ 16.Install a canvas curtain on the east side of the water blasters.
  - 17. Inspect/repair quench car third rail's steam tracing by station.
  - 18.Dig out and lubricate quench car track switch on north end.
  - 19. Petibone to clean both tracks north of switch.
- ok20.United & Miteak to inspect/repair soup tank pump heaters.
  - 21. Install plywood around three sides under each of the soup tanks.
  - 22. Repair insulation on charging steam regulators on cross-overs.
  - 23. Inspect/repair the doors on quencher pump house.
- dk24.Inspect/repair the doors on H.K.C. building.
- & 25. Inspect/repair the steam heaters in H.K.C. building.
- 26.Inspect/repair all steam traps on top of both batteries and under the suction main.
- 27. Inspect/repair old Fire Pump house, door.

10/19/96

Acme Steel Company Chicago Coke Plant

1996 Winterization List Coke Ovens Department

1. Inspect/repair makeup water lines and valves. - Insulate 2.H.K.C.steam feed to fan tracers. 3. Drain makeup water lines. 4 Close windows in alleyway and basements. 5. Anspect all machinery heaters. 6. Drain and flush hydraulic systems on door machines and pushers. If In Lost 7. Inspect and repair steam heaters in door repair area. 8. Inspect/repair wooden doors on #1 and #2 battery coke side allies. 9. Repair insulation on charging steam lines. 10: Inspect heat tracers on air systems on both larry cars. 11. Repair as needed the transite sheeting on both batteries. 12. Install salamanders for water blasters. 13. Flush all gear boxes. - LARRY CARS NEEDED 14. Inspect/repair the bin gate heat tracers. 15. Install salamanders for the patcher area. 16. Install a canvas curtain on the east side of the water blasters. 17. Inspect/repair quench car third rail's steam tracing by station. Thores, 18. Dig out and lubricate quench car track switch on north end. 19. Petibone to clean both tracks north of switch. 20. United & Min-Teq to inspect/repair soup tank pump heaters. 21. Install plywood around three sides under each of the soup tanks. 22. Repair insulation on charging steam regulators on cross-overs. 23. Inspect/repair the doors on quencher pump house. 24.Inspect/repair the doors on H.K.C. building. 25. Inspect/repair the steam heaters in H.K.C. building. 26. Inspect/repair all steam traps on top of both batteries and under the suction main.

## 1996 WINTERIZATION LIST-OVENS DEPARTMENT

UPDATE10/21/96	COMPLETE
(1) STEAM TRACERS HKC -REPAIR AS NEEDED	W.I.P.
(2) DRAIN MAKE-UP WATER LINES	-
(3) SECURE ALLEYWAY WINDOWS	
(4) INSPECT/REPAIR ALL MACHINE CAB	
HEATERS	
(5) DRAIN AND FLUSH-CHANGE FILTERS-ALL MACHINE HYDRALICS	
(6) INSPECT REPAIR AS NEEDED WOODEN	W.I.P.
DOORS-ALLEY-QUENCH STATION	
(7) INSULATE STEAM LINES AND	
REGULATORS	
(8) INSPECT/REPAIR HEAT TRACERS	W.I.P
BOTH LARRY CARS	
(9) INSTALL STEAM HEATERS- PATCHER	W.I.P.
AREA LIQUA BLASTER AREA	
10) REPAIR/REPLACE STEAM HEATER	W.I.P.
DOOR REPAIR AREA	
11) CANVAS FOR LIQUABLASTER AREA	(2) ON HAND-WILL ORDER MORE
12) INSPECT/REPAIR BIN GATE TRACERS	10/11 per
	MARKO
14) CLEAN OUT/ LUBRICATE NORTH	10/10 per
Q .TRACK SWITCH	DJP
15) STEAM TRACER- HOT RAIL- AT QUENCH	10/18 per
STATION	MARKO
16) VENDOR TO WINTERIZE LUTING MATERIAL	W.I.P
AND DELIVERY SYSTEM	
17) INSPECT/REPAIR STEAM HEATERS HKC	10/11 per
RECYCLE PUMP ROOM	MARKO
17) INSPECT/REPAIR STEAM TRAPS-ALL	W.I.P.
18) HKC DAMPER/ROD BED KEEP FROM	
FREEZING- METHOD ????	
19) WEATER SHIELDS ON HOT RAILS	NEED OUTAGE
20) CLEAN OUT AROUND QUENCH STATION	109/15 per
DOORS	DJP

### 1997 COAL & COKE HANDLING WINTERIZATION LIST

- I. Coal Receiving, Dumper, Ground Hopper.
  - 1) Repair south door E-5, latch.
  - 2) Repair door hinges and roof at E-4 tunnel entrance.
  - 3) Install scoreboard.
  - 4) Replace north syntron chute.
  - 5) Patch holes in south syntron chute.
  - 6) Repair burned out coal field tower lights.
  - 7) Repair scraper E-4 belt.
  - 8) Repair scraper E-5 belt.
  - 9) Repair scraper S belt.
  - 10) Install wear plates head end E-5 chute.
  - 11) Check heaters on Euclids.
  - 12) Repair transite on dumper building.
  - 13) Repair spur track COG line.
- II. Pulverizer Building.
  - 1) Install start/stop switch for W belt, ground level west doorway.
  - 2) Replace transite on south side of building, tail end of C belt.
  - 3) Repair holes in chute above cage paktor.
  - 4) Repair or replace door on northwest corner of pulverizer building.
  - 5) Repair or replace lip plate, bottom of hammer mill shaker screens, north end.
  - 6) Extend Cage Paktor air duct, west side of building.
  - 7) Replace transite above W pit sump pump.
  - 8) Fabricate and install platform or walkway at south side of Cage paktor feeder.
  - 9) Reline chute head end of T belt.
  - 10) Replace window head end east side of T belt.
  - 11) Replace skirt rubbers tail end of T belt.
  - 12) Reline S & T chute.
  - 13) Inspect and repair as necessary steam heaters in pulverizer building.
- III. Mixer Building and Mixer Bins.
  - 1) Repair door on south east side of whistle.
  - 2) Replace transite on north side of mixer building.
  - Repalce steam heater in mixer shanty.
  - 4) Insulate all steam lines under mixer building.
  - 5) Repair window on east side of mixer building.
  - 6) Upgrade lighting in whistle.
  - 7) Inspect and repair as necessary steam heaters in mixer building.
- IV. Charging Bins, C-20, C-21, C-22.
  - 1) Replace 3 window panels on south west corner charging bins.
  - 2) C-20
    - Replace window south east side.
    - Replace window south west side.
    - Replace transite on south east side.
    - Replace transite on south west side.
  - 3) C-21
    - Replace window on east side by C-21 drive.
    - Replace transite along east side between drive and tail end.
    - Replace window at bottom of incline on east side.
    - Replace window half way up incline on east side.
    - Replace window half way up incline on west side.
    - Replace missing roof panels south west corner on head end.
    - Replace wear plates in head end chute, coal hangs up in winter.

Replace window on north side near top of incline.

Replace window on south side near top of incline.

Replace window on south side near bottom of incline.

Replace missing window panel (green corrigated) at head end.

Replace worn out wear plates in head end chute, coal hangs up in winter.

#### V. #4 Belt and Wharf

- I) Replace transite on west side by control room.
- 2) Replace transite on south end of wharf.
- 3) Replace transite by reclaim belt.
- 4) Replace transite north of #1 belt, north west corner of transfer house.
- 5) Install tarp for #3 prime.
- 6) Get salamanders in position and ready.
- 7) North side of #4 belt loose sheeting by return idlers #57, #61 and #75.
- 8) Loose sheeting on top of west incline on #4 belt.
- 9) Repair broken door hinges on door on west end of the river span.
- 10) Replace door frame at #11 fire extinguisher.
- 11) Repair window by #11 fire extinguisher.
- 12) Repair door hinges on door by #9 fire extinguisher.
- 13) Repair broken door frame on door by #3 fire extinguisher.
- 14) Loose sheeting by doorway at #3 fire extinguisher.
- 15) Make sure water valves on wharf have holes drilled through them.
- 16) Make up 6 spare water hoses.

#### VI. Service Building

- 1) Install roof on building.
- 2) Install steam station for service man.
- 3) Repair south roll up door.
- 4) Inspect steam heaters and repair as necessary.
- 5) Buy 4 more shelf units in storage room for motors and Mtce. parts.
- 6) Replace 2 broken windows.

### VII. CCH Locker room and offices.

- 1) Inspect heaters and repair as necessary.
- 2) Check for any broken or missing windows.

#### VIII. Mobile Equipment

- 1) Install winter doors on euclids.
- 2) Inspect and repair heaters in cabs.
- 3) Seal up holes in euclid cabs.
- 4) Inspect and repair as necessary mobile equip. block heaters.


### IX. BDO Pump Room and CCH Fire System

- !) Inspect and repair steam leaks.
- 2) Inspect and repair oil leaks.
- 3) Install heat exchanger for oil.
- 4) Check to make sure fire system headers are drained.

#### X. General

- 1) Close all windows and doors throughout department.
- 2) Fill all bulk oil tanks with waste oil.
- 3) Order tarps, four 20'x24' and four 10'x12'.
- 4) Install wind protection for W belt drive.
- 5) Order winterized diesel fuel.
- 6) Install all hot works heaters.
- 7) Order propane tanks and place them at all hot works heaters.


### 1998 OVENS WINTERIZ



### OPERATIONS--ASSIGNMENT AND DEADLINE-BY ITEM-AS LISTED

- ⇒ DRAIN MAKE-UP WATER LINES- ARROYO--11/15/97
- ⇒ CLOSE WINDOWS IN ALLEY AND BASEMENT--ARROYO--11/15/97
- ⇒ INSTALL CANVAS CURTAIN BY WATERBLASTER---MACLIN--11/1/97
- CLEAN AND LUBE O. TRACK SWITCH N. END-7/3 CREW DAY OF OUTAGE
- ⇒ INSPECT ALL BATTERY, Q. STATION, MACHINERY AND HKC DOORS--LIST OF REQUIRED REPAIRS TO DJP---E. BROWN--9/29/97
- ⇒ SURVEY STEAM LINES AND TRAPS -TOPSIDE- LIST OF REQUIRED REPAIRS TO DJP-- #1 BATTERY-J. POE #2 BATTERY M BLAIR-9/29/97
- ⇒ CLEAN OUT HKC COUNTERWEIGHT CARRIAGE---7/3 CREW DAY OF OUTAGE
- ⇒ CONTACT VENDOR--LUTING MATERIAL WINTER PREP--PODGORNY-10/15/97

11.				
HKC - doors				
D STATION	- 8/6			
1 Justier	- OK			
2 pushes	- O/C			1.41
1 D.M -	- OK	. (	de a sper	expired flees OF
2 D.M -	Lower Level	LOK Access 5h	UT METAI	Level fleer OF Covering opening
	Terre wordmill	Carried D	NOW.	
#1 Q.C.X	ALONG BOTTOM.	disched)	on on-bei	- WON'T STAY
	20175111	4	Atched.	
#2 9.0	mestal,		u Area - a	leeds New States
#1 - 6.0.	doors - 0	1k		
#2 L.C.	doors- or			
		AND THE STATE OF T	0 **	- OFFICE
longs out	BATTERY AR	e ok A.	- peresent	· · · · · · ·
OOK NEED	S GATCH)	re DK A.	- peresent	- Grrice
look Need	BATTERY AM S LATEN) BOOTHS. O			



-	1			ACME ST	EEL CHIC	AGO PLANT	- 9		4 1	
			1998	WINTERIZ	ZATION LI	ST COKE O	/ENS			
	1			1.					1 - 2 2	
THE PARTY	CH I	INSPECT/	INSULATE	MAKE UE	WATER	INES AND	ALVES =	_		
						RS AND PIPI			-:	
L. Wall		HKC STEA				TO AND I II I	140	-		1 1 1 1 1
1		DRAIN MA						1,1		
月	- Carrier 14					BASEMENT				
WE		INSPECT				BASEMENT				
						ON DOOR	MACHINES	9 DIIGUE	De	
						IN DR.REP				2.74
		REINSULA					AIR & PAI	CHER ARE	A	
		REINSULA								100
14								(ED DOT!	DATTERIE	
1						LATORS AT			BATTERIE	5
0 = 2						INES BOTH		AKS		
Marian.					AS NEEDE	D BOTH BA	TIERIES			10.750
11/1		FLUSH AL								
1.11/11						DE OF H 20			10000	
						RAIL AT QUE				
						WITCH AT N		)		
						SOUP TAN	KS			
W - 1		INSPECT								
-			The second secon			IMP HOUSE				2
	-	INSPECT /	REPAIR A	ALL STEAM	I TRAPS C	N TOP OF E	SOTH BAT	TERIES		
-	22	115pz	CT AND	1 RZPA	R 6=11	+ plows	on 14	and C	2 8	
	23	EXPO	SE H		LT CO	LACTER U	W21467			
THE S	24	1N 3F	PECT H	(ZACER:	5 114 8	WUIRON	MENT	Al Boot	65 BAI	TERY To
一大线	25	INSpz.	ET 1/21	OTIRS	ON LOI	any can	5			
-	26	MAKZ	UP	91R E	iting.	For For	WATER	6/ASTE	a Gens	3
0	27	Coal	Bin	C1800	of	Sticked		The state of the		
3	28	Steam			Side		a Bicas			
	29			7.0						
	30		Service of the servic	The state of			100			
	31	* .			THE PERSON		4 7 73			
	32									
-	33	5					TATE		1 5 92	
	-									
	34	Section 1				7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7			No. of the last of	
	34 35									

No.		
	2001 OVENS WINTERIZATION LIST	
	MECHANICAL MAINTENESS	
1	MECHANICAL MAINTENENCE-	
- 10	1) REINSTALL STEAM TRACED NOT THE STEAM TRACED NOT	COMPLET
7	THE WOTALL STEAM TRACER HUT RAIL SOUTH OF STATION	
	2) TRACE AND INSULBEARING WATER-HKC FAN	
	3) INSPECT STEAM LINES TO HKC TRACERS-REPAIR WHERE REQUIRED LOY 1 4) DRAIN, FLUSH, REFILL HYDRALICS-PUSHERS/DOOR MACHINES NOTE:	
	137 INSTITUTE SKILLS FAM AND DECILIATORS	
	10) INSPECT AND REINSTILATE MAKE HID WATER LINES	
	(7) REINSTALL STEAM TRACERS O RAIL AT AND SOUTH OF STATION	
1	O) REPAIR DUURS C/S ALLEY #1 BATT	
10	9) INSULATE EMERGENCY WATER FEED TO 0. STATION	
P	10) REPAIR STEAM LEAKS PER MAINT, SHEET	-
	11) DRAIN, FLUSH, REFILL AKL MACHINERY GEARBOXES	-
	12) MAINFOLD - BE STATION E-SPRAYS	
	to do the	
1	ELECTRICAL UNICERNATATE TO SE	
	ELECTRICAL/INSTRUMENTATION-	
1	1) INSPECT AND REPAIR ALL MACHINE OPERATOR PULPIT HEATERS	100
1	2) INSPECT AND REPAIR HEAT TRACING LARRY CARSAIR SUPPLY	Um III
1	3) INSPECT AND REPAIR HEATERS -TOPSIDE ENVIRONMENTAL BOOTHS	
1	4) INSPECT AND REPLACE HOT RAIL INSULATORS-QUENCH CAR	
1	PUSHER	
I	DOOR MACHINE	
h	DPERATIONS-	
ľ	or Ella Holdo	Marie Till
h	DRAIN MAKE-UP WATER LINES- ARROYO-	COMPLET
ľ	CLOSE WINDOWS IN ALLEY AND BASEMENT-ARROYO-	
li	INSTALL CANVAS CURTAIN BY WATERBLASTERMEDVED	
F	ILIBE O TRACK SWITCH N END	
b	CLEAN HAC COUNTEDING ON THE COUNTY OF THE CO	
Þ	CONTACT VENDOR LUTING MATERIAL WILLIAM	orbite III-
Г	Oct	
F	BY OTHERS	
lii		
쀠	LEAN OUT STICKERS ALL CHARGING BINS	COMPLET
1	CENIA OOL STICKEUS AFF CHARGING BINS	