Acme Coke 11236 S. Torrence Ave. Chicago IL 60617



acmecoke.com

Document archive

Daily Maintenance Reports
Dated: 1989

ACME STEEL COMPANY CHICAGO CDKE PLANT DAILY MAINTENANCE REPORT 04-11-89

COKT OVENS:

- 1. REPAIRED STEAM LEAK MAIN CHARGING STEAM #2 BATTERY.
- 2. CHANGED A-12 AND A-15 RISER CAPS.
- 3. REMOVED C-4, C-5, AND C-6 COKE SIDE LINIEL COVERS.
- 4. EMPTIED SCRAP BOXES ON TOP OF BATTERY.
- 5. FABRICATED 20: BLOWNIPE.
- 6. REPAIRED HYDRAULIC LEAK ON #1 QUENCH CAR.
- 7. LID BARS AT WHITE CASTLE.
- 8. ASSISTED OPERATOR ON C-9 COKE SIDE DOOR (DOOR NEEDS CLEANING).
- 9. REPAIRING D-17 TIE ROD.
- 10. INSTALLING #3 BIN SOUTH CENTER SLIDE GATE FOR CLEAN OUT.

BY-PRODUCTS:

- 11. REPLACED BROKEN ELBOW ON DISCHARGE LINE FROM LIME PIT PUMP.
- 12. REPLACED LEAKING UNION AND NIPPLES IN INLET STEAM LINE TO MAIN FLOOR HEATER IN OLD SULPHATE BASEMENT.
- 13. INSULATED STEAM FEED TO NAPTHELENE BAY SYPHON.
- 14. ADJUSTED PACKING ON WATER VALVE, DISCHARGE SIDE, SOUTH PLATE AND FRAME.
- 15. CHASED AND LUBRICATED THREADS ON RODS FOR PLATE AND FRAME.
- 16. INSULATING NEW DISCHARGE LINE FROM #14 TANK SUMP PUMP.

COAL & COKE HANDLING:

- 17. PAINTED END PLATES ON PLATE AND FRAME.
- 18. PATCHED HOLE ON WES! SIDE OF CAGE PAKTOR CHUTE.
- 19. INSTALLED SIDE PLATES AND WARE PLATES ON NORTH SIDE OF #3 PRIME.
- 20. JIGHTENED BEARING COVERS FOR COUNTERWEIGHTS ON DUMPER.
- 21. WELDED CABLE ON CABLE DRUM #2 FROM SOUTH END OF DUMPER.
- 22. WELDED SIDE PLATES TOGETHER ON #2 FEEDER AT DUMPER.
- 23. RE-LAGGED E-1 DRIVE PULLEY.
- 24. PAINTING IN STOREROOM LOCKER ROOM.
- 25. PAINTING ENVIRONMENTAL SHANTY IN EXHAUSTER ROOM.

MACHINE SHOP:

- 26. MACHINED SOCKETS FOR PLATE AND FRAMES.
- 27. REPLACING FRONT ENGINE IN #5 EUCLID.
- 28. MACHINING NEW SHAFT FOR DOOR MACHINE DRIVE.
- 29. KEPAIRING BOWL DOOR ON #3 EUCLID.
- 30. FABRICATING CLEAN OUT DOORS FOR BIN GATES.
- 31. MACHINING END PIECES FOR CLEAN OUT DOORS FOR BIN GATES.

- 32. REPLACED PUSHER SIDE INSULATOR.
- 33. REPAIRED LIGHTS IN WEAK LIQUOR ROOM.
- 34. REMOVED BOTTOM RAILS ON CROSSOVER THAT WERE HITTING HOOD CAR ANTENNA.
- 35. ADJUSTED SHOP CRANE BRAKE.
- TO, REPLACED GATE LIGHT WIRES ON #1 QUENCH CAR.
 - CHANGED THERMOSTAT IN BY PRODUCTS BACK OFFICE.
- 38. FINISHED CHANGING STARTER ON #1 PUSHER DE CARB AIR.
- 39. WORKING ON LINTERN UNITS FOR OVEN MACHINES.
- 40. WORKING ON NEW FEEDER FOR SLURRY PUMP.

ACME STEEL COMPANY CHICAGO COKE PLANT

DAILY MAINTENANCE REPORT 09-21-89

COKE OVENS:

- FABRICATED CHIPPING BARS AND AIR LANCES.
- REPAIRED BATTERY DRAIN LINE. WELDED PUSHER SIDE HAND RAIL.
- 4. REPLACED P.O. CHECK VALVE ON #2 QUENCH CAR.
- INSTALLED BRAKES ON HOOD CAR.
- UNLOADED TWO TWELVE PACKS OF OXYGEN TANKS.
- CLEANED SHOP.
- REPAIRED CRACK IN #1 LARRY CAR JUMPER PIPE. 8.
- REPLACED D-15 BLOWPIPE.

BY-PRODUCTS:

- TIGHTENED PACKING ON VALVE ON EAST SIDE OF LARGE SPIRAL COOLER. 1.
- REMOVED SCAFFOLDING FROM BLEEDER STACK.
- WELDED STEAM LEAK ON 380 LB. STEAM LINE TO TRAP ON FLUSHING LIQUOR TURBINE
- CHANGED VALVE ON SEAL POT NORTHWEST SIDE OF FLUSHING LIQUOR PUMP ROOM.
- REPAIRED TAR LEAK ON #13 TAR TANK.
- FABRICATED PIPING FOR #2 DRIP. 6.
- REPAIRED STEAM LEAK ON TRACER LINE IN NEW WEAK LIQUOR TANK. 7.

COAL HANDLING

- SANDBLASTED PRIMARY COOLER LANDING. 1.
- TARRED ROOF OF "W" BELT.
- TRAINED "D" BELT.
- INSTALLED TWO PLOWS ON "Y" BELT AND C-21 4.
- OPENED DRAIN LINE FROM 43 BELT TO UNDER WHILE CHANGED BAD FASTENERS ON #3 BELT
- CHANGED NORTHEAST TEARING ON "C"
- INSTALLED SCRAPER "S" BELT.
 FABRICATING FRONT OF HAMMER MILL GYREX
- FABRICATING PLOWS 10.

MECHANICAL SHOP

- 1. REPAIRED BUCKET PIN ON 992
- REPAIRED HYDRAULIC HOSE ON #1 EUCLID REMOVED NORTH BEA ON ELECTRIC EXHAUSTER MACHINING SHAFT LARRY CAR DRIVE.
- 4. MACHINING SHAFT LARRY CAR DRIVE.
 5. MACHINING AND DING PARTS FOR OVEN ELBOW DAMPERS.
- FABRICATING AND REPAIRING STAIRS AND PLATFORMS ON FINAL COLER.

- 1. REMOVED MOTORS FROM SHOP AND PUT IN STORAGE. REPAIRED LIGHT ON NUCLEAR GAUGE AT C-20 BELT.
- REPAIRED LIGHTS ON C-21 BELT.
- 4. CONDUCTED TRANSFORMER OIL TESTS.
- ADJUSTED LASER ON PUSHER.
- STEAMED COLLECTOR MAIN IMPULSE LINES.
- CALIBRATED PH AT LIME BAY AND AMMONIA STILL.
- INSPECTED AIR CONDITIONING UNITS ON OVENS AND THEY ARE ALL COAY.
- REPAIRING LIGHTS ON C-22 BELT.
- 10. WORKING ON NEW TOTAL GAS FLOW RECORDER.

ACME STEEL COMPANY CHICAGO COKE PLANT

DAILY MAINTENANCE REPORT 06/28/89

COKE OVENS:

- 1. REPAIRED #1 LARRY CAR VOLUMETRIC.
- 2. CHANGED #1 QUENCH CAR SOUTH TRUCK ASSEMBLY.
- 3. CHANGED PILOT HOSE TO #2 QUENCH CAR GATE CHECK VALVE.
- 4. CHANGED #2 DOOR MACHINE HYDRAULIC PUMP.
- 5. MADE UP SCRAPERS.
- 6. MADE 4 14" ALUMINUM AIR LANCES.
- 7. MADE 2 STEAM HOSES FOR OSCAR.
- 8. CONTINUED ON BIN SLIDE GATES.
- 9. · WORKED ON #2 BATTERY ASPIRATOR STEAM TRAPS.

BY-PRODUCTS:

- * FABRICATED NEW PIPING FOR #5 DRIP.
- 2. INSTALLED PIPING AND VALVES ON BETZ TANK.
- 3. REMOVED INSPECTION COVER ON EAST SUMP PUMP & INSTALLED COVER.
- 4. FABRICATING FLUSHING LIQUOR PIPING FOR HEADER CHANGE.
- 5. WORKING ON RIVER INTAKE.

COAL HANDLING:

- 1. GEAR BOX REPAIRED #1 FEEDER IN DUMPER.
- 2. CHANGED NOZZLE ON DIESEL TANK.
- 3. SEAL, SEAM & INSPECTED DOOR ON "Y" CHUTE.
- 4. CHANGED BUCKET CABLE ON DIESEL CRANE.
- 5. SPLICED E-1 AND TOOK PIECE OUT.
- & FABRICATING TABLE FOR BY-PRODUCTS.
- 7. PAINTING QUENCH CAR.

MECHANICAL SHOP:

- 1. REBOULT AIR MOTOR FOR AIRLIFT ON SOUTH END OF OVENS.
- 2. DRILLED HOLES FOR NEW PUMP BASE.
- 3. MACHINED PARTS FOR BIN GATE, AND CLEANED OUT DOORS.
- 4. REPLACED LOWER RADIATOR HOSE ON #2 EUCLID FRONT ENGINE.
- 5. MADE UP HYDRAULIC HOSE FOR OVEN MAINTENANCE.
- 6. MACHINED NEW PIN FOR COAL MAINTENANCE.
- 7. FABRICATING NEW PUMP BASE FOR #13-14 TAR TANKS SUMP PIT.
- 8. MACHINED PINS AND BUSHINGS FOR SPARE DOOR HEAD.
- 9. REMOTE TRANS FROM SHOP PICKUP.

- 1. CALIBRATED SEWER GAS, FI CIPITATOR LEVEL ALARM, AND WOBBIE.
- 2. INSTALLED AND REWIRED NEW AIR CONDITIONER IN LAB.
- 3. CLEANED PLUGGED AIR LINE IN EXHAUSTER ROOM.
- 4. REPAIRED FLOAT SWITCH ON INTERCEPTING PUMP.
- 5. PROBES B-19.
- 6. REFLACED LIGHT, CONDUIT & WIRING IN NAPTHELENE BAY.
- 7. INSTALLED NEW SWITCH & WIRE IN #1 LARRY CAR.
- 8. FABRICATED NEW DIODE PANEL FOR PRECIPITATOR.
- 9. FEPAIRED BOBCAT BACKUP ALARM.
- DISCONNECTED DRIF LEGS HEATING CABLES AS PER PIPE SHOP.
 - INTINUED TO TAG SWITCHES IN COKE PLANT.

ACME STEEL COMPANY CHICAGO COKE PLANT

DAILY MAINTENANCE REPORT 11-30-89

COKE OVENS:

- 1. REPLACED HOSE REEL AND HOSE ON #1 PUSHER DECARB AIR SYSTEM.
- 2. REPAIRED DECARB AIR PIPING ON #1 PUSHER MACHINE.
- 3. REPAIRED #1 PUSHER MACHINE BRAKES.
- 4. REPAIRED 12 INCH CHAIN VALVE PACKING IN TUENCH STATION.
- 5. ADJUSTED #2 DOOR MACHINE TOP BUTTON.
- 6. REPAIRED C-25 HIGH PRESSURE HATER VALVE.
- 7. REPAIRED STEAM LEAKS AT A-13, B-20, AND D-18 OVENS.
- 8. REPAIRED A-5 OKADEE VALVE.
- 9. REPAIRING ONE ELBOW 3 ARE READY TO POUR.
- 10. CONTINUED WORKING ON MAKE UP WATER INSULATION.

BY-PRODUCTS:

- 1. REPAIRED FUNNEL FOR SAMPLE LINE IN SULFATE.
- 2. INSULATING TAR LINE GROUND LEVEL AT SOUTH COLLECTOR TANK.
- 3. REPAIRED AIR LINE AT PRIMARY COOLER (INSTALLED 40' CF 3" PIPE)
- 4. PIPED NEW AIR PIPING AND REGULATOR ON FIRE LINE IN SULPHATE BAGGING ROOM.
- 1. INSTALLED HANDRAIL AND ACCESS FRAME TO CAGE FAKTOR.
- 2. CUT TUBE FOR OVENS.
- 3. PAINTED ACCESS DOOR FOR CAGE DUCT.
- 4. FABRICATED SCRAPER FOR DUMPER.
- 5. INSTALLING GAS PIPING ON SPUR TRACK.
- 6. FABRICATING ACCESS LADDER TO PLATFORM ON CAGE OVERSIZE CHUTE.
- 7. INSTALLING TRANSIT ON C-21 CONVEYOR.

MECHANICAL SHOP

- 1. REPAIRED TRANSMISSION DIL LEAK ON SHOP TRUCK.
- 2. CLEANED CHIP TRAYS.
- 3. INSTALLED GUARDS OVER STEAM RADIATORS IN LIGHT OIL.
- 4. MACHINING NEW SHAFT AND SEAL RINGS FOR PUSHER MACHINE AXLE.
- 5. MACHINING NEW SHAFTS FOR OVEN ELBONG.
- 4. BURNT OUT ALLEN SCREWS IN BEARING BOXES FOR PUSHER MACHINE AXLE.
- 7. FABRICATED STEAM BLOW PIPES FOR OVENS.

- 1. FINISHED INSTALLATION OF TWO NEW LIGHTS AT THE TAIL END OF C-21 CONVEYOR
- 2. INSTALLED COVER ON JUNCTION BOX BUY "Y' BELT MOTOR DRIVE.
- 3. MADE UP NEW FUSES FOR C-21 CONTROLS.
- 4. CALIBRATED SEWER GAS.
- 5. NEW HAMMER MILL BEARING TEMPERATURE METERS.
- 6. RESET LOW WELL LEVEL ALARM AT POWERHOUSE ..
- 7. CONTINUED WORKING ON ELECTRICAL HOOK UP AND WIRING FOR *1 DOOR MACHINE HYDRAULIC BRAKES.

COKE PLANT DAILY MAINTENANCE REPORT 12-15-88

- 1. CHECKED H.K.C. SPRAYS.
- 2. CHECKED SMOKE SLEEVE SEALS. (REPLACED SEAL ON #2 PUSHER)
- 3. REPAIRED AND ADJUSTED #2 DOOR MACHINE BRAKES.
- 4. CHANGED HYDRAULIC TANK NECK AND CAP ON #2 DOOR MACHINE.
- 5. REPLACED 3 BAD SPRAYS ON #2 PUSHER DE CARB AIR HEAD.
- 6. REPLACED BAD HOSE ON #2 PUSHER DE CARB AIR LINE.
- 7. REPLACED BAD SMOKE SLEEVE VERSA VALVE ON #1 LARRY CAR.
- 8. REPAIRED SIDE STEAM MAIN LEAK NORTH END ON #2 BATTERY.
- 9. WORKING ON SHEET STEEL ON H.K.C. HOOD CAR.
- 10. INSTALLED NEW CHEMICAL PUMP IN POWER HOUSE.
- 11. REPAIRED STEAM LEAK IN SULPHATE BAGGING ROOM.
- 12. REPAIRING STEAM LEAK IN WEAK LIQUOR PUMP ROOM.
- 13. FABRICATING NEW PIPING FOR SYPHON IN SULPHATE PUMP ROOM.
- 14. MADE PIPE FOR FIRE SYSTEM.
- 15. PRIMED NEW SHOP PICK UP TRUCK BED.
- 16. WORKING ON VIBRATING FEEDER.
- 17. MAKING BOX FOR ELECTRICAL DEPARTMENT.
- 18. PAINTING LUNCHROOM.
- 19. MAKING WINDOWS FOR LUNCHROOM.
- 20. REPAIRED RADIATOR ON CHERRY PICKER.
- 21. REPAIRED RADIATOR HOSE ON #1 EUCLID.
- 22. REPAIRED MOTOR BASE FOR VIBRATING FEEDER.
- 23. MACHINED GEAR SHAFT FOR LARRY CAR.
- 24. REPAIRING BRAKES ON ORANGE FORK LIFT.
- 25. MACHINING WHEEL SHAFT FOR LARRY CAR.
- 26. REPAIRING ENGINE ON CHERRY PICKER.
- 27. CALIBRATED SEWER GAS.
- 28. REPLACED FEED TO HAMMERMILL.
- 29. REPAIRED #2 DE CARB AIR COMPRESSOR STARTER.
- 30. WORKING ON #1 STACK CONTROLLER.
- 31. CALIBRATED CALORIMETER.
- 32. PULLING WIRE FOR PRECIPITATOR ALARM.
- 33. WORKING ON #1 LARRY CAR HEAT TAPE.
- 34. WORKING ON NEW FEEDER TO COAL HANDLING WITH CONTRACTORS.

COKE PLANT DAILY MAINTENANCE REPORT 12-66-88

- 1. CHECKED H.K.C. SPRAYS.
- 2. CHECKED SMOKE SLEEVE SEALS.
- 3. REPAIRED 150 LB. STEAM MAIN ON #2 BATTERY.
- 4. REPAIRED LEAKING UNION ON STEAM LINE AT NORTH END OF BATTERY.
- 5. ADJUSTED PACKING ON QUENCH VALVE.
- 6. FABRICATED NEW H.K.C. HOOD PLATE.
- 7. CHANGED 4 BLOWPIPES.
- 8. CHANGED 1 SWIVEL.
- 9. CHECKED #2 DOOR MACHINE.
- 10. REPAIRED DOOR EAST SIDE OF SULPHATE.
- 11. FABRICATED PLATE FOR BOTTOM OF VIBRATING FEEDER.
- 12. CUT PLATE FOR OVEN FOREMAN.
- 13. MOVED LARGE FRAME NEAR SPUR TRACK.
- 14. CHANGED BAD CLIPS ON #3 BELT.
- 15. CHECKED #3 PRIME, NO BROKEN CLIPS.
- 16. CHANGED SOUTH BEARING ON 3 PRIME TAIL PULLEY.
- 17. DROPPED BAD RETURN IDLER ON #4 BELT ON RIVER SPAN.
- 18. INSTALLED 14' PIECE ON "D" BELT.
- 19. CUT OUT CLIP ON SIDE OF "B" BELT.
- 20. TRAINED "T" BELT.
- 21. PAINTING LUNCH ROOM.
- 22. INSTALLED SYPHON LINE IN SULPHATE PUMP ROOM.
- 23. CHANGED EXPANSION JOINT ON TAR LINE.
- 24. REPAIRING STEAM LINE IN AMMONIA ABSORBER.
- 25. REPAIRED FUEL SYSTEM ON 950B.
- 26. REPAIRING ENGINE ON CHERRY PICKER.
- 27. REPAIRED FUEL SYSTEM ON #5 EUCLID.
- 28. REPAIRED RADIATOR HOSE ON REAR ENGINE OF #1 EUCLID.
- 29. REPAIRING BRAKES ON FORK LIFT.
- 30. MACHINING SHAFTS FOR LARRY CAR DRIVE.
- 31. REPLACING BED ON SHOP PICK UP TRUCK.
- 32. FABRICATING PARTS FOR DOOR MACHINE.
- 33. CHANGED STARTER ON TRACK CLEANER.
- 34. REPLACED SWITCH IN CHARLIE LYN'S LAB.
- 35. REPLACED #2 AIR COMPRESSOR MOTOR.
- 36. THAWED IMPULSE LINES TO STEAM FEED VALVE FOR AMMONIA STILL.
- 37. CALIBRATED OXYGEN ANALYZER FOR #1 BATTERY.
- 38. REPLACED SOLENOID VALVE ON #2 PUSHER DE CARB AIR LINE.
- 39. STEAMED COLLECTOR MAINS.
- 40. CHECKED HOT WORKS HEATERS.
- 41. CLEANED ROOMS AND INSULATORS AT PRECIPITATORS.

COKE PLANT DAILY MAINTENANCE REPORT 12-59-88

- 1. INSPECTED H.K.C. SPRAYS.
- 2. INSPECTED SMOKE SLEEVE SEALS.
- 3. REPAIRED AND ADJUSTED #2 LOCOMOTIVE BRAKES.
- 4. REPAIRED 150 LB. STEAM LEAK ABOVE #1 BATTERY PINION WALL.
- 5. REPAIRED OIL LEAK ON #1 DOOR MACHINE.
- 6. ADJUSTED PACKING ON QUENCH VALVE.
- 7. TRACED NORTH MILL WATER MAKE UP LINE ON #1 BATTERY.
- 8. INSTALLED WEAR PLATES ON COKE GUIDE.
- 9. REPAIRED BROKEN STEAM PIPE TO WEST SIDE OF SOUTH DECANTER.
- 10. REPAIRED AIR LINE ON #1 BOOSTER.
- 11. REPAIRED OIL LEAK ON #2 BOOSTER.
- 12. REPAIRING BROKEN STEAM PIPING TO AMMONIA ABSORBER.
- 13. REPAIRING BROKEN WATER LINE TO CAUSTIC PUMP ROOM.
- 14. REPAIRING BROKEN STEAM FEED TO CAUSTIC PUMP ROOM.
- 15. ADJUSTED SKIRT RUBBER, EAST SIDE OF PLOWS, ON C-21.
- 16. INSTALLED RETURN IDLER ON "W" BELT.
- 17. INSTALLED PIPING FOR FIRE LINE NEAR C-21 DRIVE.
- 18. HOOKED UP WATER AND AIR FOR REGIS TO VULCANIZE "A" BELT.
- 19. PAINTING IN LUNCH ROOM.
- 20. WORKING ON VIBRATING FEEDER.
- 21. INSTALLING NEW PLOW ON "Y" BELT.
- 22. WORKING IN OVEN SHANTY.
- 23. REPAIRED TRANSMISSION ON 950.
- 24. REPAIRING PRIMARY SUMP PUMP.
- 25. REPAIRING WEAK LIQUOR PUMP.
- 26. REPAIRING FORK LIFT BRAKES AND LIFT CYLINDER.
- 27. FABRICATING NEW BED FOR SHOP PICK UP.
- 28. FABRICATING PARTS FOR NAPTHELENE BAY.
- 29. INSTALLED NEW LIMIT ON #1 DOOR MACHINE COKE GUIDE.
- 30. HEAT TRACED #1 LARRY CAR AIR LINES.
- 31. REPLACED LIGHTS AT C-23.
- 32. DISCONNECTED AND RECONNECTED CAGE PAKTOR VIBRATING FEEDER MOTOR.
- 33. ASSEMBLING NEW RECTIFIER BOARD FOR PRECIPITATORS.
- 34. ASSEMBLING NEW DAMPER UNIT.

COKE PLANT DAILY MAINTENANCE REPORT 12-80-88

- 1. INSPECTED H.K.C. SPRAYS.
- 2. INSPECTED SMOKE SLEEVE SEALS.
- 3. INSTALLED GEAR GUARD ON #2 LARRY CAR.
- 4. REPLACED D-22 BLOWPIPE AND SWIVEL.
- 5. REPLACED 3 BAD TRAPS AND STRAINERS ON H.K.C. TRACING LINES.
- 6. REPAIRED HYDRAULIC ON #1 DOOR MACHINE.
- 7. REPAIRED HYDRAULIC LEAK ON #2 DOOR MACHINE.
- 8. REPLACED 21 1/2 ' OF DOOR MACHINE RAIL ON #2 BATTERY, WEST RAIL.
- 9. STRAIGHTENED BENT COLLECTOR ARM BRACKETS ON #1 QUENCH CAR.
- 10. REPAIRED STEAM VALVE AT LIGHT OIL COLD WELL.
- 11. REPAIRED WATER LINE TO CAUSTIC PUMP ROOM.
- 12. REPAIRED STEAM LINE TO CAUSTIC PUMP ROOM.
- 13. REMOVED, REPAIRED, AND INSTALLED SUCTION LINE FROM NAPTHELENE BAY HOT WELL.
- 14. REPAIRING STEAM LINE ON TOP OF AMMONIA ABSORBER.
- 15. CHANGED TROUGHER ON C-21 BELT.
- 16. TRAINED #1 BELT.
- 17. SET UP AND BOLTED TROUGHER UNDER WHARF.
- 18. DRAINED FUEL TANK ON PORTABLE AIR COMPRESSOR AT MIXERS.
- 19. CHANGED SPRINGS ON VIBRATING FEEDER.
- 20. MADE AND INSTALLED 2 WEDGES FOR HAMMERMILL INSPECTION DOOR.
- 21. PAINTING IN LUNCH ROOM.
- 22. PRIMING SHOP TRUCK BED.
- 23. ORDERED MATERIAL TO REPAIR FLOOR AROUND HAMMERMILL SHAKER.
- 24. REPLACED BAD LINKAGE ON #1 EUCLID HYDRAULIC CONTROL.
- 25. REPLACED OIL FILTER ON FRONT TRANSMISSION OF #2 EUCLID.
- 26. REPAIRED RIGHT FRONT WHEEL ON FORK LIFT.
- 27. REPLACED NORTH EAST PLATFORM AT NAPTHELENE BAY.
- 28. REPAIRING PUMPS.
- 29. REPAIRING BRAKE AIR CHAMBER ON #5 EUCLID.
- 30. REPAIRED DE CARB AIR SOLENOID ON #1 PUSHER.
- 31. REMOVED CONDUIT AT NAPTHELENE BAY FOR BOILERMAKERS.
- 32. REPAIRED ARM ON #2 DOOR MACHINE LIMIT.
- 33. CHANGED POWER SUPPLY AT #2 LARRY CAR.
- 34. REPAIRED STOCKING OUT CONTROLLER.
- 35. INSTALLED REPEATER ANTENNA ON AMMONIA STILL.
- 36. WORKING ON RECTIFIER FOR PRECIPITATOR.

COKE PLANT DAILY MAINTENANCE REPORT 12-21-88

- 1. INSPECTED H.K.C. SPRAYS.
- 2. INSPECTED SMOKE SLEEVE SEALS. (INSTALLED SEAL ON #1 PUSHER)
- 3. WELDED CRACK IN #1 PUSHER RAM WEB.
- 4. INSTALLED NORTH SKIRT ON H.K.C. HOOD CAR.
- 5. ADJUSTED BOTH #1 AND #2 DOOR MACHINES.
- 6. LUBRICATED H.K.C. HOOD CAR.
- 7. REPLACED BROKEN HOSE ON #2 PUSHER DE CARB AIR LINE.
- 8. ADJUSTED PACKING ON QUENCH VALVE.
- 9. WELDED CRACKS ON #1 PUSHER RAM HEAD.
- 10. WORKING ON TRACING #2 BATTERY MAKE UP WATER LINE.
- 11. WORKING ON INSTALLING DOOR ON WEST SIDE OF OVENS IN PATCHERS AREA.
- 12. INSTALLED WEST WEAK LIQUOR PUMP IN OLD PUMP ROOM.
- 13. INSTALLED PRIMARY SUMP PUMP.
- 14. INSULATED STEAM TRACE AND WATER LINE TO CAUSTIC PUMP ROOM.
- 15. REPAIRED AIR LINE AND SET FIRE SYSTEM IN SULPHATE BAGGING ROOM.
- 16. INSULATED STEAM LINE NEAR BLEEDER STACK.
- 17. REPAIRING STEAM LEAK AND LINES ON AMMONIA ABSORBER.
- 18. FABRICATED PIPING DRAIN LINE FOR TRAP FROM BY-PRODUCTS OFFICE TO TRENCH.
- 19. REPLACED 6 WINDOWS AT SUB STATION.
- 20. COVERED MANHOLE ON ROOF AT SUB STATION.
- 21. INSTALLED GUARDS AROUND PROPANE TANKS.
- 22. CHANGED 3 TROUGHERS ON AND #1 RETURN IDLER ON "D" BELT.
- 23. WELDED RETURN IDLER BRACKET ON #1 BELT.
- 24. TRAINED #1 BELT DRIVE AND PAD BELT.
- 25. INSTALLED NEW PIECE OF SKIRTING ON WEST SIDE OF "Y" BELT UNDER NEW MIXERS.
- 26. PLUGGED HOLE ON TRIPPER SIDES.
- 27. FINISHED PRIMING BY-PRODUCTS TRUCK.
- 28. STARTED PARNTING BY-PRODUCTS TRUCK.
- 29. PAINTING IN LUNCH ROOM.
- 30. REPAIRED AIR BRAKE CHAMBERS ON #5 EUCLID.
- 31. REPAIRED REAR ENGINE ON #5 EUCLID.
- 32. REPAIRED SHOP FORK LIFT.
- 33. MACHINED ORIFICE FOR DE CARB AIR VALVE.
- 34. FABRICATED SHIMS FOR DOOR MACHINE RAILS.
- 35. MACHINING VALVE GATE FOR QUENCH VALVE.
- 36. REPAIRING LIFT CYLINDER ON ORANGE FORK LIFT.
- 37. FABRICATING DOOR FOR SULPHATE BUILDING.
- 39. ADJUSTED STEAM EXHAUSTER CONTROL.
- 40. INSTALLED PROBES IN B-19 OVEN.
- 41. MADE NEW CONTACTOR PANEL FOR DE CARB AIR ON #2 PUSHER.
- 42. INSTALLED NEW VALVE ON #1 PUSHER DE CARB AIR.
- 43. INSTALLING WIDE LIGHT OUTSIDE BY-PRODUCTS OFFICE.
- 44. WORKING ON NEW RECTIFIERS FOR PRECIPITATORS.

COKE PLANT DAILY MAINTENANCE REPORT 12-22-88

- 1. INSPECTED H.K.C. SPRAYS.
- 2. INSPECTED SMOKE SLEEVE SEALS.
- 3. PACKED QUENCH VALVE.
- 4. ADJUSTED AND WELDED BROKEN BRACE ON #2 QUENCH CAR.
- 5. CHANGED BLOWPIPE AND SWIVELS ON OVENS A-3, A-18, A-20, D-17, AND D-19.
- 6. CHANGED SIDE STEAM OKADER VALVE ON D-25 OVEN.
- 7. REMOVED BRACES ON B-19 OVEN. (PUSHER SIDE)
- 8. REPAIRED WATER LEAK UNDER C-16 OVEN IN COKE SIDE ALLEYWAY.
- 9. ROLLING DOOR INSULATION ON WEST SIDE OF PATCHERS AREA.
- 10. REPAIRED DRIVE CHAIN ON SOUTH DECANTER.
- 11. INSULATING STEAM LINE AT PRECIPITATORS.
- 12. INSULATING DRAIN LINE FOR STEAM TRAPS IN BY-PRODUCTS OFFICE
- 13. INSULATING STEAM LINE AND PIPING IN AMMONIA ABSORBER.
- 14. FINISHED PAINTING BY-PRODUCTS TRUCK.
- 15. SANDBLASTED PACKING GLAND FOR QUENCH VALVE.
- 16. CLAMPED DOW GRATING STICKING UP AT E-5. CONVEYOR WALKWAY.
- 17. LOWERED SIDE PLATES ON WEST SIDE OF TUNNEL UNDER WHARF.
- 18. CHANGED BAD FASTENERS ON 3 PRIME.
- 19. REPLACED SKIRT RUBBER ON NORTH SIDE OF "B" BELT TAIL CHUTE.
- 20. TRAINED "D" BELT.
- 21. PLUGGED HOLE ON E-5 LEAD CHUTE AT SCRAPPER.
- 22. INSPECTED WEST SIDE OF "T" BELT TAIL CHUTE FOR LEAK. (OK)
- 23. PAINTING IN LUNCH ROOM.
- 24. DISCOVERED MORE BREAKS. WHILE WORKING ON FIRE SYSTEM.
- 25. MACHINED PARTS FOR QUENCH VALVE.
- 26. ADJUSTED STEERING VALVE ON #2 EUCLID.
- 27. FABRICATING NEW BASE FOR BEARING COOLING WATER PUMP AT H.K.C. PUMP ROOM.
- 28. INSTALLING LIFT CYLINDER ON FOR LIFT.
- 29. BLOWING OUT FUEL LINE ON REAR ENGINE OF #1 EUCLID.
- 30. WELDED NEW BRACKET FOR POWER ARMS ON #2 LARRY CAR.
- 31. REPLACED FLORESCENT LIGHT IN SHOP LUNCHROOM.
- 32. REPLACED BOOSTER INLET TRANSMITTER.
- 33. REPLACED "I" TO "P" CONVERTER ON STEAM FLOW CONTROL FOR AMMONIA STILL.
- 34. WORKING ON PORTABLE HEATERS USED THROUGHOUT PLANT.