

Acme Coke
11236 S. Torrence Ave.
Chicago IL 60617



acmecoke.com
Document archive

Morning Reports
Dated: Feb-April 1994

Recovered from site on January 2 2020

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 04/21 F/A 0 REC 0 PUSHES 99

TODAY'S DATE
04/22 1993

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2324	185	75	79.7	3	0	1	0	32	3	1	1	1	2
	2352	245	85	99.7	15	0	0	1						
3/11	2372	200	75	0	14	0	0	0	34	34	1	3	1	2
	2331	237	83	0	14	2	0	0						
11/7	2402	200	75	0	13	4	0	0	33	33	1	2	1	2
	2393	237	83	0	8	5	0	0						

ITEM	QTY	UNIT	TYPE	VAL	VAL	VAL	VAL
C21/TAR BUCKETS	0	0	6-NE				
INDIANA	0	0.0	3-NW	2:1	HV FORDING	26.5	21.2
SOMERSET	0	0.0	2-CE		STD FORDING/MV FORDING	29.5	23.7
OVERSIZE	0	0.0	4-CW		TRUE ENERGY	18.0	14.4
POW/LTON	0	0.0	7-SE		HERNSHAW	27.5	22.0
HERNSHAW	14	18.9	5-SW	1:1	INLAND	29.0	10.0
ELK RUN	0	0.0			REGINA/AIMCOR PC	25.0	8.6
MAPLE MEADOW	0	0.0			TOTAL	124.7	100.0
AMONATE	0	0.0					
MV FORDING	19	25.7	ON HAND	0			GRINDING HRS 8.0
SMOKY RIVER	0	0.0	REC'D	0			DUMPING HRS 0.0
REGINA PC	3	4.1	DUMPED	0			
AIMCOR PC	3	4.1	ON HAND 7AM	0			
LINE CREEK	0	0.0					

TEST MIX STARTS PUSHING @10:30am

ITEM	QTY	UNIT	TYPE	VAL	VAL	VAL	VAL
TRUE ENERGY	12	16.2	D	Q/Q/D/D	35	32	80
STD FORDING	0	0.0	A	Q/Q/D/D	35	32	80
HV FORDING	17	23.0	N	Q/Q/D/D	35	32	80
ACME BLEND	0	0.0					
INLAND	6	8.1	OVENS				
COAL 19	0	0.0	DUMPING ON PAD				
TOTAL	74	100.0					

#1 EUC	31	PB	1
#2 EUC	22	D4	0
#3 EUC	0	D15	32
#4 EUC	35	BC1	88
#5 EUC	100	TOM	66
950	94	FL	97
950B	312	AC	16
992	73		

#1 QC-IRON WORK, NOISY HYDRAULIC PUMP, MOTOR ok
#2 QC-HYDRAULIC PUMP
#2 PUSHER-SATURN BRAKES
c/o WOBBE's-thermal bank???

TRUCKS	QTY	UNIT	TYPE	VAL
HERNSHAW	105	TAR TR	3	
mv Fordin	0	LO TRK	2	
MAPLE MEA	0	SUL TR	0	
REGINA PC	0	N PR T	39	
STD FORDI	0	S PR T	39	
TRUE ENER	0	C L PR	86	
elk run	0	F L PR	56	
EAGLE NES	0	SUC B4	190	
INLAND	0	SUC AF	270	
HV FORDIN	0	HD PR	110	
GAS BTU	0	SEC T	20	
GAS-FCE	9861	WO T	27	
GAS-TOT	21076	FG T	30	
STILL FL	90	FG PR	48	

BY-PRODUCTS
COND. PUMP ROOM-2 3" VALVES LEAKING BADLY
W 150# STEAM STATION-SAFETY VALVE LEAKS THROUGH
#2 PPT-S ELEPHANT EAR PLUGGED
PRIMARY COOLER SUMP PUMP-WON'T PUMP
S SPIRAL-AUTO WATER REGULATOR VALVE BAD

COAL HANDLING
#2 ECU-HYDRAULIC LEAK UNDER CAB
992-BRAKES (parts on order)
C&C TRUCK-REPAIR GAS LEAK
#7 BIN-BROKEN HINGES ON INSPECTION DOOR
#4 BELT-PATCH HOLES IN SIDE PLATES N SIDE

ELECTRICAL-see list
LIGHTS

5984

COKE PLANT
MORNING REPORT

T993 DATE PUSHED F/A REC PUSHES
04/07 0 0 114

TODAY'S DATE
04/08 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES						
					20	25	30	35	P	D	L	Q			
7/3	2330	192	80	0	6	1	0	0	38	38	2	1	3	1	D14-330
	2371	255	90	0	5	3	2	0							D12-355
3/11	2320	167	60	0	13	0	0	0	38	38	2	1	1	1	D11-300
	2342	200	60	0	8	6	1	0							
11/7	2327	187	70	0	15	0	1	0	38	38	2	1	1	1	A25-340
	2349	225	72	0	16	2	1	0							D4-300

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.5	22.1	1/4	92.36
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	23.0	18.5	1/8	80.39
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.0	CFW	45.25
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.5	28.5	PPT	5.70
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	7.9	STOCK	11
HERNSHAW	8	8.6	5-SW	1:1	REGINA/ATMCOR PC	26.0	9.0	RECLAIM	0
ELK RUN	20	21.5			TOTAL	124.6	100.0	NET	11
MAPLE MEADOW	0	0.0							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	6	6.5	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	4	4.3	DUMPED	0					
ATMCOR PC	4	4.3	ON HAND 7AM	0					
LINE CREEK	1	1.1							
TRUE ENERGY	13	14.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	14	15.1	A	Q/Q/D/D	31 30 80 80				
HV FORDING	23	24.7	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	JAMB CLEANER NEEDS ALIGNMENT ON #1 DM						
TOTAL	93	100.0	#1 LC BOOTS NEED ADJUSTMENT OR CHANGE						
			#1 LC NEEDS SAND IN SATURN SLEEVE						
#1 EUC	58	PB	31	150# STEAM LEAK S. END OF #1 BATTERY					
#2 EUC	20	D4	0	#1 LC W. AIR BLASTER PALM BUTTON NEEDS REPLACING					
#3 EUC	0	D15	32	MT SCRAP BOX N. END OF #1 BATT					
#4 EUC	27	BC1	88						
#5 EUC	66	TOM	0	BY-PRODUCTS					
950	0	FL	32	TURBINE DRAIN LINE #1 BOOSTER RUSTED AWAY					
950B	22	AC	96	OIL LEAK AT UNION E. TURBINE BRG #2 BOOSTER					
992	145			LIGHTS S. END EXH. RM. BASEMENT					
TRUCKS				REMOVE END PLATES ON WSAC FOR TESTING					
HERNSHAW	77	TAR TR	1	REPAIR 150# STM TO #1 BATTERY ISO. VALVE GASKET BLOWN					
mv Fordin	0	LO TRK	2						
MAPLE MEA	0	SUL TR	1						
REGINA PC	0	N PR T	40	COAL HANDLING					
STD FORDI	0	S PR T	40	REPLACE AIR LINE W. SIDE AT WHISTLE					
TRUE ENER	0	C L PR	98	LOOSE GRATING AT WHISTLE E. SIDE OF W-BELT INCLINE					
elk run	0	F L PR	94	LEAKING WATER HOSE AT S. END OF WHARF					
Acme Blen	0	SUC B4	195	SKIRT RUBBER TAIL OF #3 BELT					
INLAND	0	SUC AF	285	LIGHTS OUT #1 BELT TRENCH SIDE & GLOBE BROKEN					
HV FORDIN	0	HD PR	120	BOTTOM LIGHT OUT 950B					
GAS BTU	544	SEC T	23	LIGHTS IN COAL HANDLING OFFICE NEEDED					
GAS-FCE	10867	WO T	24						
GAS-TOT	21663	FG T	28						
STILL FL	95	FG PR	48	REPLACE DEFLECTOR PLATES UNDER WHARF S. END					

COKE PLANT
MORNING REPORT

1993 DATE PUSHED F/A REC PUSHES
04/06 0 0 114

TODAY'S DATE
04/07 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES						
					20	25	30	35	P	D	L	Q	A25-350		
7/3	2348	187	80	0	8	0	0	1	38	38	2	1	1	2	D12-370
	2379	252	90	0	7	6	2	1							D4-310 D10-330
3/11	2325	195	80	0	14	1	0	0	38	38	3	1	1	2	
	2373	257	90	0	13	7	0	0							D13-350 C21-300
11/7	2351	195	80	0	15	2	1	0	38	38	3	1	1	1	D2-350
	2338	257	90	0	6	9	2	2							D4-360

ITEM	QTY	WT	TYPE	TIME	DESCRIPTION	WT	WT	UNIT	WT
C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.4	1/4	92.65
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.0	1/8	80.22
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.0	CFW	45.50
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.0	28.8	PPT	6.50
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	7.9	STOCK	88
HERNSHAW	7	7.1	5-SW	1:1	REGINA/AIMCOR PC	26.0	8.9	RECLAIM	56
ELK RUN	19	19.2			TOTAL	125.1	100.0	NET	32
MAPLE MEADOW	0	0.0							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	6	6.1	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	5	5.1	DUMPED	0					
AIMCOR PC	5	5.1	ON HAND 7AM	0					
LINE CREEK	1	1.0							
TRUE ENERGY	14	14.1	D	Q/Q/D/D	31 30 80 80				
STD FORDING	17	17.2	A	Q/Q/D/D	31 30 80 80				
HV FORDING	25	25.3	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS	RESHEET #2 DOOR MACH.					
COAL 19	0	0.0	#2 BATTERY	SPOT LIGHT - OUT					
TOTAL	99	100.0		BRAKE FLUID LEAK INSIDE #2 PUSHER					

#1 EUC	50 PB	31	150# STEAM LEAK NEAR OFFICE
#2 EUC	12 D4	0	#1 BATT. SOUTH STAIR TO COLL. MAIN 5TH STEP LOOSE
#3 EUC	0 D15	32	JAMB CLEANER NEEDS ALIGNMENT ON #1 DM
#4 EUC	27 BC1	86	HOLE IN HEADER AT N. END QUENCH STA.
#5 EUC	66 TOM	0	BY-PRODUCTS
950	0 FL	24	S. P&F WATER CONTROL VALVE NUT FROZEN
950B	121 AC	88	S TAR TANK-STEAM LEAKS ON COILS
992	137		LIGHTS S. END EXH. RM. BASEMENT
TRUCKS			REMOVE END PLATES ON WSAC FOR TESTING
HERNSHAW	34 TAR TR	3	REPACK WATER VALVE FOR S. BANK P&F AT STRAINER
mv Fordin	0 LO TRK	1	LEAK ON NALCO CHEMICAL LINE AT KINNEY STRAINER
MAPLE MEA	0 SUL TR	4	RETRIEVE FLOAT FOR N. CONDENSATE TANK
REGINA PC	26 N PR T	41	
STD FORDI	0 S PR T	41	COAL HANDLING
TRUE ENER	0 C L PR	94	REPLACE SKIRT RUBBER BOTH SIDES OF T-BELT
elk run	0 F L PR	92	LEFT REAR WHEEL OF 992 LEAKING OIL
Acme Blen	0 SUC B4	200	REPLACE AIR LINE W. SIDE AT WHISTLE
INLAND	0 SUC AF	295	LOOSE GRATING AT WHISTLE E. SIDE OF W-BELT INCLINE
HV FORDIN	0 HD PR	135	REPAIR I-BEAMS ON RECLAIM HOPPER & BELT
GAS BTU	561 SEC T	23	SERVICE 950B
GAS-FCE	12172 WO T	23	TOM CAT WON'T START
GAS-TOT	24692 FG T	26	CHECK BINDICATOR SWITCH HEAD END E-4 BELT
STILL FL	95 FG PR	49	REPLACE DEFLECTOR PLATES UNDER WHARF S. END

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 04/05 F/A 0 REC 0 PUSHES 114

TODAY'S DATE
04/06 1993

1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES						
					20	25	30	35	P	D	L	Q			
7/3	2364	195	80	0	11	0	1	0	38	38	2	2	3	2	A25-320
	2347	250	90	0	11	3	0	0							
3/11	2356	195	80	0	7	0	1	0	38	38	3	3	3	2	B10-350
	2375	263	91	0	13	2	0	0							D12-300
11/7	2355	192	80	0	17	1	0	0	38	38	2	1	1	2	
	2359	255	90	0	14	5	0	0							

ITEM	QTY	UNIT	TYPE	TIME	DESCRIPTION	STRT	END	UNIT	TIME
C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.3	1/4	93.56
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	17.9	1/8	80.34
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.4	CFW	45.25
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.0	28.7	PPT	6.80
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	7.9	STOCK	44
HERNSHAW	9	9.7	5-SW	1:1	REGINA/AIMCOR PC	25.5	8.7	RECLAIM	56
ELK RUN	22	23.7			TOTAL	125.4	100.0	NET	-12
MAPLE MEADOW	0	0.0							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	5.4	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	4	4.3	DUMPED	0					
AIMCOR PC	4	4.3	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	13	14.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	15	16.1	A	Q/Q/D/D	31 30 80 80				
HV FORDING	21	22.6	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	#2 BATTERY SPOT LIGHT - OUT						
TOTAL	93	100.0	REBOOT #1 LC WEST & ASSIST SLEEVES						

ITEM	QTY	UNIT	DESCRIPTION
#1 EUC	42	PB	150# STEAM LEAK NEAR OFFICE
#2 EUC	4	D4	RESHEET #2 DOOR MACH.
#3 EUC	0	D15	RE-RAIL #1 QUENCH CAR & REPAIR RAIL
#4 EUC	27	BC1	HOLE IN HEADER AT N. END QUENCH STA.
#5 EUC	66	TOM	BY-PRODUCTS
950	204	FL	RETRIEVE FLOAT FOR N. CONDENSATE TANK
950B	106	AC	CHANGE SLURRY PUMP DISCH. VALVE - LEAKS THRU
992	129		WELD LEAK ON SLURRY PUMP DISCHARGE LINE TEE
TRUCKS			SPRAY PLUGGED ON SUCTION MAIN
HERNSHAW	0	TAR TR	AUTO CONTROL VALVE FOR MILL WATER ERRATIC CONTROL
mv Fordin	0	LO TRK	S. P&F WATER CONTROL VALVE NUT FROZEN
MAPLE MEA	0	SUL TR	S TAR TANK-STEAM LEAKS ON COILS
REGINA PC	0	N PR T	LIGHTS S. END EXH. RM. BASEMENT
STD FORDI	0	S PR T	COAL HANDLING
TRUE ENER	0	C L PR	SERVICE 950 AND TOMCAT
elk run	141	F L PR	REPLACE SKIRT RUBBER BOTH SIDES OF T-BELT
Acme Blen	0	SUC B4	REPLACE FUEL LINES ON 950B
INLAND	0	SUC AF	LEFT REAR WHEEL OF 992 LEAKING OIL
HV FORDIN	0	HD PR	REPLACE AIR LINE W. SIDE AT WHISTLE
GAS BTU	548	SEC T	INSTALL SUMP PUMP IN DUMPER BASEMENT
GAS-FCE	11268	WO T	REPLACE DEFLECTOR PLATES UNDER WHARF S. END
GAS-TOT	23008	FG T	FURNACE PLANT
STILL FL	90	FG PR	HINGES BROKE ON DOOR-#4BELT RIVER SPAN NORTH

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 04/04 F/A 0 REC 0 PUSHES 114

TODAY'S DATE 04/05 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC				MACHINES	
					20	25	30	35	P	D	L	Q		
7/3	2387	202	83	0	7	0	1	0	38	38	2	3	2	A25-340
	2387	257	95	0	13	1	0	0						
3/11	2338	195	80	0	9	0	0	0	38	38	2	2	1	D11-340
	2353	250	87	0	15	2	1	0						
11/7	2344	195	80	0	11	0	0	0	38	38	2	1	1	
	2316	250	87	0	18	0	0	0						

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.5	1/4	92.36
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.0	17.7	1/8	80.16
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.4	CFW	45.50
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.0	28.9	PPT	6.80
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	7.9	STOCK	99
HERNSHAW	7	8.4	5-SW	1:1	REGINA/AIMCOR PC	25.0	8.6	RECLAIM	122
ELK RUN	17	20.5			TOTAL	124.6	100.0	NET	-23
MAPLE MEADOW	3	3.6							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	6.0	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	4	4.8	DUMPED	0					
AIMCOR PC	4	4.8	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	8	9.6	D	Q/Q/D/D	31 30 80 80				
STD FORDING	14	16.9	A	Q/Q/D/D	31 30 80 80				
HV FORDING	21	25.3	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0							
COAL 19	0	0.0							
TOTAL	83	100.0							

#1 EUC	38	PB	30		150# STEAM LEAK NEAR OFFICE
#2 EUC	100	D4	0		#1 BATTERY CHANGE PAINTED ORIFICES
#3 EUC	0	D15	32		1 PUSHER SIDE DOOR UP, 5 DOWN
#4 EUC	20	BC1	86		#1 LC W. AIR BLASTER NEEDS TO BE REPLACED
#5 EUC	66	TOM	100		BY-PRODUCTS
950	196	FL	15		REMOVE END PLATES ON WSAC
950B	198	AC	80		FALSE SIGNAL HIGH LEVEL PRIMARY LEVEL CONTROL
992	121				AMMONIA STILL pH PROBE NOT WORKING
TRUCKS					PREP BOLTS ON #3 BOOSTER
HERNSHAW	0	TAR TR	3		S TAR TANK-STEAM LEAKS ON COILS
mv Fordin	44	LO TRK	0		LIGHTS S. END EXH. RM. BASEMENT
MAPLE MEA	0	SUL TR	1		REROUTE STEAM LINE FOR EXPLOSION PIT OVER JANITOR SUPPLY RM.
REGINA PC	34	N PR T	0		COAL HANDLING
STD FORDI	30	S PR T	0		HOLE IN BOTTOM OF CHUTE AT #1 TO #3 BELT
TRUE ENER	0	C L PR	0		REPLACE SKIRT RUBBER BOTH SIDES OF T-BELT
elk run	6	F L PR	0		REPLACE DEFLECTOR PLATES UNDER WHARF S. END
Acme Blen	0	SUC B4	0		LEFT REAR WHEEL OF 992 LEAKING OIL
INLAND	0	SUC AF	0		FENCE ON SOUTH END OF DUMPER- POST BROKEN
HV FORDIN	0	HD PR	0		REMOVE INSULATION FROM CAB #1 EUCLID
GAS BTU	533	SEC T	0		
GAS-FCE	11947	WO T	0		FURNACE PLANT
GAS-TOT	23169	FG T	0		HINGES BROKE ON DOOR-#4BELT RIVER SPAN NORTH
STILL FL	0	FG PR	0		

MTL orders

COKE PLANT
MORNING REPORT

1993 DATE PUSHED
04/03 F/A REC PUSHES
0 0 114

TODAY'S DATE
04/04 1993 **1994**

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD	PUSHES				PSH/HKC	MACHINES
						20	25	30	35		
7/3	2342	195	83	0	8	0	0	1	38	38	2 3 3 2 B10-STUCK
	2352	252	95	0	13	3	1	0			D20-300
3/11	2353	195	83	0	9	0	0	0	38	38	2 1 1 2 D11-330
	2393	252	95	0	15	2	1	0			
11/7	2362	195	83	0	13	0	0	0	38	38	2 1 1 1 D12-300
	2349	252	95	0	11	6	1	0			

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.5	1/4	90.85
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.1	1/8	80.35
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.5	CFW	45.00
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.5	28.5	PPT	7.50
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	22.5	7.8	STOCK	33
HERNSHAW	7	8.2	5-SW	1:1	REGINA/AIMCOR PC	25.0	8.6	RECLAIM	52
ELK RUN	18	21.2			TOTAL	124.4	100.0	NET	-19
MAPLE MEADOW	11	12.9							

AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	5.9	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	5	5.9	DUMPED	0					
AIMCOR PC	5	5.9	ON HAND 7AM	0					

LINE CREEK	0	0.0	=====						
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	14	16.5	A	Q/Q/D/D	31 30 80 80				
HV FORDING	20	23.5	N	Q/Q/D/D	31 30 80 80				

ACME BLEND	0	0.0	=====*						
COAL 18	0	0.0	OVENS	#1 lc w. air blaster -replace					
COAL 19	0	0.0	N. STACK PILOT OUT & DAMPER LEAKS						
TOTAL	85	100.0	HOLE IN HEADER AT N. END QUENCH STA.						

#1 EUC	38	PB	30	#2 DM NEED SIDE & BOTTOM PLATES ON CG E. SIDE
#2 EUC	92	D4	0	#2 PUSHER LATCH LIFTER NEEDS ADJUSTMENT
#3 EUC	0	D15	32	#2 BATT. 380# CHARGING STM LK AT FLANGE
#4 EUC	16	BC1	86	#2 LC W. PALM BUTTON- REPLACE

#5 EUC	62	TOM	96	BY-PRODUCTS
950	196	FL	7	INSTALL END PLATES ON WSAC
950B	182	AC	72	GAS BLEEDER PUMP DOWN
992	113			STM EXH-LK ON DRAIN LINE FOR U TUBE

TRUCKS				PREP BOLTS ON #3 BOOSTER
HERNSHAW	0	TAR TR	0	S TAR TANK-STEAM LEAKS ON COILS
mv Fordin	0	LO TRK	0	LIGHTS S. END EXH. RM. BASEMENT
MAPLE MEA	0	SUL TR	1	

REGINA PC	0	N PR T	0	COAL HANDLING
STD FORDI	0	S PR T	0	BOBCAT #1 CAGE NEEDS BOLTED DOWN & DOOR
TRUE ENER	0	C L PR	0	T.T. #848 ON 4 BELT S. ROLLER WORN
elk run	0	F L PR	0	HINGES BROKE ON DOOR-#4BELT RIVER SPAN NORTH
Acme Blen	0	SUC B4	0	REPLACE DEFLECTOR PLATES UNDER WHARF S. END
INLAND	0	SUC AF	0	REPAIR WATER TUBING UNDER STAIRS AT WHARF
HV FORDIN	0	HD PR	0	REPLACE SKIRT RUBBER BOTH SIDES OF T-BELT
GAS BTU	533	SEC T	0	LEFT REAR WHEEL OF 992 LEAKING OIL
GAS-FCE	11276	WO T	0	STEAM ELBOW LEAKING AT W-PIT SYPHON
GAS-TOT	22685	FG T	0	FENCE ON SOUTH END OF DUMPER- POST BROKEN
STILL FL	0	FG PR	0	LOOSE BOARD ON #11 FIRE BOX - AT WHARF

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 04/02
F/A 0
REC 0
PUSHES 114

TODAY'S DATE
04/03 1993

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2365	187	75	0	14	0	0	0	38	38	3	3	1	2
	2361	247	90	0	14	3	0	0						
3/11	2328	182	75	0	10	0	1	0	38	38	1	1	1	2 A25-360
	2376	252	90	0	13	0	1	0						D4-300
11/7	2302	185	75	0	6	0	0	0	38	38	2	3	1	2 D11-330
	2322	252	90	0	9	4	1	0						

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.5	22.1	1/4	91.25
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.1	1/8	80.30
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.4	CFW	45.75
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.0	28.9	PPT	5.10
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	7.9	STOCK	99
HERNSHAW	8	9.3	5-SW	1:1	REGINA/AIMCOR PC	25.0	8.6	RECLAIM	284
ELK RUN	20	23.3			TOTAL	124.6	100.0	NET	-185
MAPLE MEADOW	9	10.5							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	5.8	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	5	5.8	DUMPED	0					
AIMCOR PC	5	5.8	ON HAND 7AM	0					

LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	14	16.3	A	Q/Q/D/D	31 30 80 80				
HV FORDING	20	23.3	N	Q/Q/D/D	31 30 80 80				

ACME BLEND 0 0.0
 COAL 18 0 0.0 OVENS #1 lc w. air blaster -replace
 COAL 19 0 0.0 N. STACK PILOT OUT & DAMPER LEAKS
 TOTAL 86 100.0 HOLE IN HEADER AT N. END QUENCH STA.

#1DM CG NEEDS STRAIGHTING & AC REPAIRED
 #1 EUC 38 PB 29 #2 DM NEED SIDE & BOTTOM PLATES ON CG E. SIDE
 #2 EUC 84 D4 0 #2 PUSHER LATCH LIFTER NEEDS ADJUSTMENT
 #3 EUC 0 D15 32 #2 BATT. 380# CHARGING STM LK AT FLANGE
 #4 EUC 16 BC1 86 #2 LC W. PALM BUTTON- REPLACE
 #5 EUC 54 TOM 96 BY-PRODUCTS
 950 196 FL 7 INSTALL END PLATES ON WSAC
 950B 167 AC 64 GAS BLEEDER PUMP DOWN
 992 113 STM EXH-LK ON DRAIN LINE FOR U TUBE
 TRUCKS PREP BOLTS ON #3 BOOSTER
 HERNSHAW 0 TAR TR 0 S TAR TANK-STEAM LEAKS ON COILS
 mv Fordin 0 LO TRK 1 LIGHTS S. END EXH. RM. BASEMENT
 MAPLE MEA 0 SUL TR 2
 REGINA PC 0 N PR T 0 COAL HANDLING
 STD FORDI 0 S PR T 0 BOBCAT #1 CAGE NEEDS BOLTED DOWN & DOOR
 TRUE ENER 0 C L PR 0 T.T. #848 ON 4 BELT S. ROLLER WORN
 elk run 0 F L PR 0 HINGES BROKE ON DOOR-#4BELT RIVER SPAN NORTH
 Acme Blen 0 SUC B4 0 REPLACE DEFLECTOR PLATES UNDER WHARF S. END
 INLAND 0 SUC AF 0 REPAIR WATER TUBING UNDER STAIRS AT WHARF
 HV FORDIN 0 HD PR 0 REPLACE SKIRT RUBBER BOTH SIDES OF T-BELT
 GAS BTU 546 SEC T 0 LEFT REAR WHEEL OF 992 LEAKING OIL
 GAS-FCE 12043 WO T 0 STEAM ELBOW LEAKING AT W-PIT SYPHON
 GAS-TOT 23541 FG T 0 FENCE ON SOUTH END OF DUMPER- POST BROKEN
 STILL FL 0 FG PR 0 LOOSE BOARD ON #11 FIRE BOX - AT WHARF

COKE PLANT
MORNING REPORT

1993 DATE PUSHED F/A REC PUSHES
04/01 0 0 114

TODAY'S DATE
04/02 1993

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD				PUSHES	PSH/HKC MACHINES				
					20	25	30	35		P	D	L	Q	
7/3	2387	225	80	0	9	0	0	0	38	38	2	1	3	3
	2351	250	95	0	14	3	0	0						
3/11	2376	225	80	0	8	1	0	0	38	38	2	1	1	2
	2385	250	95	0	12	0	0	0						
11/7	2367	215	73	0	13	0	0	0	38	38	2	2	1	1
	2329	250	90	0	14	4	2	0						D4-330 D11-330

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.5	1/4	92.32
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.0	17.7	1/8	80.12
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.5	CFW	45.25
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.5	28.5	PPT	6.50
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	8.0	STOCK	66
HERNSHAW	9	9.8	5-SW	1:1	REGINA/AIMCOR PC	25.5	8.8	RECLAIM	188
ELK RUN	22	23.9			TOTAL	124.4	100.0	NET	-122
MAPLE MEADOW	12	13.0							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	5.4	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	4	4.3	DUMPED	0					
AIMCOR PC	4	4.3	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	15	16.3	A	Q/Q/D/D	31 30 80 80				
HV FORDING	21	22.8	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0							
TOTAL	92	100.0							

#1 EUC	38	PB	29	
#2 EUC	76	D4	0	
#3 EUC	0	D15	32	
#4 EUC	16	BC1	86	
#5 EUC	46	TOM	96	BY-PRODUCTS
950	196	FL	7	
950B	151	AC	56	
992	105			

TRUCKS				
HERNSHAW	0	TAR TR	0	
mv Fordin	119	LO TRK	0	
MAPLE MEA	0	SUL TR	0	
REGINA PC	0	N PR T	0	COAL HANDLING
STD FORDI	0	S PR T	0	
TRUE ENER	0	C L PR	0	
elk run	0	F L PR	0	
Acme Blen	0	SUC B4	0	
INLAND	0	SUC AF	0	
HV FORDIN	0	HD PR	0	
GAS BTU	549	SEC T	0	
GAS-FCE	11567	WO T	0	
GAS-TOT	23233	FG T	0	
TALL FL	0	FG PR	0	

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/31 F/A 0 REC 0 PUSHES 114

TODAY'S DATE
04/01 1993

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES						
					20	25	30	35	P	D	L	Q			
7/3	2380	230	85	0	4	0	0	0	38	38	1	3	3	2	D4-320
	2318	240	96	0	10	1	1	0							
3/11	2355	220	85	0	5	0	0	0	38	38	3	3	1	2	
	2351	240	96	0	16	0	0	0							
11/7	2375	225	82	0	11	0	0	1	38	38	2	1	1	2	A25-400
	2320	245	95	0	12	3	1	0							D11-350

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.0	22.1	1/4	91.41
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.0	18.0	1/8	79.83
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.3	CFW	45.75
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.5	29.0	PPT	6.40
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	22.5	7.9	STOCK	220
HERNSHAW	8	9.4	5-SW	1:1	REGINA/AIMCOR PC	25.0	8.8	RECLAIM	72
ELK RUN	19	22.4			TOTAL	122.4	100.0	NET	148
MAPLE MEADOW	3	3.5							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	5.9	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	4	4.7	DUMPED	0					
AIMCOR PC	4	4.7	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	9	10.6	D	Q/Q/D/D	31	30	80	80	
STD FORDING	13	15.3	A	Q/Q/D/D	31	30	80	80	
HV FORDING	20	23.5	N	Q/Q/D/D	31	30	80	80	
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0							
TOTAL	85	100.0							

#1 EUC	36	PB	29	
#2 EUC	68	D4	0	
#3 EUC	0	D15	32	
#4 EUC	16	BC1	86	
#5 EUC	40	TOM	86	BY-PRODUCTS
950	192	FL	92	
950B	135	AC	48	
992	97			

TRUCKS			
HERNSHAW	0	TAR TR	2
mv Fordin	0	LO TRK	2
MAPLE MEA	0	SUL TR	3
REGINA PC	0	N PR T	0
STD FORDI	96	S PR T	0
TRUE ENER	0	C L PR	0
elk run	0	F L PR	0
Acme Blen	0	SUC B4	0
INLAND	0	SUC AF	0
HV FORDIN	0	HD PR	0
GAS BTU	551	SEC T	0
GAS-FCE	11893	WO T	0
GAS-TOT	24123	FG T	0
ALL FL	0	FG PR	0

COAL HANDLING

COKE PLANT
MORNING REPORT

1993 DATE PUSHED F/A REC PUSHES
03/28 0 1 114

TODAY'S DATE
03/29 1993-1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES						
					20	25	30	35	P	D	L	Q			
7/3	2328	215	85		0	10	0	0	0	38	38	2	1	3	2
	2310	250	94		0	11	0	1	0						
3/11	2337	220	75		0	7	0	0	0	38	38	3	3	1	2
	2319	210	98		0	15	1	0	1						
11/7	2317	212	75		0	9	0	0	0	38	38	3	3	1	2
	2352	262	100		0	9	5	0	0						

D9-320

ITEM	QTY	WT	DIR	TIME	TYPE	GRINDING HRS	DUMPING HRS	NET
C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.0	22.0	1/4
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.0	17.9	1/8
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.2	CFW
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.0	29.3	PPT
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	22.5	7.9	STOCK
HERNSHAW	8	9.3	5-SW		REGINA PC	25.0	8.7	RECLAIM
ELK RUN	19	22.1			TOTAL	122.9	100.0	
MAPLE MEADOW	0	0.0						
AMONATE	0	0.0	DUMPER					
MV FORDING	5	5.8	ON HAND	0				GRINDING HRS 8.0
SMOKY RIVER	0	0.0	REC'D	0				DUMPING HRS 0.0
REGINA PC	7	8.1	DUMPED	0				
AIMCOR PC	0	0.0	ON HAND 7AM	0				
LINE CREEK	0	0.0						

ITEM	QTY	WT	DIR	TIME	TYPE	GRINDING HRS	DUMPING HRS	NET
TRUE ENERGY	12	14.0	D	Q/Q/D/D	31 30 80 80			
STD FORDING	14	16.3	A	Q/Q/D/D	31 30 80 80			
HV FORDING	21	24.4	N	Q/Q/D/D	31 30 80 80			
ACME BLEND	0	0.0						
COAL 18	0	0.0						
COAL 19	0	0.0						
TOTAL	86	100.0						

OVENS
#1 QUENCH CAR STRUCTURAL REBUILD
D4 DAMPER ASS'Y LEAKS
#1 DM-HKC ANTENNA, D.E. JERKS BEFORE GOING IN
RISER CAP SPRINGS-see list

BY-PRODUCTS
#3 BOOSTER-PREP BOLTS FOR BLANKING
#1 & #3 VOC HEADERS-CHARTS NOT RECORDING
INSTALL END PLATES ON WSAC
CHANGE GASKETS ON #4 SPIRAL COOLER AT LIGHT OIL
CHECK #6 HEADER CONTROLLER-NEEDLE ON CHART BOUNCING

#1 EUC	16	PB	28
#2 EUC	56	D4	0
#3 EUC	0	D15	32
#4 EUC	16	BC1	86
#5 EUC	24	TOM	86
950	178	FL	84
950B	95	AC	24
992	71		
TRUCKS			
HERNSHAW	88	TAR TR	2
mv Fordin	0	LO TRK	2
MAPLE MEA	0	SUL TR	2
REGINA PC	0	N PR T	41
STD FORDI	0	S PR T	41
TRUE ENER	0	C L PR	95
elk run	0	F L PR	92
Acme Blen	0	SUC B4	190
INLAND	0	SUC AF	280
HV FORDIN	0	HD PR	130
GAS BTU	544	SEC T	24
GAS-FCE	10948	WO T	26
GAS-TOT	22886	FG T	25
STILL FL	105	FG PR	48

COAL HANDLING
W BELT-WORN RI, MID INCLINE
T BELT-BROKEN TROUGH
C&C TRUCK-WON'T START
FORKLIFT-REPAIR HEATER & DOOR
#2 EUC-DOOR LATCH
LEAKING WATER HOSE S END WHARF

LIGHTS-Y BELT(mixers & s of partition), C21

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/24 F/A 1 REC 0 PUSHES 114

TODAY'S DATE 03/25 1993 **1994**

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD	PUSHES				PSH/HKC	MACHINES					
						20	25	30	35		P	D	Q	B-12	350	
7/3	2352	215	78	0	8	0	1	0	38	38	2	1	1	2	D-4	305
	2352	240	90	0	12	2	1	0								
3/11	2320	215	78	0	10	1	0	0	38	38	2	1	1	1	C-8	350
	2300	240	90	0	11	9	0	0							D-12	260
11/7	2369	215	78	0	8	0	1	0	38	38	2	1	2	1		
	2343	240	90	0	7	4	1	0								

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.6	1/4	92.34				
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.2	1/8	80.04				
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.2	CFW	45.50				
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.0	28.3	PPT	6.50				
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	22.5	7.8	STOCK	220				
HERNSHAW	9	9.8	5-SW		REGINA PC	25.5	8.9	RECLAIM	160				
ELK RUN	21	22.8		TOTAL		123.6	100.0	NET	60				

MAPLE MEADOW	0	0.0											
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0				
MV FORDING	5	5.4	ON HAND	0				DUMPING HRS	0.0				
SMOKY RIVER	0	0.0	REC'D	0									
REGINA PC	8	8.7	DUMPED	0									
AIMCOR PC	0	0.0	ON HAND 7AM	0									

LINE CREEK	0	0.0											
TRUE ENERGY	12	13.0	D	Q/Q/D/D	31	30	80	80					
STD FORDING	15	16.3	A	Q/Q/D/D	31	30	80	80					
HV FORDING	22	23.9	N	Q/Q/D/D	31	30	80	80					

ACME BLEND 0 0.0

COAL 18	0	0.0	OVENS										
COAL 19	0	0.0	#1 QUENCH CAR STRUCTURAL REBUILD										
TOTAL	92	100.0	REPLACE QUENCH VALVE										

#1 EUC	0	PB	27	INSTALL SHIELD OVER HOT CAR RAILS
#2 EUC	24	D4	0	REPLACE HOT CAR INSULATOR BRACKETS
#3 EUC	0	D15	32	
#4 EUC	16	BC1	86	
#5 EUC	8	TOM	85	

950	136	FL	73	#3 BOOSTER-PREP BOLTS FOR BLANKING
950B	63	AC	8	BETZ TANK-REPIPE, HOOK UP HEAT TRACER
992	22			STEAM HEATER IN OVENS/BP LOCKER ROOM
TRUCKS				CHANGE GASKETS ON #4 SPIRAL COOLER AT LIGHT OIL
HERNSHAW	0	TAR TR	1	#2 BOOSTER TRIP HAS OIL LEAK ON BOTTOM
mv Fordin	0	LO TRK	1	INSTALL HANDRAIL AT LADDER TO LBA BY-PASS
MAPLE MEA	0	SUL TR	1	

REGINA PC	0	N PR T	39	COAL HANDLING
STD FORDI	0	S PR T	39	REPLACE SKIRT RUBBER ON C-20 NORTH SIDE
TRUE ENER	60	C L PR	92	CRACKED CLIP ON C-21 BELT
elk run	62	F L PR	89	NEED SCREEN GUARD OVER E-MAN SHANTY HEATER
Acme Blen	0	SUC B4	200	BDO PUMP HOUSE-OIL LEAK ABOVE PUMP
INLAND	0	SUC AF	270	1&2 EUCLIDS NEED SEATS
HV FORDIN	0	HD PR	125	BAD DOOR ON FORK LIFT
GAS BTU	557	SEC T	24	NEED STARTER SOLENOID FOR AIR COMPRESSOR
GAS-FCE	11276	WO T	20	
GAS-TOT	23078	FG T	23	
STILL FL	90	FG PR	48	

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/23 F/A 0 REC 0 PUSHES 114

TODAY'S DATE 03/24 1993 *1999*

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2350	215	76	0	7	2	0	0	38	38	2	1	1	2
	2363	250	95	0	13	2	0	0						
3/11	2356	215	76	0	10	0	0	0	38	38	2	1	1	1
	2309	250	95	0	11	5	1	0						
11/7	2379	215	77	0	6	0	0	0	38	38	2	1	1	2
	2352	240	89	0	11	4	3	0						

C21/TAR BUCKETS	0	3	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.4	1/4	92.52
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.0	1/8	80.22
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.4	CFW	45.25
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.5	28.4	PPT	6.10
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	7.9	STOCK	418
HERNSHAW	8	9.3	5-SW		REGINA PC	25.5	8.8	RECLAIM	92
ELK RUN	20	23.3			TOTAL	124.9	100.0	NET	326
MAPLE MEADOW	0	0.0							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	6	7.0	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	7	8.1	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	12	14.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	15	17.4	A	Q/Q/D/D	31 30 80 80				
HV FORDING	18	20.9	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	#1 QUENCH CAR STRUCTURAL REBUILD						
TOTAL	86	100.0	#1 LARRY CAR ASSIST SLEEVE INSTALL						
			C-2 & C-4 ORIFICES CHANGE ON OUTERS						
#1 EUC	102	PB	27	#2 BASEMENT-REMOVE BRACKETS					
#2 EUC	16	D4	0	SMOKE SLEEVE GASKETS 1&2 PUSHERS					
#3 EUC	0	D15	32						
#4 EUC	16	BC1	86	BY-PRODUCTS					
#5 EUC	0	TOM	77	NORTH PLATE AND FRAME FLOW METER CALIBRATE					
950	120.5	FL	65	HOLE IN SULFATE SLURRY PUMP DISCHARGE FOR KILL					
950B	55	AC	0	#3 BOOSTER-PREP BOLTS FOR BLANKING					
992	11			BETZ TANK-REPIPE, HOOK UP HEAT TRACER					
TRUCKS				STEAM HEATER IN OVENS/BP LOCKER ROOM					
HERNSHAW	0	TAR TR	3	WALL BLEEDER-PULL BLANKS, RETURN TO SERVICE					
mv Fordin	0	LO TRK	1	INSTALL HANDRAIL AT LADDER TO LBA BY-PASS					
MAPLE MEA	0	SUL TR	3	COAL HANDLING					
REGINA PC	0	N PR T	40	BROKEN CLIP C-21 SPLICE					
STD FORDI	0	S PR T	40	SERVICE #1 EUCLID, BAD STEERING NEEDS SEAT					
TRUE ENER	84	C L PR	96	REPLACE SKIRT RUBBER ON C-20 NORTH SIDE					
elk run	41	F L PR	86	BDO PUMP HOUSE-OIL LEAK ABOVE PUMP					
Acme Blen	0	SUC B4	190	REBOLT GUARD ON C-WEST MIXER MACH. NORTH SIDE					
INLAND	0	SUC AF	270	LOOSE GRATTING AT WHISTLE EAST SIDE W-BELT INCLINE					
HV FORDIN	0	HD PR	145	NEED STARTER SOLENOID FOR AIR COMPRESSOR					
GAS BTU	539	SEC T	25	BAD FUEL PUMP ON FORK LIFT					
GAS-FCE	11463	WO T	21	992-TRANSMISSION LEAKING, BACKUP HORN					
GAS-TOT	23315	FG T	27	950-LIGHTS, BACKUP HORN					
STILL FL	100	FG PR	48	LIGHTS WEST SIDE Y-BELT					

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/22
F/A 0
REC 1
PUSHES 114

TODAY'S DATE
03/23 1993 *1994*

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC	MACHINES				
					20	25	30	35		P	D	L	Q	
7/3	2329	213	79	0	5	0	0	0	35	15	1	1	2	1
	2314	240	95	0	13	0	0	1						D11-370
3/11	2341	210	77	0	5	0	0	0	41	41	2	1	1	1
	2298	230	90	0	12	3	0	0						
11/7	2325	215	76	0	4	0	0	0	38	38	2	1	2	1
	2343	250	95	0	11	3	0	1						D11-395

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.0	22.0	1/4	92.32
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.0	17.9	1/8	80.12
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.6	CFW	45.50
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.5	28.9	PPT	6.20
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	22.5	7.9	STOCK	385
HERNSHAW	8	8.7	5-SW		REGINA PC	25.0	8.7	RECLAIM	0
ELK RUN	20	21.7		TOTAL		122.9	100.0	NET	385
MAPLE MEADOW	0	0.0							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	6	6.5	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	9	9.8	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	13	14.1	D	Q/Q/D/D	31 30 80 80				
STD FORDING	14	15.2	A	Q/Q/D/D	31 30 80 80				
HV FORDING	22	23.9	N	Q/Q/D/D	31 30 80 80				

ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	ENGINEERS-REMOVE FLARE STACK SLIP BLANKS						
TOTAL	92	100.0	#2 DM-CHANGE AXLE ON JC						
			#2 QC-IRON WORK						
#1 EUC	94	PB	27	#2 BASEMENT-REMOVE BRACKETS					
#2 EUC	8	D4	0	SMOKE SLEEVE GASKETS					
#3 EUC	0	D15	32						
#4 EUC	16	BC1	86						
#5 EUC	0	TOM	69	BY-PRODUCTS					
950	112	FL	57	E INTERCEPT PUMP-NO LOW LEVEL ALARM					
950B	47	AC	166	pH REGULATOR AMMONIA BAY-NOT CONTROLLING					
992	0			#3 BOOSTER-PREP BOLTS FOR BLANKING					
TRUCKS				BETZ TANK-REPIPE, HOOK UP HEAT TRACER					
HERNSHAW	49	TAR TR	3	EXH ROOM TOILET TANK LEAKING					
mv Fordin	36	LO TRK	1	WALL BLEEDER-PULL BLANKS, RETURN TO SERVICE					
MAPLE MEA	0	SUL TR	0						
REGINA PC	0	N PR T	39	COAL HANDLING					
STD FORDI	0	S PR T	40	#4 BELT CHUTE-SIDE PLATE HOLES N SIDE RECLAIM CHUTE ARES					
TRUE ENER	58	C L PR	98	#4 BELT-REPAIR BACK UP RUBBER BOTTOM OF 3/4 CHUTE					
elk run	0	F L PR	84	Y BELT-SKIRT RUBBER in various places					
Acme Blen	0	SUC B4	190	BDO PUMP HOUSE-OIL LEAK ABOVE PUMP					
INLAND	0	SUC AF	270	AIR COMPRESSOR(@ mixers)-TRANS LEAK					
HV FORDIN	0	HD PR	140	992-TRANSMISSION LEAKING, BACKUP HORN					
GAS BTU	552	SEC T	25	950-LIGHTS, BACKUP HORN					
GAS-FCE	0	WO T	18						
GAS-TOT	22838	FG T	26	*** E MAN SHANTY-NEED GUARD OVER HEATER					
STILL FL	105	FG PR	48	LITES-#1 BELT (wharf)					

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/21 F/A 0 REC 0 PUSHES 114

TODAY'S DATE
03/22 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD	PUSHES				PSH/HKC MACHINES					
						20	25	30	35	P	D	L	Q		
7/3	2324	210	78		0	5	1	0	0	38	38	2	3	2	2
	2332	240	90		0	13	1	0	0						
3/11	2343	225	80		0	6	0	0	0	38	38	1	1	3	1
	2321	240	93		0	11	3	1	0						D12-330
11/7	2343	213	79		0	8	0	0	0	38	26	1	1	2	1
	2332	240	95		0	9	1	2	0						C1-310 C5-300

ITEM	QTY	UNIT	DESCRIPTION	AMOUNT	AMOUNT	AMOUNT	AMOUNT	AMOUNT	AMOUNT
C21/TAR BUCKETS	0	0	6-NE 1:1 HV FORDING/STD FORDING	28.0	22.6	1/4	92.35		
INDIANA	0	0.0	3-NW 2:1 HV FORDING/MV FORDING	22.0	17.8	1/8	80.35		
SOMERSET	0	0.0	2-CE MAPLEMEADOW	17.5	14.1	CFW	45.25		
OVERSIZE	0	0.0	4-CW 2:1 ELK RUN/HERNSHAW	35.5	28.7	PPT	7.10		
POW'LTON	0	0.0	7-SE 1:1 STANDARD/ELK RUN	22.5	7.8	STOCK	66		
HERNSHAW	8	9.2	5-SW REGINA PC	26.0	9.0	RECLAIM	188		
ELK RUN	20	23.0	TOTAL	123.9	100.0	NET	-122		

MAPLE MEADOW	6	6.9							
AMONATE	0	0.0	DUMPER			GRINDING HRS	8.0		
MV FORDING	6	6.9	ON HAND	0		DUMPING HRS	0.0		
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	9	10.3	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0				COAL MIX CHANGE			
TRUE ENERGY	4	4.6	D Q/Q/D/D	31	30	80	80		Maple Meadow out, True Energy in
STD FORDING	13	14.9	A Q/Q/D/D	31	30	80	80		First Push-11am 3/23/94
HV FORDING	21	24.1	N Q/Q/D/D	31	30	80	80		FED EPA IN @ 9AM TODAY-OVENS INSPECTION

ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	ENGINEERS-REMOVE FLARE STACK SLIP BLANKS						
TOTAL	87	100.0	HKC HOOD CAR SHEARED COUPLING @4:30am						

#1 EUC	86	PB	27	#2 QC-IRON WORK					
#2 EUC	0	D4	0	#2 BASEMENT-REMOVE BRACKETS					
#3 EUC	0	D15	32	SMOKE SLEEVE GASKETS					
#4 EUC	16	BC1	86						
#5 EUC	90	TOM	69	BY-PRODUCTS					
950	96	FL	49	REINSULATE #2 SPIRAL COOLER WASH OIL LINES					
950B	39	AC	158	REPOSITION BETZ WSAC TANK ON NEW PLATFORM					
992	169			#3 BOOSTER-PREP BOLTS FOR BLANKING					

TRUCKS				REMOVE SCRAP @LO BLDG UPPER FLOORS					
HERNSHAW	134	TAR TR	3	EXH ROOM TOILET TANK LEAKING					
mv Fordin	9	LO TRK	0	WALL BLEEDER-PULL BLANKS, RETURN TO SERVICE					
MAPLE MEA	0	SUL TR	5						
REGINA PC	0	N PR T	40	COAL HANDLING					
STD FORDI	0	S PR T	40	#4 BELT CHUTE-SIDE PLATE HOLES N SIDE RECLAIM CHUTE ARES					
TRUE ENER	0	C L PR	96	#4 BELT-REPAIR BACK UP RUBBER BOTTOM OF 3/4 CHUTE					
elk run	0	F L PR	86	C21 BELT-BROKEN CLIP					
Acme Blen	0	SUC B4	210	W BELT-REPLACE RI @ TAIL END					
INLAND	0	SUC AF	280	S BELT-ADJUST SCRAPER					
HV FORDIN	0	HD PR	125	992-BACKUP HORN					
GAS BTU	557	SEC T	24	950-LIGHTS, BACKUP HORN					
GAS-FCE	10870	WO T	19						
GAS-TOT	22657	FG T	27	LITES-#1 BELT (wharf)					
STILL FL	105	FG PR	49						

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/17 F/A 0 REC 0 PUSHES 114

TODAY'S DATE 03/18 1993 1999

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2350	207	80	0	8	0	0	0	38	38	2	3	3	2
	2322	240	90	0	13	2	1	0						D12-320
3/11	2343	215	80	0	8	0	0	0	38	38	2	2	3	2
	2343	245	92	0	12	5	1	0						C1-305
11/7	2365	210	80	0	11	0	0	0	38	38	2	2	3	1
	2349	253	95	0	9	5	0	0						

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.5	22.1	1/4	91.93
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.1	1/8	81.57
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.1	CFW	45.75
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.0	28.9	PPT	5.20
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	8.0	STOCK	726
HERNSHAW	8	10.1	5-SW		REGINA PC	25.5	8.8	RECLAIM	132
ELK RUN	16	20.3			TOTAL	124.4	100.0	NET	594
MAPLE MEADOW	11	13.9							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	6.3	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	10	12.7	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	10	12.7	A	Q/Q/D/D	31 30 80 80				
HV FORDING	19	24.1	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							

COAL 18 0 0.0 OVENS

COAL 19 0 0.0 #2 P-SETS DOORS TOO HIGH

TOTAL 79 100.0 #1 P-TOP LATCH LIFTER DOES NOT LIFT ALL THE WAY

QUENCH SUMP-MAKEUP VALVE STICKS CLOSED

#1 EUC 54 PB 24 #2 QC-WELD BRACKET FOR S GATES LIGHTS

#2 EUC 75 D4 0 c/o STEPS @ NORTH END GOING TO TOP OF BATTERY

#3 EUC 0 D15 32

#4 EUC 8 BC1 86

#5 EUC 90 TOM 63

950 48 FL 31

950B 5 AC 126

992 131

TRUCKS

HERNSHAW 0 TAR TR 1

mv Fordin 0 LO TRK 1

MAPLE MEA 0 SUL TR 1

REGINA PC 0 N PR T 39

STD FORDI 0 S PR T 40

TRUE ENER 0 C L PR 104

elk run 148 F L PR 86

Acme Blen 0 SUC B4 210

INLAND 0 SUC AF 290

HV FORDIN 0 HD PR 125

GAS BTU 556 SEC T 24

GAS-FCE 21592 WO T 23

GAS-TOT 22761 FG T 24

STILL FL 100 FG PR 49

BY-PRODUCTS

COND TANK PUMP ROOM-REPLACE NIPPLE & SAMPLE VALVE

FUEL GAS RECORDER IN EXH ROOM DOWN

#2 SPIRAL-REPLACE GASKETS

REMOVE SCRAP @LO BLDG UPPER FLOORS

EXH ROOM TOILET TANK LEAKING

BP LOCKER ROOM-N STEAM HEATER BAD

COAL HANDLING

#4 BELT CHUTE-SIDE PLATE HOLES N SIDE RECLAIM CHUTE ARES

#4 BELT-REPAIR BACK UP RUBBER BOTTOM OF 3/4 CHUTE

C21 BELT-CRACKED CLIP

HAMMER MILL-c/o MISSING HAMMERS

HM GYREX-REPAIR SUPPORT BAR (wip)

LITES-INSTALLING LIGHTS @ WHISTLE (wip)

B10

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/17 F/A 0 REC 0 PUSHES 114

TODAY'S DATE 03/18 1993-1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES						
					20	25	30	35	P	D	L	Q			
7/3	2350	207	80		0	8	0	0	0	38	38	2	3	3	2
	2322	240	90		0	13	2	1	0						D12-320
3/11	2343	215	80		0	8	0	0	0	38	38	2	2	3	2
	2343	245	92		0	12	5	1	0						C1-305
11/7	2365	210	80		0	11	0	0	0	38	38	2	2	3	1
	2349	253	95		0	9	5	0	0						

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.5	22.1	1/4	91.93
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.1	1/8	81.57
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.1	CFW	45.75
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.0	28.9	PPT	5.20
POW'LTON	0	0.0	7-SE	1:1	STANDARD/ELK RUN	23.0	8.0	STOCK	726
HERNSHAW	8	10.1	5-SW		REGINA PC	25.5	8.8	RECLAIM	132
ELK RUN	16	20.3			TOTAL	124.4	100.0	NET	594
MAPLE MEADOW	11	13.9							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	6.3	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	10	12.7	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	10	12.7	A	Q/Q/D/D	31 30 80 80				
HV FORDING	19	24.1	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							

COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	#2 P-SETS DOORS TOO HIGH						
TOTAL	79	100.0	#1 P-TOP LATCH LIFTER DOES NOT LIFT ALL THE WAY						
#1 EUC	54	PB	24	QUENCH SUMP-MAKEUP VALVE STICKS CLOSED					
#2 EUC	75	D4	0	#2 QC-WELD BRACKET FOR S GATES LIGHTS					
#3 EUC	0	D15	32	c/o STEPS @ NORTH END GOING TO TOP OF BATTERY					
#4 EUC	8	BC1	86						
#5 EUC	90	TOM	63	BY-PRODUCTS					
950	48	FL	31	COND TANK PUMP ROOM-REPLACE NIPPLE & SAMPLE VALVE					
950B	5	AC	126	FUEL GAS RECORDER IN EXH ROOM DOWN					
992	131			#2 SPIRAL-REPLACE GASKETS					
TRUCKS				REMOVE SCRAP @LO BLDG UPPER FLOORS					
HERNSHAW	0	TAR TR	1	EXH ROOM TOILET TANK LEAKING					
mv Fordin	0	LO TRK	1	BP LOCKER ROOM-N STEAM HEATER BAD					
MAPLE MEA	0	SUL TR	1						
REGINA PC	0	N PR T	39	COAL HANDLING					
STD FORDI	0	S PR T	40	#4 BELT CHUTE-SIDE PLATE HOLES N SIDE RECLAIM CHUTE AREAS					
TRUE ENER	0	C L PR	104	#4 BELT-REPAIR BACK UP RUBBER BOTTOM OF 3/4 CHUTE					
elk run	148	F L PR	86	C21 BELT-CRACKED CLIP					
Acme Blen	0	SUC B4	210	HAMMER MILL-c/o MISSING HAMMERS					
INLAND	0	SUC AF	290	HM GYREX-REPAIR SUPPORT BAR (wip)					
HV FORDIN	0	HD PR	125						
GAS BTU	556	SEC T	24						
GAS-FCE	21592	WO T	23						
GAS-TOT	22761	FG T	24	LITES-INSTALLING LIGHTS @ WHISTLE (wip)					
STILL FL	100	FG PR	49						

COKE PLANT
MORNING REPORT

1993 DATE PUSHED F/A REC PUSHES
03/16 1 0 114

TODAY'S DATE
03/17 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2354	207	83	0	10	1	0	0	38	38	2	3	3	1
	2310	240	90	0	11	3	2	0	D15-330 D4-310					
3/11	2362	205	83	0	9	0	0	0	38	38	2	1	2	1
	2354	240	90	0	13	4	0	0						
11/7	2340	207	80	0	7	1	0	0	38	38	2	1	2	1
	2359	240	90	0	13	0	0	1	D11-360					

ITEM	QTY	WT	TYPE	GRINDING	DUMPING	NET	RECLAIM	
C21/TAR BUCKETS	10	2	6-NE 1:1	HV FORDING/STD FORDING	28.0	22.4	1/4	92.62
INDIANA	0	0.0	3-NW 2:1	HV FORDING/MV FORDING	22.5	18.0	1/8	80.32
SOMERSET	0	0.0	2-CE	MAPLEMEADOW	18.0	14.4	CFW	45.25
OVERSIZE	0	0.0	4-CW 2:1	ELK RUN/HERNSHAW	35.5	28.4	PPT	6.10
POW'LTON	0	0.0	7-SE 1:1	STANDARD/ELK RUN	23.0	7.9	STOCK	198
HERNSHAW	8	9.3	5-SW	REGINA PC	26.0	8.9	RECLAIM	130
ELK RUN	19	22.1	TOTAL		125.1	100.0	NET	68
MAPLE MEADOW	13	15.1						

AMONATE	0	0.0	DUMPER				GRINDING HRS	8.5
MV FORDING	7	8.1	ON HAND	0			DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0				
REGINA PC	5	5.8	DUMPED	0				
AIMCOR PC	0	0.0	ON HAND 7AM	0				

LINE CREEK	0	0.0						
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31	30	80	80
STD FORDING	12	14.0	A	Q/Q/D/D	31	30	80	80
HV FORDING	22	25.6	N	Q/Q/D/D	31	30	80	80
ACME BLEND	0	0.0						

COAL 18	0	0.0	OVENS					
COAL 19	0	0.0	#1 QC-IRONWORK					
TOTAL	86	100.0	#2 LC-PLATFORM BY EAST HOPPER					

#1 EUC	46	PB	24	#2DM-COKE GUIDES CAUGHT IN D13,D15,C2,C21
#2 EUC	72	D4	30	FAB DOOR CLEANING & LID BARS
#3 EUC	0	D15	32	c/o STEPS @ NORTH END GOING TO TOP OF BATTERY
#4 EUC	8	BC1	86	

#5 EUC	86	TOM	63	BY-PRODUCTS
950	40	FL	23	COND TANK PUMP ROOM-REPLACE NIPPLE & SAMPLE VALVE
950B	324	AC	118	#3 BOOSTER-BOUND UP
992	118			#2 BOOSTER-OIL LEAK FROM BOTTOM OF TRIP

TRUCKS				ELEC EXH-U TUBE DRAIN
HERNSHAW	37	TAR TR	0	EXH ROOM TOILET TANK LEAKING
mv Fordin	0	LO TRK	1	JOY AIR COMPRESSOR-c/o PANEL BOARD (INSTR. DEPT)
MAPLE MEA	0	SUL TR	3	

REGINA PC	0	N PR T	41	COAL HANDLING
STD FORDI	0	S PR T	41	#4 BELT CHUTE-SIDE PLATE HOLES N SIDE RECLAIM CHUTE ARES
TRUE ENER	0	C L PR	104	#4 BELT-REPAIR BACK UP RUBBER BOTTOM OF 3/4 CHUTE
elk run	55	F L PR	94	RECLAIM HOPPER-REPAIR APRON
Acme Blen	0	SUC B4	200	W BELT-WORN RI
INLAND	0	SUC AF	295	#5 EUC-REPAIR DOOR LATCH
HV FORDIN	0	HD PR	130	HAMMER MILL-c/o MISSING HAMMERS

GAS BTU	555	SEC T	24	
GAS-FCE	8985	WO T	22	
GAS-TOT	22717	FG T	28	LITES-INSTALLING LIGHTS @ WHISTLE (wip)
STILL FL	100	FG PR	49	

COKE PLANT 1993 DATE PUSHED F/A REC PUSHES
MORNING REPORT 03/06 0 0 114

TODAY'S DATE
03/07 1993-1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2435	235	110	0	12	1	0	0	38	38	2	2	3	3
	2422	285	108	0	15	2	1	0						C1-300
3/11	2427	223	108	0	9	0	1	0	38	38	2	2	2	A25-400
	2424	280	105	0	8	4	1	0						
11/7	2408	215	100	0	11	0	0	0	38	38	2	1	2	
	2386	260	100	0	16	5	1	0						C1-330

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.4	1/4	92.19
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.0	17.6	1/8	80.46
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.0	CFW	43.75
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.5	29.2	PPT	5.10
POW'LTON	0	0.0	7-SE	1:1	STANDARD/MV FORDING	22.5	7.7	STOCK	33
HERNSHAW	7	9.5	5-SW		REGINA PC	26.0	9.0	RECLAIM	144
ELK RUN	14	18.9			TOTAL	124.9	100.0	NET	-111
MAPLE MEADOW	10	13.5							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	10	13.5	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	8	10.8	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	4	5.4	A	Q/Q/D/D	31 30 80 80				
HV FORDING	21	28.4	N	Q/Q/D/D	31 30 80 80				

ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	SHUTDOWN FOR ENGR'G TO HOT TAP COLLECTOR MAIN						
TOTAL	74	100.0	#2 DM-HYDRAULIC PUMP KICKS BREAKER WHEN TURNED ON						
			#2 STACK CONTROLLER HYDRAULIC LEAD						
#1 EUC	30	PB	16	HKC HOOD-REPAIRS DURING OUTAGE					
#2 EUC	43	D4	0	QUENCH SUMP VALVE-STICKING CLOSED					
#3 EUC	0	D15	32	BY-PRODUCTS					
#4 EUC	43	BC1	84	COLLECTOR POT-BLOWN RUPTURE DISK					
#5 EUC	34	TOM	63	EXH ROOM AIR DRYER LEAKING BADLY-ON BY-PASS					
950	307	FL	141	INSPECT LO LOADING PLATFORM-HIT BY TRUCK					
950B	187	AC	38	JOY A/C-E CYLINDER BROKEN PACKING BOLT					
992	0			WSAC-SEND OUT END PLATES TO RESORCON					
TRUCKS				S. TAR PUMP-MECH SEAL LEAK					
HERNSHAW	0	TAR TR	1	STM. VALVE LEAKING THROUGH AUX OIL PUMP STM EXH					
mv Fordin	0	LO TRK	0	COAL HANDLING					
MAPLE MEA	0	SUL TR	2	W BELT-TWO WORN IDLERS					
REGINA PC	0	N PR T	41	RECLAIM HOPPER-REPAIR APRON S SIDE					
STD FORDI	0	S PR T	41	E4 CHUTE-REPLACE BUTTERFLY ON BINDICATOR					
TRUE ENER	0	C L PR	106	#2 EUC-BROKEN PTO					
elk run	0	F L PR	82	FL-REPLACE FUEL PUMP					
Acme Blen	0	SUC B4	165	CARPENTER-#4 BELT DOOR S SIDE BY RI175, #11 FIREBOX					
INLAND	0	SUC AF	300	LITES-WHISTLE(wip), #1 BELT(tail & tunnel)					
HV FORDIN	0	HD PR	140						
GAS BTU	538	SEC T	23						
GAS-FCE	10410	WO T	24						
GAS-TOT	21329	FG T	29						
STILL FL	110	FG PR	48						

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 03/02 F/A 1 REC 1 PUSHES 114

TODAY'S DATE 03/03 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2399	217	95	0	12	0	0	0	36	36	2	1	3	2
	2393	250	90	0	13	2	1	0						
3/11	0	197	75	0	11	1	0	0	40	40	2	3	1	2
	0	250	85	0	11	8	2	0						
11/7	2350	197	75	0	4	3	0	0	37	37	2	2	1	2
	2289	250	85	0	9	8	0	0						

C21/TAR BUCKETS	7	1	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.7	1/4	93.16
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.0	17.8	1/8	80.14
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.2	CFW	45.00
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	35.5	28.8	PPT	6.40
POW/LTON	0	0.0	7-SE	1:1	STANDARD/MV FORDING	22.5	7.8	STOCK	352
HERNSHAW	9	12.7	5-SW		REGINA PC	25.0	8.7	RECLAIM	340
ELK RUN	18	25.4			TOTAL	123.4	100.0	NET	12
MAPLE MEADOW	9	12.7							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	7	9.9	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	6	8.5	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	8	11.3	A	Q/Q/D/D	31 30 80 80				
HV FORDING	14	19.7	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	BASEMENT-NIPPLES #2						
TOTAL	71	100.0							

#1 EUC	30	PB	15
#2 EUC	43	D4	0
#3 EUC	0	D15	32
#4 EUC	11	BC1	84
#5 EUC	2	TOM	59
950	233	FL	125
950B	171	AC	6
992	117		
HERNSHAW	0	TAR TR	5
mv Fordin	0	LO TRK	2
MAPLE MEA	0	SUL TR	0
REGINA PC	0	N PR T	42
STD FORDI	0	S PR T	42
TRUE ENER	0	C L PR	106
elk run	82	F L PR	84
Acme Blen	0	SUC B4	160
INLAND	20	SUC AF	280
HV FORDIN	0	HD PR	135
GAS BTU	519	SEC T	23
GAS-FCE	9307	WO T	22
GAS-TOT	20640	FG T	25
STILL FL	115	FG PR	48

BY-PRODUCTS

JOY A/C-E CYLINDER BROKEN PACKING BOLT
NIPPLE LEAK OIL COOLER #2 BOOSTER GAS END
INSTALL INSTR. FOR AUTO WALL BLEEDER
WSAC-SEND OUT END PLATES TO RESORCON
REPAIR PIPE SUPPORTS FOR WASH OIL LINE
STEAM HEATER BP LOCKER ROOM BAD

COAL HANDLING

#2 EUC-BROKEN PTO
#4 EUC-WINDSHIELD WIPER & MOTOR, FRONT ENGINE LEAKING OIL
950-HYDRAULIC OIL LEAK-BAD
992-HYDRAULIC LEAK
C&C TRUCK-REPAIR BROKEN TIE ROD
RECLAIM BELT-REPAIR DEFLECTOR PLATE
LITES-GLOBE ON EXTENSION LIGHT (pulv)

ET FIRST AID

COKE PLANT 1993 DATE PUSHED F/A REC PUSHES TODAY'S DATE
 MORNING REPORT 03/01 0 0 71 03/02 1993 1999

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD				PUSHES	PSH/HKC				MACHINES
					20	25	30	35		P	D	L	Q	
7/3	2326	215	105		0	0	0	0	0	0	0	0	0	0
	2365	260	100		0	0	0	0	0					
3/11	2308	150	65		0	8	0	0	0	33	33	3	3	1 2
	2424	215	70		0	9	2	2	0					C6-340 D2-340 D4-300
11/7	2350	195	80		0	9	1	0	0	44	44	2	1 1 2	
	2343	215	67		0	6	11	1	0					C7-300

21

BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	27.5	22.0	1/4	93.54
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	18.0	1/8	80.28
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.0	CFW	44.25
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.5	29.2	PPT	11.50
POW'LTON	0	0.0	7-SE	1:1	STANDARD/MV FORDING	23.5	8.1	STOCK	44
HERNSHAW	6	10.0	5-SW		REGINA PC	25.5	8.8	RECLAIM	842
ELK RUN	12	20.0			TOTAL	125.1	100.0	NET	-798

AMONATE 0 0.0 DUMPER GRINDING HRS 8.0
 MV FORDING 7 11.7 ON HAND 0 DUMPING HRS 0.0
 SMOKY RIVER 0 0.0 REC'D 0
 REGINA PC 7 11.7 DUMPED 0
 AIMCOR PC 0 0.0 ON HAND 7AM 0

TRUE ENERGY	0	0.0	D	Q/Q/D/D	31	30	80	80
STD FORDING	7	11.7	A	Q/Q/D/D	31	30	80	80
HV FORDING	12	20.0	N	Q/Q/D/D	31	30	80	80

ACME BLEND 0 0.0
 COAL 18 0 0.0 OVENS
 COAL 19 0 0.0 LARRY CARS-JIB HOISTS ARE TRIPPING HAZARDS
 TOTAL 60 100.0 #1 DM-HYD LEAK IN CAB ON CONTROLS

#1 EUC 24 PB 15 WATERBLASTER
 #2 EUC 43 D4 0 #1 LC OUTSIDE FEMCO
 #3 EUC 0 D15 32 #2 XOVER-380# STEAM GAGE
 #4 EUC 3 BC1 84
 #5 EUC 101 TOM 59

950 209 FL 117 BY-PRODUCTS
 950B 171 AC 168 JOY A/C-E CYLINDER BROKEN PACKING BOLT
 992 107 AIR PUMP @ BLEEDER STACK NOT WORKING

TRUCKS
 HERNSHAW 0 TAR TR 4 WSAC-REPLACE END PLATES & PRESSURE TEST
 mv Fordin 0 LO TRK 3 ELEC EXH-SEAL POT PSV HAS TRACER LEAK
 MAPLE MEA 36 SUL TR 2 INSTALL TAR CONTROL VALVE FOR SECONDARY COOLER
 REGINA PC 0 N PR T 44 ADJUST EXPANSION JOINTS ON LTV/FURNACE GAS LINE
 STD FORDI 0 S PR T 44

TRUE ENER 0 C L PR 108 COAL HANDLING
 elk run 54 F L PR 82 #2 EUC-BROKEN PTO
 Acme Blen 0 SUC B4 160 #4 EUC-WINDSHIELD WIPER & MOTOR, FRONT ENGINE LEAKING OIL
 INLAND 0 SUC AF 250 950-HYDRAULIC OIL LEAK-BAD, LIGHTS ON REAR
 HV FORDIN 0 HD PR 130 C&C TRUCK-REPAIR BROKEN TIE ROD
 GAS BTU 532 SEC T 23 RECLAIM BELT-REPAIR DEFLECTOR PLATE
 GAS-FCE 7378 WO T 21 Y BELT-TIGHTEN PLOWS
 GAS-TOT 16933 FG T 23 LITES-CH LOCKER ROOM, W BELT IN PIT
 STILL FL 115 FG PR 49 2 80ft DROP CORD LIGHTS FOR CHARGING BINS

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 02/28 F/A 0 REC 0 PUSHES 114

TODAY'S DATE 03/01 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES				
					20	25	30	35	P	D	L	Q	
7/3	2352	215	105	0	4	0	0	0	27	27	3	3	3
	2368	265	105	0	5	2	1	0					D12-300
3/11	2333	185	105	0	12	0	1	0	46	46	1	1	2 A1-350
	2356	262	105	0	14	3	0	0					
11/7	2346	215	105	0	2	0	1	0	41	41	3	1	3 2 A25-350
	2396	265	105	0	14	2	0	0					

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	28.0	22.3	1/4	93.11
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	22.5	17.9	1/8	80.10
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	17.5	14.0	CFW	44.50
OVERSIZE	0	0.0	4-CW	2:1	ELK RUN/HERNSHAW	36.5	29.1	PPT	77.00
POW'LTON	0	0.0	7-SE	1:1	STANDARD/MV FORDING	23.0	7.9	STOCK	66
HERNSHAW	8	9.8	5-SW		REGINA PC	25.5	8.7	RECLAIM	366
ELK RUN	10	12.2			TOTAL	125.4	100.0	NET	-300
MAPLE MEADOW	16	19.5							
AMONATE	0	0.0	DUMPER					GRINDING HRS	10.5
MV FORDING	9	11.0	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	7	8.5	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	13	15.9	A	Q/Q/D/D	31 30 80 80				
HV FORDING	19	23.2	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	SHUTDOWN FOR ENGINEERS AGAIN						
TOTAL	82	100.0	#2 LC-BIN GATE OPENER-electrical						

#1 EUC	24	PB	15	QUENCH SUMP-SCREEN, FILL VALVE, SUMP PUMP
#2 EUC	38	D4	0	#2 P-HYDRAULIC PUMP
#3 EUC	0	D15	32	
#4 EUC	107	BC1	84	
#5 EUC	93	TOM	59	
950	186	FL	89	BY-PRODUCTS
950B	171	AC	160	JOY A/C-E CYLINDER BROKEN PACKING BOLT
992	98			AIR PUMP @ BLEEDER STACK NOT WORKING
TRUCKS				INSTALL INSTR. FOR AUTO WALL BLEEDER
HERNSHAW	29	TAR TR	4	WSAC-REPLACE END PLATES & PRESSURE TEST
mv Fordin	0	LO TRK	0	ELEC EXH-SEAL POT PSV HAS TRACER LEAK
MAPLE MEA	53	SUL TR	3	REPLACE PIT COVER PLATE OVER WATER VALVE N OF CAUSTIC TANK
REGINA PC	0	N PR T	41	c/o BINDICATOR FOR COLLECTOR POT IN EXH RM-no auto
STD FORDI	0	S PR T	42	
TRUE ENER	0	C L PR	102	COAL HANDLING
elk run	0	F L PR	82	COMPLETE REPAIRS TO BDO SYSTEM
Acme Blen	0	SUC B4	170	#4 EUC-WINDSHIELD WIPER & MOTOR, FRONT ENGINE LEAKING OIL
INLAND	0	SUC AF	260	950-HYDRAULIC OIL LEAK-BAD, LIGHTS ON REAR
HV FORDIN	0	HD PR	135	RECLAIM BELT-REPAIR DEFLECTOR PLATE
GAS BTU	511	SEC T	24	
GAS-FCE	0	WO T	21	
GAS-TOT	21267	FG T	24	LITES-CH LOCKER ROOM, W BELT IN PIT
STILL FL	115	FG PR	49	2 80ft DROP CORD LIGHTS FOR CHARGING BINS

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 02/22 F/A 0 REC 0 PUSHES 74

TODAY'S DATE
02/23 1993

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC	MACHINES			
					20	25	30	35		P	D	L	Q
7/3	0	0	0	0	0	0	0	0	1	1	1	1	2
	0	0	0	0	1	0	0	0					
3/11	2315	125	63	0	7	0	0	0	31	31	1	1	2
	2318	160	57	0	10	3	2	0					
11/7	snow	163	70	0	7	0	0	0	39	39	1	1	2
	snow	187	51	0	9	2	1	0					

1994

D10-350 D12-350 D11-STUCK

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	25.5	20.0	1/4	93.29
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	24.5	19.2	1/8	80.19
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	19.0	14.9	CFW	44.50
OVERSIZE	0	0.0	4-CW		HERNSHAW	35.5	27.9	PPT	6.10
POW'LTON	0	0.0	7-SE	2:1	HERNSHAW/MV FORDING	29.0	9.8	STOCK	0
HERNSHAW	14	20.6	5-SW		REGINA PC	24.0	8.1	RECLAIM	770
ELK RUN	11	16.2			TOTAL	127.3	100.0	NET	-770
MAPLE MEADOW	13	19.1							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	6	8.8	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	4	5.9	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	7	10.3	A	Q/Q/D/D	31 30 80 80				
HV FORDING	13	19.1	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	#2 P-c/o	HEAD & TRAIL SHOE					
TOTAL	68	100.0	#2 QC-c/o	BOTTOM SOUTH SHOE BRACKET					

1/4 LAMP Coal

D-11 correct

#1 EUC	16	PB	14
#2 EUC	28	D4	0
#3 EUC	0	D15	32
#4 EUC	72	BC1	84
#5 EUC	40	TOM	49
950	92	FL	76
950B	123	AC	107
992	55		
TRUCKS			
HERNSHAW	20	TAR TR	3
mv Fordin	100	LO TRK	0
MAPLE MEA	0	SUL TR	1
REGINA PC	0	N PR T	41
STD FORDI	0	S PR T	40
TRUE ENER	0	C L PR	105
elk run	0	F L PR	82
Acme Blen	0	SUC B4	160
INLAND	25	SUC AF	220
HV FORDIN	0	HD PR	80
GAS BTU	543	SEC T	22
GAS-FCE	0	WO T	23
GAS-TOT	17240	FG T	23
STILL FL	115	FG PR	47

TQ1 TRAILER-NO WATER FLOW IN BATHROOM

BY-PRODUCTS

- EXH. COLLECTOR POT-BLOWN RUPTURE DISK, NO ALARM
- EAST OIL COOLER ELEC EXH FLUID DRIVE BAD
- LIGHT OIL STORAGE TANK LEVEL INDICATOR HIGH/LOW READINGS
- MILL WATER LINE TO CONDENSATE PUMP ROOM LEAKING AGAIN
- EXH RM SPRINKLER SYSTEM DRAIN VALVE LEAKS
- REPAIR PIPE SUPPORTS FOR WASH OIL LINES(old naph tank area)

COAL HANDLING

- GYREX-PATCH HOLE N WALL
- 4 BELT-WEAR PLATES TAIL END
- RECLAIM BELT-SLIPPING, WEAR PLATES @ TAIL END
- WHARF GATES-NORTH END TWO GATES BROKEN BRACKETS
- HAMMER MILL-REPLACE HAMMER, INSTALL DEFLECTOR PLATE
- LITES-#1 BELT, C21 INCLINE

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 02/21 F/A 0 REC 0 PUSHES 114

TODAY'S DATE 02/22 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD PUSHES				PSH/HKC MACHINES					
					20	25	30	35	P	D	L	Q		
7/3	2344	190	90	0	8	0	0	0	38	38	3	3	2	2
	2384	223	65	0	13	4	2	0						D10-300 D12-330
3/11	2331	187	90	0	7	0	0	0	38	38	3	2	2	
	2321	220	65	0	10	3	1	0						D4-320
11/7	2371	187	90	0	6	0	0	0	39	39	1	2	3	
	2353	225	65	0	12	1	0	1						C1-400

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/STD FORDING	25.5	20.2	1/4	93.66
INDIANA	0	0.0	3-NW	2:1	HV FORDING/MV FORDING	24.5	19.4	1/8	80.42
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.5	14.6	CFW	44.00
OVERSIZE	0	0.0	4-CW		HERNSHAW	35.0	27.7	PPT	7.80
POW'LTON	0	0.0	7-SE	2:1	HERNSHAW/MV FORDING	29.0	9.9	STOCK	176
HERNSHAW	26	30.2	5-SW		REGINA PC	24.0	8.2	RECLAIM	168
ELK RUN	0	0.0		TOTAL		126.3	100.0	NET	8
MAPLE MEADOW	14	16.3							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	10	11.6	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	7	8.1	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0				COAL MIX CHANGE	
LINE CREEK	1	1.2						HERNSHAW reduced to 50% of fluids	
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80			Replaced by Elk Run	
STD FORDING	8	9.3	A	Q/Q/D/D	31 30 80 80			1st Push 1AM 2/24	
HV FORDING	20	23.3	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	SHUTDOWN TO REPLACE ALL 4 BLEEDER STACKS						
TOTAL	86	100.0	HKC-FAN SHROUD, GREASE HOOD CAR, INSPECT DUCT						
			#1 QC-COUPLING						
#1 EUC	8	PB	14	QUENCH STATION-REPAIR TRACER LINES					
#2 EUC	28	D4	0	ELECTRICAL INSULATORS-REPAIR ON QUENCH TRACK & PUSHER TRACK					
#3 EUC	0	D15	32	4" MILL WATER LINE S END #2 BATTERY-REPLACE 4" VALVE					
#4 EUC	72	BC1	84						
#5 EUC	32	TOM	49						
950	84	FL	68	BY-PRODUCTS					
950B	107	AC	99	REPLACE END PLATES ON WSAC & PRESSURE TEST					
992	47			REPAIRS TO #4 VOC HEADER STEAM JACKETED PIPE					
TRUCKS				LIGHT OIL STORAGE TANK LEVEL INDICATOR HIGH/LOW READINGS					
HERNSHAW	11	TAR TR	3	#1 BOOSTER-c/o ELECTRIC LUBRICATOR PUMP					
mv Fordin	0	LO TRK	0	MILL WATER LINE TO CONDENSATE PUMP ROOM LEAKING AGAIN					
MAPLE MEA	54	SUL TR	3	EXH RM SPRINKLER SYSTEM DRAIN VALVE LEAKS					
REGINA PC	0	N PR T	43	REPAIR PIPE SUPPORTS FOR WASH OIL LINES(old naph tank area)					
STD FORDI	19	S PR T	44						
TRUE ENER	0	C L PR	105	COAL HANDLING					
elk run	0	F L PR	92	HAMMER MILL-BROKEN DOOR HANDLE, INSPECTION DOOR					
Acme Blen	0	SUC B4	200	4 BELT-WEAR PLATES TAIL END					
INLAND	0	SUC AF	290	RECLAIM BELT-SLIPPING, WEAR PLATES @ TAIL END					
HV FORDIN	0	HD PR	150	WHARF GATES-NORTH END TWO GATES BROKEN BRACKETS					
GAS BTU	542	SEC T	23						
GAS-FCE	0	WO T	20	LITES-#1 BELT					
GAS-TOT	22002	FG T	20						
STILL FL	115	FG PR	49						

COKE PLANT
MORNING REPORT

1993 DATE PUSHED
02/20 F/A REC PUSHES
0 0 114

TODAY'S DATE
02/21 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD	PUSHES				PSH/HKC				MACHINES	
						20	25	30	35	P	D	L	Q		
7/3	2399	195	95		0	10	0	0	0	40	40	1	3	3	
	2424	242	70		0	13	1	0	0						D10-300
3/11	2360	190	90		0	14	0	0	0	38	38	1	1	1	2
	2345	230	65		0	7	0	1	0						D9-300
11/7	2346	180	90		0	9	1	0	0	38	38	1	1	1	2
	2358	235	65		0	12	1	2	1						D4-340 C19-350 D11 STUCK

C21/TAR BUCKETS	3	1	6-NE	1:1	HV FORDING/ACME BLEND	25.0	19.8	1/4	92.69
INDIANA	0	0.0	3-NW	2:1	HV FORDING/ACME BLEND	24.0	19.0	1/8	80.33
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.5	14.6	CFW	45.50
OVERSIZE	0	0.0	4-CW		HERNSHAW	36.0	28.5	PPT	8.30
POW'LTON	0	0.0	7-SE	2:1	HERNSHAW/MV FORDING	29.5	10.0	STOCK	143
HERNSHAW	29	33.0	5-SW		REGINA PC	24.0	8.2	RECLAIM	168
ELK RUN	0	0.0			TOTAL	126.5	100.0	NET	-25
MAPLE MEADOW	12	13.6							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	9	10.2	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	7	8.0	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	1	1.1							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				
STD FORDING	9	10.2	A	Q/Q/D/D	31 30 80 80				
HV FORDING	21	23.9	N	Q/Q/D/D	31 30 80 80				
ACME BLEND	0	0.0							
COAL 18	0	0.0							
COAL 19	0	0.0							
TOTAL	88	100.0							

*MV FORDING
INLAND COAL
DELIVERY
Problems*

#1 EUC	8 PB	14			
#2 EUC	20 D4	0			
#3 EUC	0 D15	32			
#4 EUC	72 BC1	84			
#5 EUC	24 TOM	49			
950	84 FL	60			
950B	83 AC	91			
992	43				
TRUCKS					
HERNSHAW	0 TAR TR	0			
mv Fordin	0 LO TRK	0			
MAPLE MEA	0 SUL TR	2			
REGINA PC	0 N PR T	41			
STD FORDI	0 S PR T	41			
TRUE ENER	0 C L PR	105			
elk run	0 F-L PR	91			
Acme Blen	0 SUC B4	190			
INLAND	11 SUC AF	245			
HV FORDIN	0 HD PR	115			
GAS BTU	538 SEC T	23			
GAS-FCE	0 WO T	21			
GAS-TOT	23260 FG T	23			
STILL FL	115 FG PR	48			

BY-PRODUCTS
 REPLACE END PLATES ON WSAC & PRESSURE TEST
 C.L STEAM TURBINE TRIPPED, RESET BUT NOT RUNNING UP TO SPEED
 REPAIRS TO #4 VOC HEADER STEAM JACKETED PIPE
 LIGHT OIL STORAGE TANK LEVEL INDICATOR HIGH/LOW READINGS
 BOOSTER GAS INLET RECORDER RUNS INTERMITTENTLY

COAL HANDLING
 992-HYDRAULIC HOSE
 #1 EUC-REBUILD KING PIN
 #2 EUC-CAB LOOSE WITH BROKEN PIECE
 REPLACE SUMP PUMP DUMPER BASEMENT
 LEAKING ROOF-CAGE PAKTOR CONTROL ROOM
 WHARF GATES-REPAIR PIN 2nd BAY

LITES-#1 BELT, CH LOCKER ROOM

COKE PLANT
MORNING REPORT

1993 DATE PUSHED 02/17
F/A 0
REC 0
PUSHES 114

TODAY'S DATE 02/18 1993-1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD	PUSHES				PSH/HKC MACHINES				
						20	25	30	35	P	D	L	Q	
7/3	2331	195	94	0	6	1	0	0	33	33	1	1	3	2
	2356	250	75	0	8	3	4	0	C1-300 C19-310 D11-300 D25-320					
3/11	2362	195	95	0	10	0	0	0	41	41	3	1	1	2
	2371	245	75	0	10	5	1	0						
11/7	2340	190	95	0	11	0	0	0	38	38	1	3	1	2
	2382	250	75	0	15	1	2	0	C19-320 C11-330					

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/ACME BLEND	25.0	19.8	1/4	93.05
INDIANA	0	0.0	3-NW	2:1	HV FORDING/ACME BLEND	24.0	19.0	1/8	80.09
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.5	14.7	CFW	45.25
OVERSIZE	0	0.0	4-CW		HERNSHAW	35.5	28.2	PPT	5.90
POW'LTON	0	0.0	7-SE	2:1	HERNSHAW/MV FORDING	29.5	10.1	STOCK	176
HERNSHAW	26	31.3	5-SW		REGINA PC	24.0	8.2	RECLAIM	124
ELK RUN	0	0.0		TOTAL		126.0	100.0	NET	52
MAPLE MEADOW	14	16.9							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	2	2.4	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	5	6.0	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	2	2.4							
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31	30	80	80	
STD FORDING	0	0.0	A	Q/Q/D/D	31	30	80	80	
HV FORDING	20	24.1	N	Q/Q/D/D	31	30	80	80	
ACME BLEND	14	16.9							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	REPLACE WATER BLASTER ASAP						
TOTAL	83	100.0	#2 LC-ASSIST SLEEVE BOTTOM RING GUARD CUTS BOOTS						

#1 EUC	0	PB	14
#2 EUC	0	D4	0
#3 EUC	0	D15	32
#4 EUC	68	BC1	84
#5 EUC	8	TOM	45
950	84	FL	44
950B	19	AC	67
992	27		
TRUCKS			
HERNSHAW	48	TAR TR	3
mv Fordin	0	LO TRK	1
MAPLE MEA	0	SUL TR	1
REGINA PC	0	N PR T	42
STD FORDI	92	S PR T	42
TRUE ENER	0	C L PR	104
elk run	0	F L PR	79
Acme Blen	0	SUC B4	200
SOMERSET	11	SUC AF	255
HV FORDIN	0	HD PR	135
GAS BTU	0	SEC T	24
GAS-FCE	0	WO T	24
GAS-TOT	23799	FG T	28
STILL FL	115	FG PR	49

#1 LC-CENTER BOOTS
#2 P-BRAKES
LUNCH ROOM-REFRIGERATOR
C-17/C-19 DAMPER GASKET LEAKING
OVENS LADIES' ROOM-TOILET RUNS CONSTANTLY

BY-PRODUCTS
WSAC-REPLACE END PLATES & PRESSURE TEST
STM EXH-COMPRESSION FITTING OIL LK ON THROTTLE CONTROL
INSULATE LINE FROM COND TANK TO DECANter(150 ft to go)
EXH COLL POT-BLOWN RUPTURE DISK
#2 BOOSTER-GEAR PUMP LO OIL PRESS, BEARING CAP LEAKS

COAL HANDLING
E4 BELT-REPLACE SKIRT RUBBER TAIL END N SIDE
#4 BELT-REPLACE WEAR PLATES @ TAIL END
HAMMER MILL-REPAIR DOOR HANDLE
HAMMER MILL GYREX-PATCH HOLES N WALL

NORTH MIXER BELTS ARCING
LITES-#1 BELT, C21 BELT INCLINE, C&C OFFICE
LADIES LOCKER ROOM-LOCKER 13 BROKEN

← NOT FIT

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD	PUSHES				PSH/HKC MACHINES				
						20	25	30	35	P	D	L	Q	
7/3	2312	190	90	0	14	3	0	0	38	38	2	1	1	2
	2287	225	70	0	4	11	1	0						C16-340
3/11	2305	190	90	0	15	1	0	0	38	38	2	1	3	2 B23-330
	2319	245	80	0	14	4	1	0						D4-300 D11-310
11/7	2300	195	90	0	13	0	0	0	38	38	2	1	2	1
	2356	245	78	0	14	3	0	0						C8-300

C21/TAR BUCKETS	3	1	6-NE	1:1	HV FORDING/ACME BLEND	25.0	19.9	1/4	93.03
INDIANA	0	0.0	3-NW	2:1	HV FORDING/ACME BLEND	24.0	19.1	1/8	80.01
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.5	14.7	CFW	44.25
OVERSIZE	0	0.0	4-CW		HERNSHAW	35.5	28.2	PPT	6.20
POW'LTON	0	0.0	7-SE	2:1	HERNSHAW/MV FORDING	29.0	9.9	STOCK	242
HERNSHAW	27	32.1	5-SW		REGINA PC	24.0	8.2	RECLAIM	176
ELK RUN	0	0.0			TOTAL	125.8	100.0	NET	66
MAPLE MEADOW	13	15.5							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	4	4.8	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	6	7.1	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0							LOST STEAM EXH-oil pipe
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80				bled 2/15 6:30am-6:45am
STD FORDING	0	0.0	A	Q/Q/D/D	31 30 80 80				
HV FORDING	20	23.8	N	Q/Q/D/D	31 30 80 80				SHUTDOWN CANCELLED-clearance problem w/ bleeder
ACME BLEND	14	16.7							

			OVENS	
COAL 18	0	0.0		
COAL 19	0	0.0	REPAIR CHAIN ON #1 DM JAM CLEANER	
TOTAL	84	100.0	#2 DM-CG 8"CHANNEL, BOTTOM WEAR PLATE	
			LUNCH ROOM DRINKING FOUNTAIN DRAIN PLUGGED UP	
#1 EUC	98	PB 14	C-17/C-19 DAMPER GASKET LEAKING	
#2 EUC	92	D4 0	C-23 DAMPER LIQUOR LINE- HOLE	
#3 EUC	0	D15 32	#2 LC ASSIST SLEEVE- BOTTOM RING TOO LOW	
#4 EUC	52	BC1 77	HKC DAMPER - GEAR BOX	
#5 EUC	0	TOM 45	B-5 CERAMIC WELD	
950	84	FL 31	BY-PRODUCTS	
950B	8	AC 51	C.L ELEC PUMP MAKING NOISE	
			EXH. COLL POT RUPTURE DISC BLOWN	
992	9		MICROMOTION METER LK TAR TO CONTROL ROOM VIA CONDUIT	
TRUCKS			FINISH INSULATING WATER TO ACID SHOWER	
HERNSHAW	58	TAR TR 5	INSULATE LINE FROM COND TANK TO DECANTER(150 ft to go)	
mv Fordin	0	LO TRK 2	REMOVE SECTION OF #4 HEADER THAT IS PLUGGED AT CONTROL VALVE	
MAPLE MEA	53	SUL TR 3	TOILET IN EXH ROOM LEAKS AT BOTTOM	
REGINA PC	0	N PR T 40		
STD FORDI	0	S PR T 41		
TRUE ENER	0	C L PR 104	COAL HANDLING	
elk run	0	F L PR 83	REPLACE SKIRT RUBBER TAIL END T-BELT	
Acme Blen	0	SUC B4 180	CHECK STEERING #1 EUCLID	
SOMERSET	0	SUC AF 250	T BELT-ADJUST SKIRT RUBBER @ TAIL END	
HV FORDIN	0	HD PR 150	3' BELT-ADJUST SCRAPER	
GAS BTU	0	SEC T 25	CAGE PAKTOR-WEAR PLATES IN CHUTE, MOTOR	
GAS-FCE	0	WO T 27	#4 BELT-REPLACE WEAR PLATES @ TAIL END	
GAS-TOT	24150	FG T 28	LITES-WHARF (s end), 3 BELT(tail end)	
			REPLACE WEAR PLATES IN DOOR CAGE PAKTOR	

COKE PLANT
MORNING REPORT

1993 DATE PUSHED
02/14 F/A 0 REC 0 PUSHES 114

TODAY'S DATE
02/15 1993 1994

SHIFT	TEMPS	FLOW	PRS	BTU/HR	HARD	PUSHES				PSH/HKC				MACHINES
						20	25	30	35	P	D	L	Q	
7/3	2350	185	82	0	11	2	0	0	38	38	3	1	3	2
	2305	225	65	0	8	7	1	0						C16-340
3/11	2347	185	83	0	9	2	1	0	38	38	1	1	1	2
	2342	223	67	0	11	5	2	0						B23-330 D4-300 D11-310
11/7	2301	180	82	0	15	0	0	0	38	38	1	1	1	2
	2340	240	68	0	15	3	1	0						C8-300

C21/TAR BUCKETS	0	0	6-NE	1:1	HV FORDING/ACME BLEND	25.5	20.3	1/4	93.19
INDIANA	0	0.0	3-NW	2:1	HV FORDING/ACME BLEND	23.5	18.7	1/8	80.03
SOMERSET	0	0.0	2-CE		MAPLEMEADOW	18.0	14.3	CFW	44.50
OVERSIZE	0	0.0	4-CW		HERNSHAW	35.5	28.3	PPT	8.30
POW'LTON	0	0.0	7-SE	2:1	HERNSHAW/MV FORDING	29.5	10.1	STOCK	275
HERNSHAW	33	32.4	5-SW		REGINA PC	24.0	8.2	RECLAIM	134
ELK RUN	0	0.0			TOTAL	125.5	100.0	NET	141
MAPLE MEADOW	16	15.7							
AMONATE	0	0.0	DUMPER					GRINDING HRS	8.0
MV FORDING	5	4.9	ON HAND	0				DUMPING HRS	0.0
SMOKY RIVER	0	0.0	REC'D	0					
REGINA PC	9	8.8	DUMPED	0					
AIMCOR PC	0	0.0	ON HAND 7AM	0					
LINE CREEK	0	0.0						LOST STEAM EXH-oil pipe	
TRUE ENERGY	0	0.0	D	Q/Q/D/D	31 30 80 80			bled 2/15 6:30am-6:45am	
STD FORDING	0	0.0	A	Q/Q/D/D	31 30 80 80				
HV FORDING	23	22.5	N	Q/Q/D/D	31 30 80 80			SHUTDOWN CANCELLED-clearance problem w/ bleeder	
ACME BLEND	16	15.7							
COAL 18	0	0.0	OVENS						
COAL 19	0	0.0	#1 DM-JC LIMITS NEED ADJUSTING						
TOTAL	102	100.0	#2 DM-CG 8"CHANNEL, BOTTOM WEAR PLATE						

LUNCH ROOM DRINKING FOUNTAIN DRAIN PLUGGED UP									
#1 EUC	90	PB	13						
#2 EUC	84	D4	0						
#3 EUC	0	D15	32						
#4 EUC	52	BC1	77						
#5 EUC	0	TOM	45						
950	76	FL	24	BY-PRODUCTS					
950B	303	AC	43	EXH COLL. POT BLOWN RUPTURE DISK					
992	0			MICROMOTION METER LK TAR TO CONTROL ROOM VIA CONDUIT					
TRUCKS				FINISH INSULATING WATER TO ACID SHOWER					
HERNSHAW	60	TAR TR	4	INSULATE LINE FROM COND TANK TO DECANTER(150 ft to go)					
mv Fordin	0	LO TRK	1	REMOVE SECTION OF #4 HEADER THAT IS PLUGGED AT CONTROL VALVE					
MAPLE MEA	11	SUL TR	2	TOILET IN EXH ROOM LEAKS AT BOTTOM					
REGINA PC	0	N PR T	40						
STD FORDI	0	S PR T	40						
TRUE ENER	0	C L PR	102	COAL HANDLING					
elk run	55	F L PR	82	#5 EUC-OIL LEAK UNDER CAB					
Acme Blen	0	SUC B4	170	992 NEED GASKET FOT TRANSMISSION FILTER					
SOMERSET	0	SUC AF	280	T BELT-ADJUST SKIRT RUBBER @ TAIL END					
HV FORDIN	0	HD PR	145	3' BELT-ADJUST SCRAPER					
GAS BTU	565	SEC T	24	CAGE PAKTOR-WEAR PLATES IN CHUTE, MOTOR					
GAS-FCE	0	WO T	28	#4 BELT-REPLACE WEAR PLATES @ TAIL END					
GAS-TOT	23599	FG T	25	LITES-WHARF (s end), 3 BELT(tail end)					
STILL FL	115	FG PR	48						